


Fault Code: 144

Engine Coolant Temperature Sensor Circuit - Shorted High

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 144 PID(P): SPN: FMI: Lamp: Warning SRT:	Engine coolant temperature sensor signal is shorted high.	No engine protection for coolant temperature. Possible white smoke.



Engine Coolant Temperature Sensor Circuit

Circuit Description

The coolant temperature sensor is used by the electronic control module (ECM) to monitor the temperature of the engine coolant. The coolant temperature is used by the ECM for the engine protection system, timing, and fueling control. If the voltage is high, the ECM will log Fault Code 144. Voltage high can be caused by opens in the signal or return wires, voltage shorts to the signal or return wires, or a failed open sensor.

Component Location

Refer to the Engine Diagrams. 100-002 (/qs3/pubsys2/xml/en/procedures/01/01-100-002.html) for the component location.

Shoptalk

The resistance of the sensor varies with the temperature.

Refer to Troubleshooting Fault Code t05-144 (/qs3/pubsys2/xml/en/procedures/01/01-t05-144.html)

Last Modified: 29-Jul-2010
