


Fault Code: 1451

Generator Output Voltage and Electric Bus Voltage Differ - Condition Exists

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1451 PID(P): SPN: FMI: Lamp: Warning SRT:	Generator output voltage and electric bus voltage differ by more than the allowed threshold.	No action is taken by the ECM.



Generator Circuit

Circuit Description

The generator set produces electric power. This power is in the form of three-phase AC. The engine control module (ECM) uses this fault code to tell the operator that after the circuit breaker closed, the voltage of the generator set was different from the voltage of the bus.

Component Location

Refer to customer/facility/installation documentation for the location of the paralleling controller.

Shoptalk

Check the alternator voltage calibration and bus voltage calibration.

Refer to Troubleshooting Fault Code t05-1451. (</qs3/pubsys2/xml/en/procedures/01/01-t05-1451.html>)

Last Modified: 08-May-2012
