

Fault Code: 1463


Generator Set Not in Auto

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1463 PCODE(P): SPN: FMI: Lamp: None SRT:	The generator announces to the LonWorks network that it is not in auto.	No action is taken by the ECM.

©Cummins Inc



19802649

Generator Set ECM Card Cage

Circuit Description

Component Location

Refer to Troubleshooting Fault Code t05-1463 (/qs3/pubsys2/xml/en/procedures/01/01-t05-1463.html)

Last Modified: 29-Jul-2010
