

Fault Code: 1473


Electronic Control Module Watchdog Has Failed - Condition Exists

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1473 PID(P): SPN: FMI: Lamp: Shutdown SRT:	The ECM watchdog has failed.	Engine will shut down.

©Cummins Inc



19802494

Engine Control Module

Circuit Description

Component Location

Refer to Troubleshooting Fault Code t05-1473. (</qs3/pubsys2/xml/en/procedures/01/01-t05-1473.html>)

