

Fault Code: 1478


Crank Relay Driver Diagnostic

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1478 PCODE(P): SPN: FMI: Lamp: SRT: Warning	Crank relay driver diagnostic has detected an error.	The ECM will not be able to crank the engine.

©Cummins Inc



19802649

Generator Set ECM Card Cage

Circuit Description

Component Location

Refer to Troubleshooting Fault Code t05-1478 (/qs3/pubsys2/xml/en/procedures/01/01-t05-1478.html)

Last Modified: 29-Jul-2010
