


Fault Code: 212

Engine Oil Temperature Sensor Circuit - Shorted High

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 212 PID(P): SPN: FMI: Lamp: Warning SRT:	Engine oil temperature sensor signal is shorted high.	No engine protection for oil temperature. No effect on performance.



Oil Temperature Sensor Circuit

Circuit Description

The oil temperature sensor is used by the electronic control module (ECM) to monitor the temperature of the engine oil. If the oil temperature becomes too high and the engine protection is enabled, a derate condition can be incurred, possibly leading to shutdown.

Component Location

Refer to the Engine Diagrams. 100-002 (/qs3/pubsys2/xml/en/procedures/01/01-100-002.html) for the component location.

Shoptalk

The resistance of the sensor varies with the temperature.

Refer to Troubleshooting Fault Code t05-212 (/qs3/pubsys2/xml/en/procedures/01/01-t05-212.html)

Last Modified: 29-Jul-2010
