


Fault Code: 213

Engine Oil Temperature Sensor Circuit - Shorted Low

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 213 PID(P): SPN: FMI: Lamp: Warning SRT:	Engine oil temperature sensor signal is shorted low.	No engine protection for the oil temperature. No effect on performance.



Oil Temperature Sensor Circuit

Circuit Description

The oil temperature sensor is used by the electronic control module (ECM) to monitor the temperature of the engine oil. If the oil temperature becomes too high and engine protection is enabled, a derate condition will be incurred, possibly leading to shutdown.

Component Location

Refer to the Engine Diagrams. 100-002 (/qs3/pubsys2/xml/en/procedures/01/01-100-002.html) for the component location.

Shoptalk

The resistance of the sensor varies with the temperature.

Refer to Troubleshooting Fault Code t05-213 (/qs3/pubsys2/xml/en/procedures/01/01-t05-213.html)

Last Modified: 29-Jul-2010
