


Fault Code: 252

Engine Oil Level Number 1 Sensor - Data Incorrect

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 252 PID(P): SPN: FMI: Lamp: Warning SRT:	Engine oil level Number 1 sensor circuit - data incorrect.	No engine protection for low oil level. Centinel system is disabled.



Oil Level Sensor Circuit

Circuit Description

The lubricating oil level sensor is used by the ECM to monitor the amount of oil in the engine. Low oil level detected can cause the engine protection system to shut down the engine.

Component Location

The lubricating oil level sensor is in the engine oil pan.

Refer to Troubleshooting Fault Code t05-252 (/qs3/pubsys2/xml/en/procedures/01/01-t05-252.html)

Last Modified: 29-Jul-2010
