


Fault Code: 343

Engine Control Module - Warning

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 343 PID(P): SPN: FMI: Lamp: Warning SRT:	Internal ECM error.	No action is taken by the ECM. Possible loss of performance.



Electronic Control Module

Circuit Description

The electronic control module (ECM) is a computer that is responsible for engine control, diagnostics, and user features.

Component Location

Refer to the Engine Diagrams. 100-002 (</qs3/pubsys2/xml/en/procedures/01/01-100-002.html>) for the component location.

Shoptalk

This is a fault with the internal circuitry of the electronic control module (ECM). Loose engine or chassis ground connections can cause Fault Code 343 to be logged, as well as complaints of an intermittent stumble. Pay special attention to the negative starter post connection. Moisture in the ECM connectors can also cause the ECM to log Fault Code 343.

Refer to Troubleshooting Fault Code t05-343 (</qs3/pubsys2/xml/en/procedures/01/01-t05-343.html>)

Last Modified: 29-Jul-2010
