


Fault Code: 442

Battery 1 Voltage High - Warning

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 442 PID(P): SPN: FMI: Lamp: Warning SRT:	Battery 1 voltage high - warning.	ECM damage will occur.



Unswitched Battery Supply Circuit

Circuit Description

The electronic control module (ECM) receives unswitched battery input through the engine harness. There is an in-line 20 amp fuse in the unswitched positive (+) battery wire of the engine harness to protect the engine harness from overheating. The battery return wires are connected directly to the negative (-) battery post.

Component Location

The ECM is connected to the battery by the OEM harness. This direct link provides a constant power supply for the ECM. Refer to the OEM manual for the battery location.

Shoptalk

Improper wiring of the battery circuit is the most likely cause of this fault.

Refer to Troubleshooting Fault Code t05-442 (</qs3/pubsys2/xml/en/procedures/01/01-t05-442.html>)

Last Modified: 29-Jul-2010
