


Fault Code: 451

Fuel Rail Pressure Sensor Circuit - Shorted High

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 451 PID(P): SPN: FMI: Lamp: Warning SRT:	Injector metering rail 1 pressure sensor circuit - shorted high. This was formerly called the fuel rail pressure sensor.	Calibration-dependent engine shutdown occurs, or no action is taken by ECM.



Fuel Rail Pressure Sensor Circuit

Circuit Description

The fuel rail pressure sensor provides the fuel rail pressure signal to the electronic control module (ECM), through the engine harness. The ECM uses the fuel rail pressure signal to monitor the fuel rail pressure going to the injector's metering chamber from the control valve body.

Component Location

Refer to the Engine Diagrams. 100-002 (</qs3/pubsys2/xml/en/procedures/01/01-100-002.html>) for the component location.

Shoptalk

Refer to specific engine wiring diagram for the output voltage of the pressure sensor.

Note: Some engine models will use the Metri-Pack type connector on this pressure sensor, and some will use the Danfoss™ type connector. The Metri-Pack connector pin designators are alpha and the Danfoss™ connector pin designators are numeric. The steps depicted in this fault code show the Metri-Pack type connector with alpha pin callouts. Refer to specific engine wiring diagrams to determine the correct pin designators for the type of connector.

Refer to Troubleshooting Fault Code t05-451 (</qs3/pubsys2/xml/en/procedures/01/01-t05-451.html>)

Last Modified: 29-Jul-2010
