


Fault Code: 452

Fuel Rail Pressure Sensor Circuit - Shorted Low

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 452 PID(P): SPN: FMI: Lamp: Warning SRT:	Injector metering rail 1 pressure sensor circuit - shorted low. This was formerly called the fuel rail pressure sensor.	Calibration-dependent engine shutdown occurs, or no action is taken by ECM.



Injector Metering Rail 1 Pressure Sensor Circuit

Circuit Description

The fuel rail pressure sensor provides the fuel rail pressure signal to the engine control module (ECM), through the engine harness. The ECM uses the fuel rail pressure signal to monitor the fuel rail pressure going to the injector's metering chamber from the control valve body.

Component Location

Use the following procedure for the component location. Refer to Procedure 100-002 in Section E (/qs3/pubsys2/xml/en/procedures/01/01-100-002.html).

Shoptalk

Refer to specific engine wiring diagram for the output voltage of the pressure sensor.

Note: Some engine models will use the Metri-Pack™ type connector on this pressure sensor, and some will use the Danfoss™ type connector. The Metri-Pack™ connector pin designators are alpha and the Danfoss™ connector pin designators are numeric. The steps depicted in this fault code show the Metri-Pack™ type connector with alpha pin callouts. Refer to specific engine wiring diagrams to determine the correct pin designators for the type of connector.

Refer to Troubleshooting Fault Code t05-452. (/qs3/pubsys2/xml/en/procedures/01/01-t05-452.html)

Last Modified: 08-May-2012
