


Fault Code: 649

Change Lubricating Oil and Filter

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 649 PID(P): SPN: FMI: Lamp: Warning SRT:	Change lubricating oil and filter. The Centinel system has not been able to replace old oil with new. The condition has persisted long enough that the oil quality warrants a full change out.	No action is taken by the ECM. Possible damage to engine can occur.



Circuit Description

The oil make up tank provides clean oil to the make up valve of the Centinel system to replenish oil that was burned by the Centinel system.

Component Location

Varies by installation. Refer to Centinel Master Repair Manual 3666231 for further information.

Shoptalk

This fault indicates that the old oil has **not** been replenished with new oil.

Refer to Troubleshooting Fault Code t05-649 (</qs3/pubsys2/xml/en/procedures/01/01-t05-649.html>)

Last Modified: 29-Jul-2010
