


Fault Code: 729

Blowby Pressure Sensor - Shorted Low

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 729 PID(P): SPN: FMI: Lamp: Warning SRT:	Crankcase blowby pressure sensor circuit - shorted low.	No engine protection for blowby pressure.



Blowby Pressure Sensor Circuit

Circuit Description

The blowby pressure sensor monitors blowby pressure and passes information to the electronic control module (ECM). Low voltage will trip Fault Code 729 and can be caused by shorts in the supply, signal, or return wires, an open in the return wires, or a failed sensor.

Component Location

Refer to the Engine Diagrams. 100-002 (/qs3/pubsys2/xml/en/procedures/01/01-100-002.html) for the component location.

Shoptalk

Confirm that the crankcase breathers, breather tubes, and blowby sensor are **not** obstructed.

Refer to Troubleshooting Fault Code t05-729 (/qs3/pubsys2/xml/en/procedures/01/01-t05-729.html)

Last Modified: 29-Jul-2010
