


Fault Code: 173

Rack Actuator Mechanically Stuck Closed - Data Valid But Below Normal Operating Range - Moderately Severe Level

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 173 PID(P): S23 SPN: 638 FMI: 18 Lamp: Amber SRT:	Rack actuator mechanically stuck closed - data valid but below normal operating range - moderately severe level.	No action taken by the electronic control module (ECM).



Rack Actuator Circuit

Circuit Description

The fuel control rack and solenoid determine the quantity of fuel metered to the engine.

Component Location

The fuel control rack and solenoid are integral parts of the P7100 fuel pump

Shoptalk

- Confirm the actuator connector is firmly in place.
- A defective fuel pump can cause Fault Code 173.

Refer to Troubleshooting Fault Code t05-173 (</qs3/pubsys2/xml/en/procedures/07/07-t05-173.html>)

Last Modified: 18-Dec-2012
