

Fault Code: 346


Engine Control Module Calibration Memory Software - Bad Intelligent Device or Component

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 346 PID(P): SPN: 630 FMI: 12 Lamp: Yellow SRT:	Engine Control Module Calibration Memory Software - Bad Intelligent Device or Component.	Possible reduced performance.

©Cummins Inc



19900397

Engine Control Module (ECM)

Circuit Description

The ECM is a computer that is responsible for engine control, diagnostics, and user features.

Component Location

The ECM is located on the side of the engine. Refer to Procedure 100-002 in Section E.
(/qs3/pubsys2/xml/en/procedures/149/149-100-002.html)

Shoptalk

This fault code can be caused by an internal ECM malfunction. This can also be caused if battery power is disconnected before the power-down sequence is completed. Repairs to the ECM are **not** possible.

Refer to Troubleshooting Fault Code 346. (/qs3/pubsys2/xml/en/procedures/07/07-t05-346.html)

Last Modified: 07-Oct-2016
