

Trainings ▾

General Information

If the engine will out of service in less than 12 months, special precautions **must** be taken. Follow the short term storage procedure in the Troubleshooting and Repair Manual for the CENTRY™ Electronic Control System, Bulletin 3666070, or see the GTA38, K38, K50, QSK38, and QSK50 Service Manual, Bulletin 4021528. If further assistance is required, contact the nearest Cummins® Authorized Repair Location for additional information.