

Manual Change History (4326168) QSB6.7 CM2150 B109

Service Manual

Date	18-Jun-2013
Section	Back
Procedure Number	4326168-history (/qs3/pubsys2/xml/en/manual/4326168/4326168-history.html)
Procedure Title	Manual Change History
Update Reason	New manual for QSB6.7 CM2150 B109 engine released for use.

Date	20-Sep-2013
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	216-019-107 (/qs3/pubsys2/xml/en/procedures/216/216-019-107.html)
Procedure Title	Intermediate Speed Control Switch
Update Reason	Replaced this procedure with a common procedure.

Date	20-Sep-2013
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	00-019-107 (/qs3/pubsys2/xml/en/procedures/00/00-019-107.html)
Procedure Title	Intermediate Speed Control Switch
Update Reason	Added to outline.

Date	13-Dec-2013
Section	Section 1 - Cylinder Block
Procedure Number	216-001-016-tr (/qs3/pubsys2/xml/en/procedures/216/216-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Added General Information and Clean and Inspect for Reuse Steps, remove Clean and Initial Check Steps.

Date	13-May-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	216-001-024-tr (/qs3/pubsys2/xml/en/procedures/216/216-001-024-tr.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	Edited to bring procedure inline with the other B engines.
Date	14-Sep-2016
Section	Section 8 - Cooling System - Group 08
Procedure Number	216-008-036-tr (/qs3/pubsys2/xml/en/procedures/216/216-008-036-tr.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	Updated procedure to be standard across engine group.
Date	06-Oct-2016
Section	Section 1 - Cylinder Block
Procedure Number	216-001-006 (/qs3/pubsys2/xml/en/procedures/216/216-001-006.html)
Procedure Title	Bearings, Main
Update Reason	Revised, Main Bearing Dimensions and graphic.
Date	06-Oct-2016
Section	Section 1 - Cylinder Block
Procedure Number	216-001-006 (/qs3/pubsys2/xml/en/procedures/216/216-001-006.html)
Procedure Title	Bearings, Main
Update Reason	Revised, Main Bearing Dimensions and graphic.

Date	13-Oct-2018
Section	Section 1 - Cylinder Block
Procedure Number	100-001-024 (/qs3/pubsys2/xml/en/procedures/100/100-001-024.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	Changed engine specific procedure prefix to common procedure prefix.

Date	13-Sep-2018
Section	Section 1 - Cylinder Block
Procedure Number	216-022-001_01 (/qs3/pubsys2/xml/en/procedures/216/216-022-001_01.html)
Procedure Title	Service Tool
Update Reason	Added Part Numbers 5395259, 5395330, and 5395409.

Date	14-Sep-2018
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	216-002-004-tr (/qs3/pubsys2/xml/en/procedures/216/216-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Updated the valve stem diameter specification.

Date	10-Mar-2025
Section	Section E - Engine and System Identification
Procedure Number	216-100-006 (/qs3/pubsys2/xml/en/procedures/216/216-100-006.html)
Procedure Title	Cummins® Product Technology
Update Reason	Added Brazil CONAMA MAR-1 regulation to emissions information for CPT procedure.