

Manual Change History (4358372) QSZ13 CM2150 Z102 Fault Code Troubleshooting Manual Change History

Date	30-Jul-2026
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001335
Solution Title	Lubricating oil cooler is leaking
Update Reason	Solution Removed
Date	05-Apr-2026
Fault Code / Symptom	Crank No Start
Solution Number	S00001576
Solution Title	Cold weather starting aid malfunction
Update Reason	Solution Removed
Date	05-Apr-2026
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001576
Solution Title	Cold weather starting aid malfunction
Update Reason	Solution Removed
Date	08-Mar-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004290
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	08-Mar-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004290
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	26-Jan-2026
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012663
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Added
Date	26-Jan-2026
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000342
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Removed
Date	18-Jan-2026
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed
Date	11-Jan-2026
Fault Code / Symptom	Black Smoke
Solution Number	S00012651
Solution Title	Damaged camshaft or rocker lever assembly
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Engine Knock
Solution Number	S00012651
Solution Title	Damaged camshaft or rocker lever assembly
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Engine Noise
Solution Number	S00012651
Solution Title	Damaged camshaft or rocker lever assembly
Update Reason	Solution Added

Date	11-Jan-2026
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00012651
Solution Title	Damaged camshaft or rocker lever assembly
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Fuel Knock
Solution Number	S00012651
Solution Title	Damaged camshaft or rocker lever assembly
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00012651
Solution Title	Damaged camshaft or rocker lever assembly
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Low Power
Solution Number	S00012651
Solution Title	Damaged camshaft or rocker lever assembly
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Overhead Noise
Solution Number	S00012651
Solution Title	Damaged camshaft or rocker lever assembly
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00012651
Solution Title	Damaged camshaft or rocker lever assembly
Update Reason	Solution Added

Date	11-Jan-2026
Fault Code / Symptom	White Smoke
Solution Number	S00012651
Solution Title	Damaged camshaft or rocker lever assembly
Update Reason	Solution Added
Date	19-Oct-2025
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00000553
Solution Title	Verify performance complaint
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00012542
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00012542
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012517
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003211
Solution Title	OEM temperature sensor open circuit check
Update Reason	Solution Reordered
Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003211
Solution Title	OEM temperature sensor open circuit check
Update Reason	Solution Modified
Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Reordered

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Modified
Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Reordered
Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Modified
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000411
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Added

Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012387
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added

Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Added

Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Reordered

Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Modified

Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Reordered
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed

Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000411
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Removed
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000352
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000352
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Reordered

Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Modified

Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Reordered

Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Modified

Date	14-Apr-2025
Fault Code / Symptom	Engine Intake Air Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001849
Solution Title	Intake air heater relay resistance check
Update Reason	Solution Added

Date	14-Apr-2025
Fault Code / Symptom	Engine Intake Air Heater 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001849
Solution Title	Intake air heater relay resistance check
Update Reason	Solution Added

Date	09-Feb-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001048
Solution Title	Intake manifold pressure/temperature sensor is malfunctioning
Update Reason	Solution Added
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified
Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed
Date	19-Aug-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00012091
Solution Title	Fuel level check
Update Reason	Solution Added
Date	22-Jul-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	22-Jul-2024
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000689
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000689
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified

Date	26-May-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-May-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001999
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	26-May-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005561
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	26-May-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005561
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007920
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Removed

Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007922
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Removed
Date	12-May-2024
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004266
Solution Title	Water in fuel sensor circuit pin to pin short
Update Reason	Solution Added
Date	12-May-2024
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004266
Solution Title	Water in fuel sensor circuit pin to pin short
Update Reason	Solution Added
Date	12-May-2024
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00004266
Solution Title	Water in fuel sensor circuit pin to pin short
Update Reason	Solution Added

Date	30-Apr-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered
Date	30-Apr-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified
Date	30-Apr-2024
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered
Date	30-Apr-2024
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified
Date	30-Apr-2024
Fault Code / Symptom	Lubricating Oil Temperature High
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered
Date	30-Apr-2024
Fault Code / Symptom	Lubricating Oil Temperature High
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified

Date	14-Apr-2024
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00003076
Solution Title	Gear train backlash is out of adjustment
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered
Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Fuel Knock
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered
Date	14-Apr-2024
Fault Code / Symptom	Fuel Knock
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered

Date	14-Apr-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered
Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001072
Solution Title	Fuel pump actuator resistance check
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001073
Solution Title	Fuel pump actuator short to ground
Update Reason	Solution Removed

Date	07-Apr-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011989
Solution Title	Fuel pump actuator is malfunctioning
Update Reason	Solution Added
Date	07-Apr-2024
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001055
Solution Title	Electric fuel lift pump circuit pin to ground short
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00001576
Solution Title	Cold weather starting aid malfunction
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00001576
Solution Title	Cold weather starting aid malfunction
Update Reason	Solution Modified

Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified

Date	31-Mar-2024
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001576
Solution Title	Cold weather starting aid malfunction
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001576
Solution Title	Cold weather starting aid malfunction
Update Reason	Solution Modified

Date	31-Mar-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified

Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified

Date	31-Mar-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00002009
Solution Title	Fuel pump actuator resistance check
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Removed
Date	24-Dec-2023
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011720
Solution Title	Fuel pump actuator has high resistance
Update Reason	Solution Added
Date	24-Dec-2023
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000859
Solution Title	Fuel pump actuator has high resistance
Update Reason	Solution Removed
Date	24-Dec-2023
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000507
Solution Title	Fuel pump actuator circuit pin to ground short
Update Reason	Solution Removed

Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Reordered
Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Modified
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011547
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006146
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed

Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011547
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006146
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011547
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed

Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Reordered

Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Modified

Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011547
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added

Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed

Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011547
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added

Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006146
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	15-Sep-2023
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000727
Solution Title	Coolant level sensor voltage check
Update Reason	Solution Removed
Date	15-Sep-2023
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000815
Solution Title	Coolant level sensor circuit check
Update Reason	Solution Removed
Date	15-Sep-2023
Fault Code / Symptom	Coolant Level - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000727
Solution Title	Coolant level sensor voltage check
Update Reason	Solution Removed

Date	15-Sep-2023
Fault Code / Symptom	Coolant Level - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000815
Solution Title	Coolant level sensor circuit check
Update Reason	Solution Removed
Date	18-Jun-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Reordered
Date	18-Jun-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Barometric Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004225
Solution Title	Barometric pressure sensor is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Barometric Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004225
Solution Title	Barometric pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001028
Solution Title	Engine brake solenoid circuit pin to pin short
Update Reason	Solution Removed
Date	23-Apr-2023
Fault Code / Symptom	Engine Brake Actuator Driver 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001027
Solution Title	Engine brake solenoid circuit pin to pin short
Update Reason	Solution Added
Date	23-Apr-2023
Fault Code / Symptom	Engine Brake Actuator Driver 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001028
Solution Title	Engine brake solenoid circuit pin to pin short
Update Reason	Solution Removed
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added

Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00008078
Solution Title	Internal ECM Error
Update Reason	Solution Removed
Date	26-Mar-2023
Fault Code / Symptom	High Blowby
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	26-Mar-2023
Fault Code / Symptom	Blue Smoke
Solution Number	S00005035
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	26-Mar-2023
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00011256
Solution Title	Unswitched battery open circuit check
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00009619
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00009619
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00009619
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Low Power
Solution Number	S00009619
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00009619
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000362
Solution Title	Lubricating oil temperature sensor resistance check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000362
Solution Title	Lubricating oil temperature sensor resistance check
Update Reason	Solution Removed

Date	20-Feb-2023
Fault Code / Symptom	Engine Intake Air Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001108
Solution Title	Intake air heater is malfunctioning
Update Reason	Solution Removed
Date	29-Jan-2023
Fault Code / Symptom	Auxiliary Pressure Sensor Input 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010980
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added

Date	01-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Removed

Date	01-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Removed

Date	27-Nov-2022
Fault Code / Symptom	Black Smoke
Solution Number	S00001202
Solution Title	Fuel injector is leaking
Update Reason	Solution Removed

Date	27-Nov-2022
Fault Code / Symptom	Black Smoke
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed

Date	27-Nov-2022
Fault Code / Symptom	Low Power
Solution Number	S00001202
Solution Title	Fuel injector is leaking
Update Reason	Solution Removed

Date	27-Nov-2022
Fault Code / Symptom	Low Power
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed

Date	27-Nov-2022
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000452
Solution Title	Remote accelerator pedal position sensor SIGNAL wire shorted to high source
Update Reason	Solution Removed
Date	20-Nov-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added

Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Auxiliary PWM Driver 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Auxiliary PWM Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	06-Nov-2022
Fault Code / Symptom	Engine Starter Motor Relay Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	16-Oct-2022
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000499
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	09-Oct-2022
Fault Code / Symptom	No Communication ECM to Component
Solution Number	S00010993
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication ECM to Component
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication ECM to Component
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00010993
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	02-Oct-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified

Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified

Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000833
Solution Title	Ambient air temperature sensor open circuit check
Update Reason	Solution Removed
Date	24-Sep-2022
Fault Code / Symptom	
Solution Number	
Solution Title	
Update Reason	QSZ13 CM2150 Z102 New manual released for use.

Last Modified: 23-Aug-2026
