



Service Tool Instruction

Service Tool Instruction
Number: 3377861-2

Revision Level:

Released Date: 15-nov-
2005


Description

Injector Leak Test Kit

Purpose

This document provides information for injector leak test kit, Part Number 3164001. The kit is used to identify faulty injectors on the Signature, ISX, ISX with CM870, and QSX15 engines. For additional information, refer to Procedure 006-026 (/qs3/pubsys2/xml/en/procedures/10/10-006-026.html) in the Signature, ISX, and QSX15 Engines Service Manual, Bulletin 3666239.

©Cummins Inc



05c00123

Table 1, Injector Leak Test Kit, Part Number 3164001

Item Number	Part Number	Description	Quantity
1	3164002	Mounting plate	1
2	3867640	O-ring	5
3	3164009	Hose fitting	1
4	3163527	Flexible tubing	1

