



Technical Service Bulletin: tsb100458

Released Date: 24-Apr-2006

New Heavy Duty Machined-from-Solid Turbocharger Compressor Wheel

New Heavy Duty Machined-from-Solid Turbocharger Compressor Wheel

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin supersedes topic, 05T10-10. Please replace 05T10-10 with this topic.

This Technical Service Bulletin revises data in the CPL to machined-from-solid turbocharger compressor wheel compatibility chart. CPL2610 is removed as a compatible CPL for the ISM 3590045 (cast) and 4038847 (MFS) turbochargers. It is added as a compatible CPL for the ISM, ISMe 3592779 (cast) and 4039198 (MFS) turbochargers.

This Technical Service Bulletin announces a new machined-from-solid turbocharger compressor wheel for certain heavy duty engine and application combinations. The new turbocharger addresses low-cycle fatigue mode issues.

The previous compressor wheel is a cast design with the outer blade contour machined to achieve the desired profile. The sides of the cast wheel blades are in 'as cast' condition.

The new compressor wheel is a machined-from-solid design which is created by machining the wheel from a solid billet of aluminum. All surfaces of the machined-from-solid wheel are machined.

This product improvement is **not** covered by warranty.

Only certain, high-duty cycle applications are eligible to receive machined-from-solid turbocharger compressor wheels.

Only certain high-duty cycle applications are subject to a temporary repair practice (TRP). In most instances, cast wheels have **not** been obsoleted and superseded.

Consult QuickServe® Online to determine if a given engine and application combination is eligible to receive this product improvement.

Note : This is a product improvement and not subject to campaign.

The compatibility chart below shows the machined-from-solid turbocharger compressor wheels that can potentially be used with the CPLs listed.

Engine	CPL	Cast Turbocharger Part Number	MFS Turbocharger Part Number	MFS Service Kit	ReCon® Part Number	Direct Super session?	Application/Comments
ISM, ISM ^e	2350, 2614, 2830	3592782	4039200	4089922	4089922 NX	No	Automotive
ISM ^e	2830	4037740	N/A	N/A	N/A	No	Korean bus - no MFS for this - CCV
ISM	2012, 2036, 2037, 2040, 2041, 2178, 2199, 2200, 2370, 2371, 2477, 2562, 2563, 2576, 2607, 2608, 2611, 2612, 2615	3590045	4038847	4089818	N/A	No	Automotive
ISM	2140, 2141, 2201, 2425	3537066	3599956	4089599	4089599 RX	Yes	Transit bus (San Francisco)
ISM, ISM ^e	2350, 2610, 2614, 2830	3592779	4039198	4089921	4089921 NX	No	

Engine	CPL	Cast Turboch arger Part Number	MFS Turboch arger Part Number	MFS Service Kit	ReCon® Part Number	Direct Super session?	Applicati on/Com ments
ISM, ISM e	2350, 2614, 2830	3592776	4039196	4089821	4089821 NX	No	Automoti ve and Hong Kong bus
QSM	2828, 8409	3593607	4040345	4089988	4089988 RX	No	FEL
ISX1	8037, 8046, 8047, 8048, 8049, 8083, 8084, 8242, 8243, 8255, 8256, 8257, 8258	3595091	4036900	4089754	4089754 RX	Yes	Automoti ve
ISX1	8037, 8046, 8047, 8048, 8049, 8083, 8084, 8242, 8243, 8255, 8256, 8257, 8258	3595093	4036902	4089754	4089754 RX	Yes	Automoti ve
ISX2	2629, 2632, 2933, 2934, 8244, 8245	3596622	4037481	4089768	4089768 RX	Yes	Automoti ve

Engine	CPL	Cast Turboch arger Part Number	MFS Turboch arger Part Number	MFS Service Kit	ReCon® Part Number	Direct Super session?	Applicati on/Com ments
ISX2	2629, 2632, 2933, 2934, 8244, 8245	3596623	4037482	4089768	4089768 RX	Yes	Automoti ve
ISX3	2442, 2630, 2633, 2801, 2802, 2834, 2835, 8246, 8247	3596624	4038282	4089760	4089760 NX	Yes	Automoti ve
ISX3	2442, 2630, 2633, 2801, 2802, 2834, 2835, 8246, 8247	3596625	4038283	4089760	4089760 NX	Yes	Automoti ve
QSX15	2825, 8469, 8489, 8571, 8741, 8742	3598763	4038500	4089970	4089970 NX	No	Industrial
QSX15	2825, 8469, 8489, 8571, 8741, 8742	3598764	4038501	4089970	4089970 NX	No	Industrial

Engine	CPL	Cast Turboch arger Part Number	MFS Turboch arger Part Number	MFS Service Kit	ReCon® Part Number	Direct Super session?	Applicati on/Com ments
Qsx15	2825, 8469, 8489, 8571, 8741, 8742	3598765	4038502	4089970	4089970 NX	No	Industrial

Last Modified: 24-Apr-2006
