



Technical Service Bulletin

Technical Service Bulletin: tsb100666

Released Date: 28-Jan-2008

Monotherm® Pistons

Monotherm® Pistons

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts obsoletes topic 07T1-56. Replace 07T1-56 with this topic.

This Technical Service Bulletin announces the articulated piston, Part Number 4059345, used on QSX15 engines, will no longer be available as a service part. This piston is being replaced by Monotherm® piston, Part Number 4923744.

Due to the articulated piston **not** being available, two important items **must** be considered.

⚠ CAUTION ⚠

Replacing any fewer than all six (6) articulated pistons with Monotherm® pistons could result in significant engine damage.

⚠ CAUTION ⚠

Failure to install connecting rods and bearings with an oil feed hole for Monotherm® pistons can result in significant engine damage.

1. Articulated pistons and Monotherm® pistons can **not** be mixed in an engine. If replacing an articulated piston with a Monotherm® piston, all cylinders **must** be upgraded.
2. When upgrading to Monotherm® pistons use connecting rods that are equipped with the oil drillings to the wrist pin bushing, as well as, drilled upper rod bearings, redesigned piston pins and an updated piston ring set. Please contact a Cummins® Authorized Repair Location for additional information.

Articulated Piston (No Longer Available)	Monotherm® Piston
4059345	4923744

Non-Drilled Connecting Rods		Drilled Connection Rods	
3681343 NX/RX		4059429 NX	
Non-Drilled Connecting Rod Bearing Set		Drilled Connecting Rod Bearing Set	
4089139		4089405	
Articulated Piston/Cylinder Kits	Monotherm® Overhaul Upgrade Kit		4955599
4089610	Piston Kit		
4025216	Cylinder Kit		
4025314	Cylinder Kit		
Note : Individual articulated piston and cylinder kits are being superseded to a complete Monotherm® overhaul upgrade kit, facilitate the complete conversion of all six cylinders.			
Monotherm® Overhaul Upgrade Kit Contents 4955599			
Part Number	Quantity	Description	
3064305	12	Ring, Retaining	
3678738	6	Seal, O-ring	
3800298	1	Set, Main Bearing	
3820320	1	Plunger, Bypass Valve	
4059429	6	Rod, Engine Connecting	
4089405	6	Set, Rod Bearing (Standard)	
4089406	6	Set, Piston Ring	
4101507	6	Liner, Cylinder	
4923744	6	Piston, Engine	
4923748	6	Pin, Piston	
4955590	1	Set, Lower Engine Gasket	
4955595	1	Set, Upper Engine Gasket	

Last Modified: 28-Jan-2008
