



Technical Service Bulletin

Technical Service Bulletin: tsb102247

Released Date: 10-May-2007

Revision, Maintenance Schedule, Fuel Filter Change Interval

Revision, Maintenance Schedule, Fuel Filter Change Interval

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic changes the Fuel Filter (Spin-On Type) change interval from 1,500 Hours, or 1 Year to 250 Hours, or 6 Months, in Maintenance Schedule, Procedure 100-002.

Related Procedures

10-102-002-om-ind
(/qs3/pubsys2/xml/en/procedures/10/10-102-002-om-ind.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/10/10-102-002-om-ind.html)

Last Modified: 10-May-2007