



Technical Service Bulletin

Technical Service Bulletin: tsb102627	Released Date: 01-Feb-2008
Revision, Circuit Diagram, Fault Code 482	

Revision, Circuit Diagram, Fault Code 482

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Fault Code 482 to include a numbered component list to follow the system circuit graphic.

Low Fuel Pressure

Last Modified: 01-Feb-2008
