



Technical Service Bulletin

Technical Service Bulletin: tsb102838

Released Date: 02-May-2008

Addition, Measure Step, Lubricating Oil Filter (Spin-On) Procedure

Addition, Measure Step, Lubricating Oil Filter (Spin-On) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds a Measure step to Procedure 007-013 (Lubricating Oil Filter (Spin-On)) in Section 7 of the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239, to check for a plugged filter by measuring the pressure drop across the lubricating oil filter.

Related Procedures

10-007-013-tr
(/qs3/pubsys2/xml/en/procedures/10/10-007-013-tr.html)

Lubricating Oil Filter (Spin-On)
(/qs3/pubsys2/xml/en/procedures/10/10-007-013-tr.html)

Last Modified: 02-May-2008