



Technical Service Bulletin

Technical Service Bulletin: tsb102878

Released Date: 06-Jun-2008

Bearings, Connecting Rod and Piston and Connecting Rod Assembly Procedures Install
Section Revisions

Bearings, Connecting Rod and Piston and Connecting Rod Assembly Procedures Install Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Install section of Procedures 001-005 (Bearings, Connecting Rod) and 001-054 (Piston and Connecting Rod Assembly) in the K19 Service Manual, Bulletin 4021499.

Related Procedures

18-001-005 (/qs3/pubsys2/xml/en/procedures/18/18-001-005.html)	Bearings, Connecting Rod (/qs3/pubsys2/xml/en/procedures/18/18-001-005.html)
18-001-054-tr (/qs3/pubsys2/xml/en/procedures/18/18-001-054-tr.html)	Piston and Connecting Rod Assembly (/qs3/pubsys2/xml/en/procedures/18/18-001-054-tr.html)

Last Modified: 06-Jun-2008