



Technical Service Bulletin

Technical Service Bulletin: tsb103072

Released Date: 19-Sep-2008

Lubricating Oil System Specifications, Revision

Lubricating Oil System Specifications, Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates Procedure 018-017 (Lubricating Oil System) in the specifications section of the Signature™, ISX, and QSX15 manuals listed above.

- The update changes the lubricating oil pan capacity for power generation applications to 90.8 liters [24 gal].

Related Procedures

10-018-017

(/qs3/pubsys2/xml/en/procedures/10/10-018-017.html)

Lubricating Oil System

(/qs3/pubsys2/xml/en/procedures/10/10-018-017.html)

Last Modified: 19-Sep-2008