



Technical Service Bulletin

Technical Service Bulletin: tsb103145

Released Date: 10-Oct-2008

Maintenance Schedule Revision, Overhead Set

Maintenance Schedule Revision, Overhead Set

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 102-002 (Maintenance Schedule) to remove the Overhead Set - Adjust procedure from the maintenance schedule in Section 2 of the Operation and Maintenance Manual QSK23 Series Engine, Bulletin 4021374.

Related Procedures

89-102-002-om
(/qs3/pubsys2/xml/en/procedures/89/89-102-002-om.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/89/89-102-002-om.html)

Last Modified: 10-Oct-2008