



Technical Service Bulletin

Technical Service Bulletin: tsb103189	Released Date: 20-Nov-2008
Symptom Tree t103-56 (Lubricating Oil Filter Plugged), Major Revision	

Symptom Tree t103-56 (Lubricating Oil Filter Plugged), Major Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Symptom Tree t103-56 (Lubricating Oil Filter Plugged) to give more specific instructions as to when the unit should return to service. Several steps have also been modified and added for clarity.

Lubricating Oil Filter Plugged

Last Modified: 20-Nov-2008
