



Technical Service Bulletin

Technical Service Bulletin: tsb103458

Released Date: 24-Apr-2009

Maintenance Schedule, Crankcase Breather Element Revision

Maintenance Schedule, Crankcase Breather Element Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Section 7 with the removal of the 1 year specification from the section title in Procedure 102-002 (Maintenance Schedule) in the Signature™ and ISX Operation and Maintenance Manual, Bulletin 3666251. The crankcase breather element maintenance, in Section 7, is an emissions related component and can **not** have a time limit specified for a service interval. The customer **must** use the mileage or hours as a guideline.

Related Procedures

10-102-002-om-auto
(/qs3/pubsys2/xml/en/procedures/10/10-102-002-om-auto.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/10/10-102-002-om-auto.html)

Last Modified: 24-Apr-2009