



Technical Service Bulletin

Technical Service Bulletin: tsb103953

Released Date: 21-Sep-2009

Lubricating Oil Filter Head Adapter Procedure, Remove Section Revision

Lubricating Oil Filter Head Adapter Procedure, Remove Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-018 (Lubricating Oil Filter Head Adapter) in Section 7 in Service Manual, Signature™, ISX, and QSX15, Bulletin 3666239. Information on removing a remote filter head adapter from the lubricating oil filter head was added to the Remove section of this procedure.

Related Procedures

10-007-018-tr
(/qs3/pubsys2/xml/en/procedures/10/10-007-018-tr.html)

Lubricating Oil Filter Head Adapter
(/qs3/pubsys2/xml/en/procedures/10/10-007-018-tr.html)

Last Modified: 21-Sep-2009