



Technical Service Bulletin

Technical Service Bulletin: tsb104130

Released Date: 21-Apr-2010

Cylinder Head Procedure, Inspect for Reuse and Measure Section Revisions

Cylinder Head Procedure, Inspect for Reuse and Measure Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 002-004 (Cylinder Head) in Service Manual, Signature™, ISX, and QSX15, Bulletin 3666239. The valve recess specification was revised in the Inspect for Reuse and Measure sections.

Related Procedures

10-002-004-tr
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Last Modified: 21-Apr-2010