



Technical Service Bulletin

Technical Service Bulletin: TSB110055

Released Date: 18-Mar-2011

New ISX Liner Located Piston Cooling Nozzle

New ISX Liner Located Piston Cooling Nozzle

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces the new ISX "liner located" piston cooling nozzle (PCN). The nozzle has changed from a "block located" piston cooling nozzle to a "liner located" piston cooling nozzle. The main reason for this change was to improve piston cooling nozzle targeting, by locating the nozzle off of a machined part (the liner) rather than a cast part (the cylinder block). Targeting variation is significantly reduced as a result of this nozzle location change.



01a00279

Old "Block Located" Nozzle



01a00280

New "Liner Located" Nozzle



01a00281

"Liner Located Nozzle" Installed in the Block

These new nozzles are completely backwards compatible and can be mixed or matched within an engine.

Table 1: "Liner Located" Nozzle Supersession Information

Engine Family	New Piston Cooling Nozzle Part Number	Old Piston Cooling Nozzle Part Number	Engine Serial Number (ESN) First	Start Date
ISX/QSX (15 Liter)	3687058	3412860	79452563	12/13/10

Document History

Date	Details
2011-2-25	Module Created

