



Technical Service Bulletin

Technical Service Bulletin: TSB120232

Released Date: 02-Oct-2012

ISX/QSX and ISM/QSM CM570 Horsepower and Torque Ratings Can Display Incorrectly in INSITE™ Electronic Service Tool

ISX/QSX and ISM/QSM CM570 Horsepower and Torque Ratings Can Display Incorrectly in INSITE™ Electronic Service Tool

Core Issue

When connected to a unit's engine control module (ECM) with INSITE™ electronic service tool, the horsepower and torque ratings may **not** be displayed.

Confirmation

When connected to a unit's ECM with INSITE™ electronic service tool, Features and Parameters will display the engine's horsepower and torque ratings. The ratings are listed in System Information under the System ID and Dataplate Section of Features and Parameters.

If the calibration that is presently in the ECM is affected, the values will be shown as zeros.

Resolution

There is no solution readily available to make the horsepower and torque values display correctly in INSITE™ electronic service tool. If the horsepower and torque values are needed, the values are displayed in the Calibration Selection tab for each particular ECM Code. An INCAL™ DVD or the calibration downloaded from QuickServe™ Online, once loaded into INSITE™ electronic service tool, will display the needed values.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2012-7-27	Module Created
2012-8-21	Information update

