



Technical Service Bulletin

Technical Service Bulletin: TSB140145

Released Date: 10-Mar-2015

New Valve Springs for All Four Valve per Cylinder B/C/F/L Series Engines

New Valve Springs for All Four Valve per Cylinder B/C/F/L Series Engines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces new valve springs for all four valve per cylinder B/C/F/L series engines.

The valve springs are backward compatible and transparent to assembly. Service parts became available on 02 September 2014. In stock parts are affected. See Parts Alert MDC-040-14 for details. A paint color visual check is available to distinguish the new valve springs from the obsolete valve springs.

When changing valve springs, both valve springs under the same crosshead for any midrange engine should be changed. See TSB130158 for reference.

Table 1, Valve Spring Information

Obsolete Part Number	Obsolete Valve Spring Color	New Part Number	New Valve Spring Color	Engine Family
4936076 / 5292626	Green	5316172	White	C/L
4936079 / 5292627	Blue	5316173	Purple	C/L, Using Valve Rotator
4936080 / 5292628	Orange	5303406	Pink	B/F

Table 2, Valve Spring Plant Information

	Rocky Mountain Engine Plant	Darlington Engine Plant	Columbus Midrange Engine Plant	Beijing Foton Cummins Engine Company
--	-----------------------------	-------------------------	--------------------------------	--------------------------------------

New Part Number	ESN First	Build Date	ESN First	Build Date	ESN First	Build Date	ESN First	Build Date
5316172	73690315	27 May 2014	22132344	24 June 2014	N/A	N/A	N/A	N/A
5316173	73691698	29 May 2014	22132344	24 June 2014	N/A	N/A	N/A	N/A
5303406	73706610	07 July 2014	22136940	23 July 2014	58432697	09 July 2014	89173464	14 June 2014

Engine build date can be found on the engine dataplate.

The following plants may also be affected, however ESN first and build date information is not available.

Plants affected for Part Numbers 5316172 and 5316173

- Cummins Brazil S.A.
- Cummins S.A. (Mexico)
- Komatsu Cummins Engine Co. (Oyama)

Plants affected for Part Number 5303406

- Cummins Brazil S.A.
- Cummins S.A. (Mexico)
- Hyundai Cummins Engine Co
- Komatsu Cummins Engine Co. (Oyama)

Document History

Date	Details
2014-10-6	Module Created
2015-3-6	none

Last Modified: 10-Mar-2015
