



Technical Service Bulletin

Technical Service Bulletin: TSB150179

Released Date: 03-Dec-2015

New Valve Camshaft Removal and Installation Service Tool Kit

New Valve Camshaft Removal and Installation Service Tool Kit

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected


- ISX15 (All Versions)
- QSX15 (All Versions)

Description of Change

A new valve camshaft removal and installation service tool kit has been released.

Reason for Change

The valve camshaft removal and installation service tool kit has been released to provide easier removal and installation of the valve camshaft in and out of the cylinder head. The valve camshaft removal and installation tool service kit, Part Number 5299837 includes two pilots, Part Numbers 5299839 and 5299844, and one sleeve, Part Number 5299841, that are used to provide a centering guide for one end of the camshaft while being inserted or removed from the cylinder head.



22r00035

Figure 1, Valve Camshaft Removal and Installation Service Tool Kit. From Left: 5299844, 5299839, and 5299841

Service Instructions

A video showing the valve camshaft removal and installation service tool kit being used to install a valve camshaft can be seen below.

Note : <http://tsb.cumminsvirtualcollege.com/TSB150179.aspx>
(<http://tsb.cumminsvirtualcollege.com/TSB150179.aspx>)

As demonstrated in the video above, the need to manually guide the valve camshaft lobes and journals through the bores during this process has been eliminated. This reduces the amount of handling required to install the valve camshaft and minimizes the potential for valve camshaft bushing damage.

The service tool connects magnetically to either end of the valve camshaft to allow for installation from either the front or rear of the engine, depending on access requirements. The valve camshaft removal and installation tool service kit is also segmented and can be shortened between the valve camshaft bores for in-chassis or restricted access installations.

Service Tools Available

The service tool is available. See Table 1 for part numbers.

Table 1, Service Tool	
Part Description	New Part Number
Valve Camshaft Removal and Installation Service Tool	5299837

Publications Affected

Table 3, Affected Publications

Manual Type	Bulletin Number	Procedure Title	Procedure
Signature, ISX, and QSX15 Service Manual	3666239	Overhead Camshaft, Valve	002-024
		Service Tools	022-001
ISX15 CM2250 Service Manual	4022250	Overhead Camshaft, Valve	002-024
		Service Tools	022-001
ISX15 CM2250 SN Service Manual	4310736	Overhead Camshaft, Valve	002-024
		Service Tools	022-001
ISX15 CM2350 X101 Service Manual	4310641	Overhead Camshaft, Valve	002-024
		Service Tools	022-001
QSX15 CM2250 ECF Service Manual	2883557	Overhead Camshaft, Valve	002-024
		Service Tools	022-001
QSX15 CM2350 X105 Service Manual	4332667	Overhead Camshaft, Valve	002-024
		Service Tools	022-001
QSX15 CM2350 X106 Service Manual	4332712	Overhead Camshaft, Valve	002-024
		Service Tools	022-001

Document History

Date	Details
2015-11-5	Module Created

Last Modified: 03-Dec-2015
