



Technical Service Bulletin: TSB210075

Released Date: 09-Apr-2021

Lubricating Oil System Pressure Pulsations

## Lubricating Oil System Pressure Pulsations

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

#### Product Affected

- QSX15 CM2250
- QSX15 CM2250 ECF
- QSX15 CM2250 X115
- QSX15 CM2350 X105
- QSX15 CM2350 X106
- QSX15 CM2350 X118
- QSX15 CM2350 X130C
- QSX15 CM570

#### Issue

Symptom:

- Unusual lubricating oil pressure fluctuations with remote lubricating oil filter lines with part option LF 1278.

Root Cause:

- The feedback system in the lubricating oil pump is underdamped.

#### Verification

Operate the engine at 1000 rpm and look for oil pressure pulsations greater than 30 kPa [ 5 psi ].

#### Resolution

- The lubricating oil pressure pulsation will **not** damage the engine.
- A new lubricating oil pump with a smaller feedback orifice was released. Reference Table 1 below.

#### Service Instructions

Engines with remote mount lubricating oil filter options, or that have experienced pressure pulsation issues should be repaired with the new lubricating oil pump part number.

### Service Parts Availability

Service parts are available. See Table 1 for part numbers.

| Table 1, Service Parts           |                      |          |            |                 |
|----------------------------------|----------------------|----------|------------|-----------------|
| Part Description                 | Existing Part Number | Obsolete | Superseded | New Part Number |
| PUMP,<br>LUBRICATING<br>OIL PUMP | 5532492              | Yes      | Yes        | 5599284         |

### Production Status

Implemented for production. See Table 2.

| Table 2, Production Information                                  |                         |                        |
|------------------------------------------------------------------|-------------------------|------------------------|
| ESN First                                                        | Build Date <sup>1</sup> | Plant                  |
| 80289282                                                         | 3 November 2020         | Jamestown Engine Plant |
| <sup>1</sup> Engine build date can be found on engine dataplate. |                         |                        |

## Document History

| Date     | Details        |
|----------|----------------|
| 2021-4-1 | Module Created |

---

Last Modified: 09-Apr-2021

---