



Technical Service Bulletin

Technical Service Bulletin: TSB240015

Released Date: 18-Jan-2024

New Turbocharger Oil Supply Flexible Hose Part Number

New Turbocharger Oil Supply Flexible Hose Part Number

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISM CM570
- ISM CM870
- ISM CM875
- ISM CM876 E
- ISM CM876,
- ISM11 CM876 M103
- ISM11 CM876 SN
- M11 CELECT
- M11 CELECT PLUS
- M11 MECHANICAL
- QSM11 CM570
- QSM11 CM876

Description of Change

A new turbocharger oil supply flexible hose part number is available.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Flexible Hose	2864075	No	No	5546511

Document History

Date	Details
2024-1-11	Module Created

Last Modified: 18-Jan-2024
