



Service Bulletin Number: 3666244

Released Date: 01-jul-1997

Unauthorized Adjustment of Midrange Fuel Injection Pumps

Unauthorized Adjustment of Midrange Fuel Injection Pumps

Purpose

The fuel adjusting screw on Cummins Inc. Midrange engines (B and C Series) is very sensitive to overfueling. Special test equipment and training are required to adjust the injection pump properly. Any adjustment other than those specifically stated in Cummins Inc. literature is viewed as tampering and can result in the following:

1. Increase emissions regulatory standards are exceeded.
2. Void the fuel system manufacturer's warranty if the fuel injection pump settings have been changed beyond specifications.
3. Void Cummins Inc. warranty for failures resulting from overfueling.
4. Increase cylinder pressures beyond design limits.
5. Reduce engine reliability and durability.
6. Reduce fuel economy.
7. Lead to premature failure of drive line or drive components.

Note : This restriction applies to all Cummins Inc. Midrange engine pumps.

If there is a power or performance complaint, reference the appropriate troubleshooting and repair manual for "Engine Power Output Low" symptom tree. If the problem is **not** resolved, the fuel injection pump can be removed and checked by authorized fuel equipment personnel **only**.

⚠ CAUTION ⚠

Do not adjust Midrange engine fuel injection pumps. Adjustments can result in equipment failure and violation of State and Federal laws.

When an engine is changed or modified it **must** comply with the Federal tampering prohibition as contained in Section 203 (a) (3) of the Clean Air Act (Act) 42 U.S.C. S7522 (a) (3). Section 203 (a) (3) (A) of the Act prohibits any person from removing or rendering inoperative any emissions control device or element of design installed on or in a motor vehicle or motor vehicle engine prior to its sale and delivery to an ultimate purchaser and prohibits a dealer or manufacturer from knowingly removing or rendering inoperative any such device or element or design after such sale and delivery, and the causing thereof. The maximum civil penalty for a violation of this section is \$10,000 (dollars).

Section 203 (a) (3) (B) of the Act prohibits fleet operators and persons engaged in the business of servicing, repairing, selling, leasing, or trading motor vehicles or motor vehicle engines from knowingly removing or rendering inoperative any emission control device or element of design installed on or in a motor vehicle or motor vehicle engine after its sale and delivery to the ultimate purchaser and the causing thereof. The maximum civil penalty for a violation of this section is \$2,500 (dollars).

California Vehicle Code Section 27156, the state's anti-tampering statute prohibits the advertising, sale, offering for sale, or installation of any device which modifies a vehicle's emission control system, unless exempted by the Air Resources Board (ARB).