

Manual Change History (3666003) C Troubleshooting and Repair Manual

Date	Not Available
Section	front
Procedure Number	3666003-toc (/qs3/pubsys2/xml/en/manual/3666003/3666003-toc.html)
Procedure Title	Table of Contents
Update Reason	

Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-004 (/qs3/pubsys2/xml/en/procedures/99/99-204-004.html)
Procedure Title	Symbols
Update Reason	

Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-005 (/qs3/pubsys2/xml/en/procedures/99/99-204-005.html)
Procedure Title	Illustrations
Update Reason	

Date	03-Apr-2002
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-002 (/qs3/pubsys2/xml/en/procedures/99/99-t00-002.html)
Procedure Title	Troubleshooting Symptom Charts
Update Reason	

Date	03-Sep-2002
Section	Section 14 - Engine Testing - Group 14
Procedure Number	41-014-012 (/qs3/pubsys2/xml/en/procedures/41/41-014-012.html)
Procedure Title	Engine Compression
Update Reason	
Date	08-Oct-2002
Section	Section 8 - Cooling System - Group 08
Procedure Number	99-008-040 (/qs3/pubsys2/xml/en/procedures/99/99-008-040.html)
Procedure Title	Fan, Cooling
Update Reason	
Date	05-May-2003
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	100-016-010 (/qs3/pubsys2/xml/en/procedures/100/100-016-010.html)
Procedure Title	Engine Mounts
Update Reason	
Date	13-May-2003
Section	front
Procedure Number	3666003-titlepage (/qs3/pubsys2/xml/en/manual/3666003/3666003-titlepage.html)
Procedure Title	Titlepage
Update Reason	
Date	13-May-2003
Section	Section F - Familiarization
Procedure Number	41-000-999 (/qs3/pubsys2/xml/en/procedures/41/41-000-999.html)
Procedure Title	Complete Engine - Overview
Update Reason	

Date	13-May-2003
Section	Section F - Familiarization
Procedure Number	41-001-999 (/qs3/pubsys2/xml/en/procedures/41/41-001-999.html)
Procedure Title	Cylinder Block - Overview
Update Reason	
Date	13-May-2003
Section	Section F - Familiarization
Procedure Number	41-002-999 (/qs3/pubsys2/xml/en/procedures/41/41-002-999.html)
Procedure Title	Cylinder Head - Overview
Update Reason	
Date	13-May-2003
Section	Section F - Familiarization
Procedure Number	41-004-999 (/qs3/pubsys2/xml/en/procedures/41/41-004-999.html)
Procedure Title	Cam Followers/Tappets - Overview
Update Reason	
Date	13-May-2003
Section	Section F - Familiarization
Procedure Number	41-007-999-tr (/qs3/pubsys2/xml/en/procedures/41/41-007-999-tr.html)
Procedure Title	Lubricating Oil System - Overview
Update Reason	
Date	13-May-2003
Section	Section F - Familiarization
Procedure Number	41-008-999 (/qs3/pubsys2/xml/en/procedures/41/41-008-999.html)
Procedure Title	Cooling System - Overview
Update Reason	

Date	13-May-2003
Section	Section F - Familiarization
Procedure Number	41-011-999 (/qs3/pubsys2/xml/en/procedures/41/41-011-999.html)
Procedure Title	Exhaust System - Overview
Update Reason	
Date	13-May-2003
Section	Section F - Familiarization
Procedure Number	41-012-999 (/qs3/pubsys2/xml/en/procedures/41/41-012-999.html)
Procedure Title	Compressed Air System - Overview
Update Reason	
Date	13-May-2003
Section	Section F - Familiarization
Procedure Number	41-013-999 (/qs3/pubsys2/xml/en/procedures/41/41-013-999.html)
Procedure Title	Electrical Equipment - Overview
Update Reason	
Date	13-May-2003
Section	Section F - Familiarization
Procedure Number	41-014-999 (/qs3/pubsys2/xml/en/procedures/41/41-014-999.html)
Procedure Title	Engine Testing - Overview
Update Reason	
Date	13-May-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-026 (/qs3/pubsys2/xml/en/procedures/41/41-001-026.html)
Procedure Title	Cylinder Block
Update Reason	

Date	13-May-2003
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-002-016 (/qs3/pubsys2/xml/en/procedures/41/41-002-016.html)
Procedure Title	Valve Guide Seal, Cylinder Head
Update Reason	
Date	13-May-2003
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	41-022-001_04 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_04.html)
Procedure Title	Service Tools
Update Reason	
Date	13-May-2003
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-005-001 (/qs3/pubsys2/xml/en/procedures/41/41-005-001.html)
Procedure Title	AFC Assembly
Update Reason	
Date	13-May-2003
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-005-008 (/qs3/pubsys2/xml/en/procedures/41/41-005-008.html)
Procedure Title	Engine Fuel Heater, Electric
Update Reason	
Date	13-May-2003
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-005-013 (/qs3/pubsys2/xml/en/procedures/41/41-005-013.html)
Procedure Title	Fuel Injection Pump, In-Line, Spill Port Timing
Update Reason	

Date	13-May-2003
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-005-029 (/qs3/pubsys2/xml/en/procedures/41/41-005-029.html)
Procedure Title	Fuel Pump Idle Speed
Update Reason	
Date	13-May-2003
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-005-043 (/qs3/pubsys2/xml/en/procedures/41/41-005-043.html)
Procedure Title	Fuel Shutoff Valve
Update Reason	
Date	13-May-2003
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-005-045 (/qs3/pubsys2/xml/en/procedures/41/41-005-045.html)
Procedure Title	Fuel Lift Pump
Update Reason	
Date	13-May-2003
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	41-007-051 (/qs3/pubsys2/xml/en/procedures/41/41-007-051.html)
Procedure Title	Lubricating Oil Analysis
Update Reason	
Date	13-May-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	41-022-001_08 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_08.html)
Procedure Title	Service Tools
Update Reason	

Date	13-May-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	41-008-009 (/qs3/pubsys2/xml/en/procedures/41/41-008-009.html)
Procedure Title	Coolant Filter Valve
Update Reason	
Date	13-May-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	41-008-017 (/qs3/pubsys2/xml/en/procedures/41/41-008-017.html)
Procedure Title	Coolant Vent Lines
Update Reason	
Date	13-May-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	41-008-060 (/qs3/pubsys2/xml/en/procedures/41/41-008-060.html)
Procedure Title	Supplemental Coolant Additive (SCA)
Update Reason	
Date	13-May-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-022-001_10 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_10.html)
Procedure Title	Service Tools
Update Reason	
Date	13-May-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-010-050 (/qs3/pubsys2/xml/en/procedures/41/41-010-050.html)
Procedure Title	Turbocharger Wastegate Actuator
Update Reason	

Date	13-May-2003
Section	Section 14 - Engine Testing - Group 14
Procedure Number	41-022-001_14 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_14.html)
Procedure Title	Service Tools
Update Reason	
Date	21-Jul-2003
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	100-016-006 (/qs3/pubsys2/xml/en/procedures/100/100-016-006.html)
Procedure Title	Flywheel Housing
Update Reason	
Date	21-Jul-2003
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	100-017-007 (/qs3/pubsys2/xml/en/procedures/100/100-017-007.html)
Procedure Title	Pipe Plug
Update Reason	
Date	18-Aug-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-057 (/qs3/pubsys2/xml/en/procedures/100/100-001-057.html)
Procedure Title	Engine Dataplate
Update Reason	
Date	18-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	100-013-003 (/qs3/pubsys2/xml/en/procedures/100/100-013-003.html)
Procedure Title	Alternator Bracket
Update Reason	

Date	20-Aug-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-024 (/qs3/pubsys2/xml/en/procedures/100/100-001-024.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	
Date	20-Aug-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-025 (/qs3/pubsys2/xml/en/procedures/100/100-001-025.html)
Procedure Title	Crankshaft Wear Sleeve, Front
Update Reason	
Date	20-Aug-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-052 (/qs3/pubsys2/xml/en/procedures/100/100-001-052.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	
Date	22-Aug-2003
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-001 (/qs3/pubsys2/xml/en/procedures/41/41-006-001.html)
Procedure Title	AFC Air Tube
Update Reason	
Date	22-Aug-2003
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-003 (/qs3/pubsys2/xml/en/procedures/41/41-006-003.html)
Procedure Title	Air in Fuel
Update Reason	

Date	22-Aug-2003
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-020 (/qs3/pubsys2/xml/en/procedures/41/41-006-020.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	
Date	22-Aug-2003
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-021-tr (/qs3/pubsys2/xml/en/procedures/41/41-006-021-tr.html)
Procedure Title	Fuel Manifold (Drain)
Update Reason	
Date	22-Aug-2003
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-024 (/qs3/pubsys2/xml/en/procedures/41/41-006-024.html)
Procedure Title	Fuel Supply Lines
Update Reason	
Date	22-Aug-2003
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-044 (/qs3/pubsys2/xml/en/procedures/41/41-006-044.html)
Procedure Title	Fuel Return Overflow Valve
Update Reason	
Date	22-Aug-2003
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-051 (/qs3/pubsys2/xml/en/procedures/41/41-006-051.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	

Date	26-Aug-2003
Section	Section F - Familiarization
Procedure Number	41-010-999 (/qs3/pubsys2/xml/en/procedures/41/41-010-999.html)
Procedure Title	Air Intake System - Overview
Update Reason	
Date	26-Aug-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-122 (/qs3/pubsys2/xml/en/procedures/100/100-010-122.html)
Procedure Title	Intake Manifold Air Heater Wiring Harness
Update Reason	
Date	26-Aug-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-123 (/qs3/pubsys2/xml/en/procedures/100/100-010-123.html)
Procedure Title	Intake Manifold Air Heater Temperature Sensor
Update Reason	
Date	26-Aug-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-124 (/qs3/pubsys2/xml/en/procedures/100/100-010-124.html)
Procedure Title	Intake Manifold Air Heater Element
Update Reason	
Date	26-Aug-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-125 (/qs3/pubsys2/xml/en/procedures/100/100-010-125.html)
Procedure Title	Intake Manifold Air Heater Control Module
Update Reason	

Date	26-Aug-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-126 (/qs3/pubsys2/xml/en/procedures/100/100-010-126.html)
Procedure Title	Intake Manifold Air Heater Solenoid Switch
Update Reason	
Date	26-Aug-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-127 (/qs3/pubsys2/xml/en/procedures/100/100-010-127.html)
Procedure Title	Intake Manifold Air Heater Speed Sensor
Update Reason	
Date	26-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	99-013-007 (/qs3/pubsys2/xml/en/procedures/99/99-013-007.html)
Procedure Title	Batteries
Update Reason	
Date	26-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	99-013-009 (/qs3/pubsys2/xml/en/procedures/99/99-013-009.html)
Procedure Title	Battery Cables and Connections
Update Reason	
Date	28-Aug-2003
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	100-007-001 (/qs3/pubsys2/xml/en/procedures/100/100-007-001.html)
Procedure Title	Engine Oil Heater
Update Reason	

Date	28-Aug-2003
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	100-007-011 (/qs3/pubsys2/xml/en/procedures/100/100-007-011.html)
Procedure Title	Lubricating Oil Dipstick Tube
Update Reason	
Date	28-Aug-2003
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	100-007-037 (/qs3/pubsys2/xml/en/procedures/100/100-007-037.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	02-Sep-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-089 (/qs3/pubsys2/xml/en/procedures/100/100-001-089.html)
Procedure Title	Block Stiffener Plate
Update Reason	
Date	02-Sep-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-007 (/qs3/pubsys2/xml/en/procedures/100/100-008-007.html)
Procedure Title	Coolant Filter Head
Update Reason	
Date	02-Sep-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-013 (/qs3/pubsys2/xml/en/procedures/100/100-008-013.html)
Procedure Title	Coolant Thermostat
Update Reason	

Date	02-Sep-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-039 (/qs3/pubsys2/xml/en/procedures/100/100-008-039.html)
Procedure Title	Fan Spacer and Pulley
Update Reason	
Date	02-Sep-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-042 (/qs3/pubsys2/xml/en/procedures/100/100-008-042.html)
Procedure Title	Radiator
Update Reason	
Date	02-Sep-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-080 (/qs3/pubsys2/xml/en/procedures/100/100-008-080.html)
Procedure Title	Belt Tensioner, Automatic (Water Pump)
Update Reason	
Date	02-Sep-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-019 (/qs3/pubsys2/xml/en/procedures/100/100-010-019.html)
Procedure Title	Air Crossover
Update Reason	
Date	02-Sep-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-045 (/qs3/pubsys2/xml/en/procedures/100/100-010-045.html)
Procedure Title	Turbocharger Oil Drain Line
Update Reason	

Date	03-Sep-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	100-013-001 (/qs3/pubsys2/xml/en/procedures/100/100-013-001.html)
Procedure Title	Alternator
Update Reason	
Date	03-Sep-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	100-013-017 (/qs3/pubsys2/xml/en/procedures/100/100-013-017.html)
Procedure Title	Starter Magnetic Switch
Update Reason	
Date	03-Sep-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	100-013-018 (/qs3/pubsys2/xml/en/procedures/100/100-013-018.html)
Procedure Title	Starter Switch
Update Reason	
Date	03-Sep-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	100-013-019 (/qs3/pubsys2/xml/en/procedures/100/100-013-019.html)
Procedure Title	Starter Solenoid
Update Reason	
Date	15-Sep-2003
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	100-007-025 (/qs3/pubsys2/xml/en/procedures/100/100-007-025.html)
Procedure Title	Lubricating Oil Pan
Update Reason	

Date	22-Sep-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-005 (/qs3/pubsys2/xml/en/procedures/100/100-001-005.html)
Procedure Title	Bearings, Connecting Rod
Update Reason	
Date	22-Sep-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-006 (/qs3/pubsys2/xml/en/procedures/100/100-001-006.html)
Procedure Title	Bearings, Main
Update Reason	
Date	22-Sep-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-013 (/qs3/pubsys2/xml/en/procedures/100/100-001-013.html)
Procedure Title	Camshaft Gear (Camshaft Removed)
Update Reason	
Date	22-Sep-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-047 (/qs3/pubsys2/xml/en/procedures/100/100-001-047.html)
Procedure Title	Piston Rings
Update Reason	
Date	22-Sep-2003
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	100-004-014 (/qs3/pubsys2/xml/en/procedures/100/100-004-014.html)
Procedure Title	Push Rods or Tubes
Update Reason	

Date	22-Sep-2003
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	100-004-015 (/qs3/pubsys2/xml/en/procedures/100/100-004-015.html)
Procedure Title	Tappet
Update Reason	
Date	20-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t008-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t008-tr.html)
Procedure Title	Air Compressor Will Not Maintain Adequate Air Pressure (Not Pumping Continuously)
Update Reason	
Date	20-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t050-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t050-tr.html)
Procedure Title	Engine Noise Excessive - Main Bearing
Update Reason	
Date	20-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t062-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t062-tr.html)
Procedure Title	Engine Runs Rough or Misfires
Update Reason	
Date	20-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t066-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t066-tr.html)
Procedure Title	Engine Speed Surges at Low or High Idle
Update Reason	

Date	20-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t081-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t081-tr.html)
Procedure Title	Engine Will Not Shut Off
Update Reason	
Date	20-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t091-5-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t091-5-tr.html)
Procedure Title	Fuel Knock
Update Reason	
Date	20-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t092-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t092-tr.html)
Procedure Title	Fuel in Lubricating Oil
Update Reason	
Date	20-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t097-25-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t097-25-tr.html)
Procedure Title	Intake Manifold Air Heater System Malfunctioning
Update Reason	
Date	20-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t106-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t106-tr.html)
Procedure Title	Lubricating Oil Sludge in the Crankcase Excessive
Update Reason	

Date	22-Jan-2004
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-012 (/qs3/pubsys2/xml/en/procedures/41/41-006-012.html)
Procedure Title	Fuel Drain Line Restriction
Update Reason	
Date	22-Jan-2004
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-013 (/qs3/pubsys2/xml/en/procedures/41/41-006-013.html)
Procedure Title	Fuel Drain Lines
Update Reason	
Date	29-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	99-008-067 (/qs3/pubsys2/xml/en/procedures/99/99-008-067.html)
Procedure Title	Sea Water Strainer
Update Reason	
Date	29-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	99-008-104 (/qs3/pubsys2/xml/en/procedures/99/99-008-104.html)
Procedure Title	Sea Water Hoses
Update Reason	
Date	09-Feb-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t080-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t080-tr.html)
Procedure Title	Engine Will Not Reach Rated Speed (RPM)
Update Reason	

Date	12-Feb-2004
Section	Section 11 - Exhaust System - Group 11
Procedure Number	41-011-009 (/qs3/pubsys2/xml/en/procedures/41/41-011-009.html)
Procedure Title	Exhaust Restriction
Update Reason	
Date	03-Mar-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t118-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t118-tr.html)
Procedure Title	Smoke, White-Excessive
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-010 (/qs3/pubsys2/xml/en/procedures/99/99-018-010.html)
Procedure Title	Fraction, Decimal, Millimeter Conversions
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-011 (/qs3/pubsys2/xml/en/procedures/99/99-018-011.html)
Procedure Title	Newton-Meter to Foot-Pound Conversions
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-012 (/qs3/pubsys2/xml/en/procedures/99/99-018-012.html)
Procedure Title	Pipe Plug Torque Values
Update Reason	

Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-013 (/qs3/pubsys2/xml/en/procedures/99/99-018-013.html)
Procedure Title	Tap-Drill Chart - U.S. Customary and Metric
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-014 (/qs3/pubsys2/xml/en/procedures/99/99-018-014.html)
Procedure Title	Weights and Measures - Conversion Factors
Update Reason	
Date	17-Mar-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t018-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t018-tr.html)
Procedure Title	Coolant Contamination
Update Reason	
Date	17-Mar-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t048-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t048-tr.html)
Procedure Title	Engine Noise Excessive - Combustion Knocks
Update Reason	
Date	19-May-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-031 (/qs3/pubsys2/xml/en/procedures/100/100-010-031.html)
Procedure Title	Air Intake Restriction
Update Reason	

Date	02-Jun-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t072-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t072-tr.html)
Procedure Title	Engine Starts But Will Not Keep Running
Update Reason	
Date	02-Jun-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t087-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t087-tr.html)
Procedure Title	Fuel Consumption Excessive
Update Reason	
Date	02-Jun-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t093-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t093-tr.html)
Procedure Title	Fuel or Lubricating Oil Leaking From Exhaust Manifold
Update Reason	
Date	25-Aug-2004
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	100-003-018 (/qs3/pubsys2/xml/en/procedures/100/100-003-018.html)
Procedure Title	Crankcase Breather Tube
Update Reason	
Date	08-Nov-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	41-007-039 (/qs3/pubsys2/xml/en/procedures/41/41-007-039.html)
Procedure Title	Lubricating Oil Thermostat
Update Reason	

Date	08-Nov-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	41-008-023 (/qs3/pubsys2/xml/en/procedures/41/41-008-023.html)
Procedure Title	Engine Coolant Heater
Update Reason	
Date	08-Nov-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	41-008-057 (/qs3/pubsys2/xml/en/procedures/41/41-008-057.html)
Procedure Title	Sea Water Pump
Update Reason	
Date	15-Nov-2004
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	100-003-011 (/qs3/pubsys2/xml/en/procedures/100/100-003-011.html)
Procedure Title	Rocker Lever Cover
Update Reason	
Date	15-Nov-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	100-007-031 (/qs3/pubsys2/xml/en/procedures/100/100-007-031.html)
Procedure Title	Lubricating Oil Pump
Update Reason	
Date	22-Nov-2004
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	100-017-002 (/qs3/pubsys2/xml/en/procedures/100/100-017-002.html)
Procedure Title	Cup Plug
Update Reason	

Date	29-Nov-2004
Section	Section 0 - Complete Engine - Group 00
Procedure Number	41-022-001_00 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_00.html)
Procedure Title	Service Tools
Update Reason	
Date	29-Nov-2004
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-022-001_02 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_02.html)
Procedure Title	Service Tools
Update Reason	
Date	29-Nov-2004
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	41-022-001_03 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_03.html)
Procedure Title	Service Tools
Update Reason	
Date	29-Nov-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	41-022-001_07 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_07.html)
Procedure Title	Service Tools
Update Reason	
Date	29-Nov-2004
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	41-022-001_13 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_13.html)
Procedure Title	Service Tools
Update Reason	

Date	29-Nov-2004
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	41-022-001_16 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_16.html)
Procedure Title	Service Tools
Update Reason	
Date	29-Nov-2004
Section	back
Procedure Number	3666003-backcover (/qs3/pubsys2/xml/en/manual/3666003/3666003-backcover.html)
Procedure Title	Backcover
Update Reason	
Date	07-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t013-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t013-tr.html)
Procedure Title	Alternator Not Charging or Insufficient Charging
Update Reason	
Date	07-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t014-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t014-tr.html)
Procedure Title	Alternator Overcharging
Update Reason	
Date	07-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t022-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t022-tr.html)
Procedure Title	Coolant Temperature Above Normal - Gradual Overheat
Update Reason	

Date	07-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t023-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t023-tr.html)
Procedure Title	Coolant Temperature is Above Normal - Sudden Overheat
Update Reason	
Date	07-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t024-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t024-tr.html)
Procedure Title	Coolant Temperature is Below Normal
Update Reason	
Date	07-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t026-156-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t026-156-tr.html)
Procedure Title	Coolant Temperature Above Normal - Sea Water Coolant System
Update Reason	
Date	07-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t043-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t043-tr.html)
Procedure Title	Engine Difficult to Start or Will Not Start (Exhaust Smoke)
Update Reason	

Date	07-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	41-t00-004 (/qs3/pubsys2/xml/en/procedures/41/41-t00-004.html)
Procedure Title	Troubleshooting Overview
Update Reason	
Date	07-Dec-2004
Section	Section 0 - Complete Engine - Group 00
Procedure Number	41-000-001 (/qs3/pubsys2/xml/en/procedures/41/41-000-001.html)
Procedure Title	Engine Removal
Update Reason	
Date	07-Dec-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-016 (/qs3/pubsys2/xml/en/procedures/41/41-001-016.html)
Procedure Title	Crankshaft
Update Reason	
Date	07-Dec-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-018 (/qs3/pubsys2/xml/en/procedures/100/100-001-018.html)
Procedure Title	Crankshaft Gear, Front (Crankshaft Installed)
Update Reason	
Date	07-Dec-2004
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-002-019 (/qs3/pubsys2/xml/en/procedures/41/41-002-019.html)
Procedure Title	Valve Seat Insert, Cylinder Head
Update Reason	

Date	07-Dec-2004
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-002-020 (/qs3/pubsys2/xml/en/procedures/41/41-002-020.html)
Procedure Title	Valve, Cylinder Head
Update Reason	
Date	07-Dec-2004
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-002-021 (/qs3/pubsys2/xml/en/procedures/41/41-002-021.html)
Procedure Title	Cylinder Head Gasket
Update Reason	
Date	07-Dec-2004
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-005-018 (/qs3/pubsys2/xml/en/procedures/41/41-005-018.html)
Procedure Title	Fuel Pump Control Lever and Spring
Update Reason	
Date	07-Dec-2004
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-026 (/qs3/pubsys2/xml/en/procedures/41/41-006-026.html)
Procedure Title	Injector
Update Reason	
Date	07-Dec-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	41-008-014 (/qs3/pubsys2/xml/en/procedures/41/41-008-014.html)
Procedure Title	Coolant Thermostat Housing
Update Reason	

Date	07-Dec-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	41-008-030 (/qs3/pubsys2/xml/en/procedures/41/41-008-030.html)
Procedure Title	Fan Drive Idler Pulley Assembly
Update Reason	
Date	07-Dec-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-047 (/qs3/pubsys2/xml/en/procedures/100/100-008-047.html)
Procedure Title	Radiator Pressure Cap
Update Reason	
Date	07-Dec-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-010-002 (/qs3/pubsys2/xml/en/procedures/41/41-010-002.html)
Procedure Title	Aftercooler Assembly
Update Reason	
Date	07-Dec-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-010-023 (/qs3/pubsys2/xml/en/procedures/41/41-010-023.html)
Procedure Title	Air Intake Manifold
Update Reason	
Date	07-Dec-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-010-033-tr (/qs3/pubsys2/xml/en/procedures/41/41-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	

Date	07-Dec-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-010-038 (/qs3/pubsys2/xml/en/procedures/41/41-010-038.html)
Procedure Title	Turbocharger Axial Clearance
Update Reason	

Date	07-Dec-2004
Section	Section 11 - Exhaust System - Group 11
Procedure Number	41-011-007-tr (/qs3/pubsys2/xml/en/procedures/41/41-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	

Date	07-Dec-2004
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	41-012-003 (/qs3/pubsys2/xml/en/procedures/41/41-012-003.html)
Procedure Title	Air Compressor Carbon Buildup
Update Reason	

Date	07-Dec-2004
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	41-012-018 (/qs3/pubsys2/xml/en/procedures/41/41-012-018.html)
Procedure Title	Air Governor (Air Compressor Pumps Continuously)
Update Reason	

Date	07-Dec-2004
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	41-013-023 (/qs3/pubsys2/xml/en/procedures/41/41-013-023.html)
Procedure Title	Charging System Indicator
Update Reason	
Date	07-Dec-2004
Section	Section 14 - Engine Testing - Group 14
Procedure Number	41-014-003 (/qs3/pubsys2/xml/en/procedures/41/41-014-003.html)
Procedure Title	Engine Run-in (Chassis Dynamometer)
Update Reason	
Date	07-Dec-2004
Section	Section 14 - Engine Testing - Group 14
Procedure Number	41-014-004 (/qs3/pubsys2/xml/en/procedures/41/41-014-004.html)
Procedure Title	Engine Run-in (Without Dynamometer)
Update Reason	
Date	07-Dec-2004
Section	Section 14 - Engine Testing - Group 14
Procedure Number	41-014-006 (/qs3/pubsys2/xml/en/procedures/41/41-014-006.html)
Procedure Title	Engine Run-in (Engine Dynamometer)
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t004-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t004-tr.html)
Procedure Title	Air Compressor Air Pressure Rises Slowly
Update Reason	

Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t005-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t005-tr.html)
Procedure Title	Air Compressor Cycles Frequently
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t006-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t006-tr.html)
Procedure Title	Air Compressor Noise is Excessive
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t007-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t007-tr.html)
Procedure Title	Air Compressor Pumping Excess Lubricating Oil into the Air System
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t009-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t009-tr.html)
Procedure Title	Air Compressor Will Not Pump Air
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t010-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t010-tr.html)
Procedure Title	Air Compressor Will Not Stop Pumping
Update Reason	

Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t019-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t019-tr.html)
Procedure Title	Coolant Loss
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t025-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t025-tr.html)
Procedure Title	Coolant in the Lubricating Oil
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t027-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t027-tr.html)
Procedure Title	Crankcase Gases (Blowby) Excessive
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t033-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t033-tr.html)
Procedure Title	Engine Acceleration or Response Poor
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t047-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t047-tr.html)
Procedure Title	Engine Noise Excessive
Update Reason	

Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t049-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t049-tr.html)
Procedure Title	Engine Noise Excessive - Connecting Rod
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t051-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t051-tr.html)
Procedure Title	Engine Noise Excessive - Piston
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t052-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t052-tr.html)
Procedure Title	Engine Noise Excessive - Turbocharger
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t057-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t057-tr.html)
Procedure Title	Engine Power Output Low
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t061-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t061-tr.html)
Procedure Title	Engine Runs Rough at Idle
Update Reason	

Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t075-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t075-tr.html)
Procedure Title	Engine Vibration Excessive
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t076-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t076-tr.html)
Procedure Title	Engine Will Not Crank or Cranks Slowly
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t081-001-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t081-001-tr.html)
Procedure Title	Excessive Noise
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t096-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t096-tr.html)
Procedure Title	Intake Manifold Air Temperature Above Specification
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t102-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t102-tr.html)
Procedure Title	Lubricating Oil Consumption Excessive
Update Reason	

Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t107-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t107-tr.html)
Procedure Title	Lubricating Oil Temperature Above Specification
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t108-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t108-tr.html)
Procedure Title	Lubricating or Transmission Oil in the Coolant
Update Reason	
Date	08-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t116-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t116-tr.html)
Procedure Title	Smoke, Black-Excessive
Update Reason	
Date	08-Dec-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-028 (/qs3/pubsys2/xml/en/procedures/100/100-001-028.html)
Procedure Title	Cylinder Liner
Update Reason	
Date	08-Dec-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-043 (/qs3/pubsys2/xml/en/procedures/100/100-001-043.html)
Procedure Title	Piston
Update Reason	

Date	08-Dec-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	41-008-103 (/qs3/pubsys2/xml/en/procedures/41/41-008-103.html)
Procedure Title	Sea Water System Diagnostics
Update Reason	
Date	08-Dec-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-010-024 (/qs3/pubsys2/xml/en/procedures/41/41-010-024.html)
Procedure Title	Air Leaks, Air Intake and Exhaust Systems
Update Reason	
Date	08-Dec-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-010-047 (/qs3/pubsys2/xml/en/procedures/41/41-010-047.html)
Procedure Title	Turbocharger Radial Bearing Clearance
Update Reason	
Date	13-Dec-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t044-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t044-tr.html)
Procedure Title	Engine Difficult to Start or Will Not Start (No Exhaust Smoke)
Update Reason	
Date	13-Dec-2004
Section	Section 0 - Complete Engine - Group 00
Procedure Number	41-000-002 (/qs3/pubsys2/xml/en/procedures/41/41-000-002.html)
Procedure Title	Engine Installation
Update Reason	

Date	22-Dec-2004
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	41-012-019 (/qs3/pubsys2/xml/en/procedures/41/41-012-019.html)
Procedure Title	Air Leaks, Compressed Air System
Update Reason	
Date	07-Jan-2005
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	41-012-017 (/qs3/pubsys2/xml/en/procedures/41/41-012-017.html)
Procedure Title	Air Governor (Air Compressor Will Not Pump)
Update Reason	
Date	26-Jan-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	100-007-035 (/qs3/pubsys2/xml/en/procedures/100/100-007-035.html)
Procedure Title	Lubricating Oil Suction Tube (Block-Mounted)
Update Reason	
Date	09-Mar-2005
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-015-tr (/qs3/pubsys2/xml/en/procedures/41/41-006-015-tr.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	
Date	28-Apr-2005
Section	Section F - Familiarization
Procedure Number	41-200-001-tr (/qs3/pubsys2/xml/en/procedures/41/41-200-001-tr.html)
Procedure Title	Flow Diagram, Fuel System
Update Reason	

Date	28-Apr-2005
Section	Section F - Familiarization
Procedure Number	41-200-002-tr (/qs3/pubsys2/xml/en/procedures/41/41-200-002-tr.html)
Procedure Title	Flow Diagram, Lubricating Oil System
Update Reason	
Date	28-Apr-2005
Section	Section F - Familiarization
Procedure Number	41-200-003-tr (/qs3/pubsys2/xml/en/procedures/41/41-200-003-tr.html)
Procedure Title	Flow Diagram, Cooling System
Update Reason	
Date	02-May-2005
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-002-004-tr (/qs3/pubsys2/xml/en/procedures/41/41-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	
Date	07-Jun-2005
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	100-016-005 (/qs3/pubsys2/xml/en/procedures/100/100-016-005.html)
Procedure Title	Flywheel
Update Reason	
Date	07-Jun-2005
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	100-016-008 (/qs3/pubsys2/xml/en/procedures/100/100-016-008.html)
Procedure Title	Flywheel Ring Gear
Update Reason	

Date	13-Jun-2005
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	41-003-004 (/qs3/pubsys2/xml/en/procedures/41/41-003-004.html)
Procedure Title	Overhead Set
Update Reason	
Date	13-Jun-2005
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	100-013-020 (/qs3/pubsys2/xml/en/procedures/100/100-013-020.html)
Procedure Title	Starting Motor
Update Reason	
Date	15-Jun-2005
Section	Section F - Familiarization
Procedure Number	41-200-005-tr (/qs3/pubsys2/xml/en/procedures/41/41-200-005-tr.html)
Procedure Title	Flow Diagram, Exhaust System
Update Reason	
Date	20-Jun-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	100-007-003 (/qs3/pubsys2/xml/en/procedures/100/100-007-003.html)
Procedure Title	Lubricating Oil Cooler
Update Reason	
Date	30-Jun-2005
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-027-tr (/qs3/pubsys2/xml/en/procedures/100/100-010-027-tr.html)
Procedure Title	Charge-Air Cooler
Update Reason	

Date	07-Jul-2005
Section	Section E - Engine Identification
Procedure Number	41-100-001-tr (/qs3/pubsys2/xml/en/procedures/41/41-100-001-tr.html)
Procedure Title	Engine Identification
Update Reason	
Date	11-Jul-2005
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-022-001_05 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_05.html)
Procedure Title	Service Tools
Update Reason	
Date	08-Aug-2005
Section	Section F - Familiarization
Procedure Number	41-200-004-tr (/qs3/pubsys2/xml/en/procedures/41/41-200-004-tr.html)
Procedure Title	Flow Diagram, Air Intake System
Update Reason	
Date	03-Jan-2006
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	00-016-025 (/qs3/pubsys2/xml/en/procedures/00/00-016-025.html)
Procedure Title	Propeller Shaft
Update Reason	
Date	02-Feb-2006
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	00-016-026 (/qs3/pubsys2/xml/en/procedures/00/00-016-026.html)
Procedure Title	Marine Vibration Isolator
Update Reason	

Date	22-May-2006
Section	front
Procedure Number	tr-frwd (/qs3/pubsys2/xml/en/manual/preface/tr-frwd.html)
Procedure Title	Foreword
Update Reason	
Date	27-Jun-2006
Section	Section L - Service Literature
Procedure Number	99-205-002 (/qs3/pubsys2/xml/en/procedures/99/99-205-002.html)
Procedure Title	Service Literature Ordering Location
Update Reason	
Date	06-Jul-2006
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	100-012-014-tr (/qs3/pubsys2/xml/en/procedures/100/100-012-014-tr.html)
Procedure Title	Air Compressor
Update Reason	
Date	31-Aug-2006
Section	Section F - Familiarization
Procedure Number	41-005-999 (/qs3/pubsys2/xml/en/procedures/41/41-005-999.html)
Procedure Title	Fuel System - Overview
Update Reason	
Date	23-Oct-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	100-007-029 (/qs3/pubsys2/xml/en/procedures/100/100-007-029.html)
Procedure Title	Lubricating Oil Pressure Regulator (Main Rifle)
Update Reason	

Date	26-Oct-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-002 (/qs3/pubsys2/xml/en/procedures/100/100-008-002.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	
Date	17-Jan-2007
Section	Section L - Service Literature
Procedure Number	41-205-001-tr (/qs3/pubsys2/xml/en/procedures/41/41-205-001-tr.html)
Procedure Title	Additional Service Literature
Update Reason	
Date	17-Apr-2007
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	100-003-008 (/qs3/pubsys2/xml/en/procedures/100/100-003-008.html)
Procedure Title	Rocker Lever
Update Reason	
Date	01-May-2007
Section	Section E - Engine Identification
Procedure Number	41-100-002-tr (/qs3/pubsys2/xml/en/procedures/41/41-100-002-tr.html)
Procedure Title	Engine Diagrams
Update Reason	
Date	03-May-2007
Section	Section 21 - Main Power Generator - Group 21
Procedure Number	41-021-009 (/qs3/pubsys2/xml/en/procedures/41/41-021-009.html)
Procedure Title	Generator, Main
Update Reason	

Date	04-May-2007
Section	Section V - Specifications
Procedure Number	41-018-016-tr (/qs3/pubsys2/xml/en/procedures/41/41-018-016-tr.html)
Procedure Title	Fuel System
Update Reason	
Date	04-May-2007
Section	Section V - Specifications
Procedure Number	41-018-019-tr (/qs3/pubsys2/xml/en/procedures/41/41-018-019-tr.html)
Procedure Title	Air Intake System
Update Reason	
Date	04-May-2007
Section	Section V - Specifications
Procedure Number	41-018-020-tr (/qs3/pubsys2/xml/en/procedures/41/41-018-020-tr.html)
Procedure Title	Exhaust System
Update Reason	
Date	04-May-2007
Section	Section V - Specifications
Procedure Number	41-018-022 (/qs3/pubsys2/xml/en/procedures/41/41-018-022.html)
Procedure Title	Compressed Air System
Update Reason	
Date	04-May-2007
Section	Section V - Specifications
Procedure Number	41-018-023 (/qs3/pubsys2/xml/en/procedures/41/41-018-023.html)
Procedure Title	Engine Testing
Update Reason	

Date	08-May-2007
Section	Section V - Specifications
Procedure Number	41-018-017-tr (/qs3/pubsys2/xml/en/procedures/41/41-018-017-tr.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	08-May-2007
Section	Section V - Specifications
Procedure Number	41-018-018-tr (/qs3/pubsys2/xml/en/procedures/41/41-018-018-tr.html)
Procedure Title	Cooling System
Update Reason	
Date	09-May-2007
Section	Section V - Specifications
Procedure Number	41-018-015-tr (/qs3/pubsys2/xml/en/procedures/41/41-018-015-tr.html)
Procedure Title	General Engine
Update Reason	
Date	24-May-2007
Section	Section V - Specifications
Procedure Number	41-018-021-tr (/qs3/pubsys2/xml/en/procedures/41/41-018-021-tr.html)
Procedure Title	Electrical System
Update Reason	
Date	08-Jun-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t104-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t104-tr.html)
Procedure Title	Lubricating Oil Pressure High
Update Reason	

Date	06-Jul-2007
Section	Section F - Familiarization
Procedure Number	41-200-006-tr (/qs3/pubsys2/xml/en/procedures/41/41-200-006-tr.html)
Procedure Title	Flow Diagram, Compressed Air System
Update Reason	
Date	23-Jul-2007
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-014 (/qs3/pubsys2/xml/en/procedures/100/100-001-014.html)
Procedure Title	Connecting Rod
Update Reason	
Date	23-Jul-2007
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	100-007-009 (/qs3/pubsys2/xml/en/procedures/100/100-007-009.html)
Procedure Title	Lubricating Oil Dipstick
Update Reason	
Date	23-Jul-2007
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-038 (/qs3/pubsys2/xml/en/procedures/100/100-008-038.html)
Procedure Title	Fan Shroud Assembly
Update Reason	
Date	23-Jul-2007
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-062-tr (/qs3/pubsys2/xml/en/procedures/100/100-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	

Date	24-Jul-2007
Section	Section i - Introduction
Procedure Number	99-204-008 (/qs3/pubsys2/xml/en/procedures/99/99-204-008.html)
Procedure Title	General Cleaning Instructions
Update Reason	
Date	27-Jul-2007
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	100-013-006 (/qs3/pubsys2/xml/en/procedures/100/100-013-006.html)
Procedure Title	Alternator Pulley
Update Reason	
Date	31-Aug-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t105-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t105-tr.html)
Procedure Title	Lubricating Oil Pressure Low
Update Reason	
Date	04-Sep-2007
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-010-057 (/qs3/pubsys2/xml/en/procedures/41/41-010-057.html)
Procedure Title	Intake Manifold Pressure
Update Reason	
Date	05-Sep-2007
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-023-tr (/qs3/pubsys2/xml/en/procedures/100/100-001-023-tr.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	

Date	30-Oct-2007
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-033 (/qs3/pubsys2/xml/en/procedures/41/41-001-033.html)
Procedure Title	Gear Housing, Front
Update Reason	
Date	30-Oct-2007
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-049 (/qs3/pubsys2/xml/en/procedures/41/41-001-049.html)
Procedure Title	Timing Pin Housing
Update Reason	
Date	04-Apr-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-067-tr (/qs3/pubsys2/xml/en/procedures/100/100-001-067-tr.html)
Procedure Title	Crankshaft Wear Sleeve, Rear
Update Reason	
Date	29-Apr-2008
Section	Section 8 - Cooling System - Group 08
Procedure Number	41-008-036 (/qs3/pubsys2/xml/en/procedures/41/41-008-036.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	
Date	13-May-2008
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-002-022 (/qs3/pubsys2/xml/en/procedures/41/41-002-022.html)
Procedure Title	Injector Protrusion
Update Reason	

Date	24-Jul-2008
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-018-tr (/qs3/pubsys2/xml/en/procedures/100/100-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	
Date	05-Aug-2008
Section	Section 10 - Air Intake System - Group 10
Procedure Number	100-010-046 (/qs3/pubsys2/xml/en/procedures/100/100-010-046.html)
Procedure Title	Turbocharger Oil Supply Line
Update Reason	
Date	28-Aug-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-022-001_01 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_01.html)
Procedure Title	Service Tools
Update Reason	
Date	17-Sep-2008
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-002-017 (/qs3/pubsys2/xml/en/procedures/41/41-002-017.html)
Procedure Title	Valve Guide, Cylinder Head
Update Reason	
Date	19-May-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	41-007-024 (/qs3/pubsys2/xml/en/procedures/41/41-007-024.html)
Procedure Title	Lubricating Oil Leaks
Update Reason	

Date	09-Jun-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	41-007-013-tr (/qs3/pubsys2/xml/en/procedures/41/41-007-013-tr.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	
Date	24-Jun-2009
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	100-017-011 (/qs3/pubsys2/xml/en/procedures/100/100-017-011.html)
Procedure Title	Straight Thread Plug
Update Reason	
Date	25-Jun-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-001-tr (/qs3/pubsys2/xml/en/procedures/99/99-t00-001-tr.html)
Procedure Title	Troubleshooting Procedures and Techniques
Update Reason	
Date	26-Jun-2009
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	100-016-007 (/qs3/pubsys2/xml/en/procedures/100/100-016-007.html)
Procedure Title	Flywheel Housing, REPTO
Update Reason	
Date	08-Jul-2009
Section	Section 14 - Engine Testing - Group 14
Procedure Number	100-014-002 (/qs3/pubsys2/xml/en/procedures/100/100-014-002.html)
Procedure Title	Engine Testing (Chassis Dynamometer)
Update Reason	

Date	22-Jul-2009
Section	Section L - Service Literature
Procedure Number	99-205-004 (/qs3/pubsys2/xml/en/procedures/99/99-205-004.html)
Procedure Title	Cummins Customized Parts Catalog
Update Reason	
Date	20-Aug-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-008 (/qs3/pubsys2/xml/en/procedures/41/41-001-008.html)
Procedure Title	Camshaft
Update Reason	
Date	10-Sep-2009
Section	Section i - Introduction
Procedure Number	99-204-002-tr (/qs3/pubsys2/xml/en/procedures/99/99-204-002-tr.html)
Procedure Title	About the Manual
Update Reason	
Date	08-Oct-2009
Section	Section i - Introduction
Procedure Number	99-204-007-tr (/qs3/pubsys2/xml/en/procedures/99/99-204-007-tr.html)
Procedure Title	General Repair Instructions
Update Reason	
Date	15-Oct-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	99-008-045 (/qs3/pubsys2/xml/en/procedures/99/99-008-045.html)
Procedure Title	Radiator Hoses
Update Reason	

Date	23-Nov-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-054 (/qs3/pubsys2/xml/en/procedures/41/41-001-054.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	
Date	03-Dec-2009
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-005-012 (/qs3/pubsys2/xml/en/procedures/41/41-005-012.html)
Procedure Title	Fuel Injection Pumps, In-Line
Update Reason	
Date	25-Jan-2010
Section	Section i - Introduction
Procedure Number	99-204-006-tr (/qs3/pubsys2/xml/en/procedures/99/99-204-006-tr.html)
Procedure Title	General Safety Instructions
Update Reason	
Date	25-Jan-2010
Section	Section V - Specifications
Procedure Number	99-018-005 (/qs3/pubsys2/xml/en/procedures/99/99-018-005.html)
Procedure Title	Drive Belt Tension
Update Reason	
Date	25-Jan-2010
Section	Section V - Specifications
Procedure Number	99-018-009 (/qs3/pubsys2/xml/en/procedures/99/99-018-009.html)
Procedure Title	Capscrew Markings and Torque Values
Update Reason	

Date	01-Mar-2010
Section	Section 14 - Engine Testing - Group 14
Procedure Number	100-014-010 (/qs3/pubsys2/xml/en/procedures/100/100-014-010.html)
Procedure Title	Crankcase Blowby, Measure
Update Reason	
Date	17-Mar-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-031-tr (/qs3/pubsys2/xml/en/procedures/100/100-001-031-tr.html)
Procedure Title	Gear Cover, Front
Update Reason	
Date	24-Mar-2010
Section	Section i - Introduction
Procedure Number	99-204-009 (/qs3/pubsys2/xml/en/procedures/99/99-204-009.html)
Procedure Title	Acronyms and Abbreviations
Update Reason	
Date	06-Apr-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-010 (/qs3/pubsys2/xml/en/procedures/41/41-001-010.html)
Procedure Title	Camshaft Bushings
Update Reason	
Date	25-May-2010
Section	Section i - Introduction
Procedure Number	99-204-003-tr (/qs3/pubsys2/xml/en/procedures/99/99-204-003-tr.html)
Procedure Title	How to Use the Manual
Update Reason	

Date	25-May-2010
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-019-tr (/qs3/pubsys2/xml/en/procedures/100/100-008-019-tr.html)
Procedure Title	Cooling System - Air or Combustion Gas Test
Update Reason	
Date	27-May-2010
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-006 (/qs3/pubsys2/xml/en/procedures/100/100-008-006.html)
Procedure Title	Coolant Filter
Update Reason	
Date	19-Nov-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-054 (/qs3/pubsys2/xml/en/procedures/41/41-001-054.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Revised torque specification for nut and stud used for horizontal split connecting rods only.
Date	18-Mar-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-028 (/qs3/pubsys2/xml/en/procedures/100/100-001-028.html)
Procedure Title	Cylinder Liner
Update Reason	Modification to liner protrusion specification.

Date	9-May-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-043 (/qs3/pubsys2/xml/en/procedures/100/100-001-043.html)
Procedure Title	Piston
Update Reason	Revised procedure to contain the piston ring groove measurement limits for the intermediate ring.

Date	07-Jun-2011
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t027-tr (/qs3/pubsys2/xml/en/manual/3666003/3666003-t027-tr.html)
Procedure Title	Crankcase Gases (Blowby) Excessive
Update Reason	Corrected links within the tree for turbocharger and air compressor isolation during troubleshooting.

Date	11-Jan-2012
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-002-004-tr (/qs3/pubsys2/xml/en/procedures/41/41-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Updated the Clean and Inspect for Reuse section for combustion seal ring.

Date	27-Apr-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-051-tr (/qs3/pubsys2/xml/en/procedures/41/41-001-051-tr.html)
Procedure Title	Vibration Damper, Rubber
Update Reason	Added procedure to outline.

Date	27-Apr-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-052-tr (/qs3/pubsys2/xml/en/procedures/41/41-001-052-tr.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	Added procedure to outline.
Date	14-Jun-2012
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	41-007-003-tr (/qs3/pubsys2/xml/en/procedures/41/41-007-003-tr.html)
Procedure Title	Lubricating Oil Cooler
Update Reason	Added instructions to address debris in the oil cooler.
Date	28-Sep-2012
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	00-016-026-tr (/qs3/pubsys2/xml/en/procedures/00/00-016-026-tr.html)
Procedure Title	Marine Vibration Isolator
Update Reason	Procedure was revised to include information specific to the new isolator design introduced with the marine engine and to align with the most recent installation angularity requirements in the Marine Installation Directions.
Date	10-Oct-2012
Section	Section F - Familiarization
Procedure Number	41-200-002-tr (/qs3/pubsys2/xml/en/procedures/41/41-200-002-tr.html)
Procedure Title	Flow Diagram, Lubricating Oil System
Update Reason	Removed ISC engine content and organized the procedure.

Date	11-Jan-2013
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666003-t104 (/qs3/pubsys2/xml/en/manual/3666003/3666003-t104.html)
Procedure Title	Lubricating Oil Pressure High
Update Reason	Changed correction from Check to Replace the main oil pressure regulator assembly.
Date	18-Mar-2013
Section	Section 14 - Engine Testing
Procedure Number	100-014-010 (/qs3/pubsys2/xml/en/procedures/100/100-014-010.html)
Procedure Title	Crankcase Blowby, Measure
Update Reason	Revised MidRange Blowby Specifications Chart to include B6.7s
Date	07-Aug-2013
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-002-004-tr (/qs3/pubsys2/xml/en/procedures/41/41-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Removal of installation instructions of rocker levers prior to tightening the head bolts.
Date	12-Sep-2013
Section	Section 7 - Lubricating Oil System
Procedure Number	41-007-003-tr (/qs3/pubsys2/xml/en/procedures/41/41-007-003-tr.html)
Procedure Title	Lubricating Oil Cooler
Update Reason	Updated procedure to discard old gasket and install new gasket when lubricating oil cooler is removed.

Date	04-Dec-2013
Section	Section 7 - Lubricating Oil System
Procedure Number	100-007-025 (/qs3/pubsys2/xml/en/procedures/100/100-007-025.html)
Procedure Title	Lubricating Oil Pan
Update Reason	Changed lubricating oil pan capscrew torque to 28 n.m [248 in-lb].
Date	28-Jan-2014
Section	Section 14 - Engine Testing
Procedure Number	100-014-010 (/qs3/pubsys2/xml/en/procedures/100/100-014-010.html)
Procedure Title	Crankcase Blowby, Measure
Update Reason	Revised Blowby Specification for New or Rebuild for C8.3 to 101.6 mm [4 H20] and Blowby Specification for Troubleshooting to 254 mm [10 h20].
Date	26-Aug-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-019 (/qs3/pubsys2/xml/en/procedures/41/41-001-019.html)
Procedure Title	Crankshaft Gear, Front (Crankshaft Removed)
Update Reason	This procedure was added to the manual and replaces procedure 001-018 (Crankshaft Gear, Front (Crankshaft Installed)).
Date	09-Sep-2014
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	100-013-006 (/qs3/pubsys2/xml/en/procedures/100/100-013-006.html)
Procedure Title	Alternator Pulley
Update Reason	The Install step is revised to include torque values for the alternator pulley mounting fastener for all available alternator suppliers.

Date	13-Mar-2015
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	41-002-016 (/qs3/pubsys2/xml/en/procedures/41/41-002-016.html)
Procedure Title	Valve Guide Seal, Cylinder Head
Update Reason	Clarify that valve guide seals can be serviced without removing the cylinder head.
Date	08-Apr-2015
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-018-tr (/qs3/pubsys2/xml/en/procedures/100/100-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	Added directions to allow the engine to cool before draining coolant.
Date	05-Apr-2016
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-005-043 (/qs3/pubsys2/xml/en/procedures/41/41-005-043.html)
Procedure Title	Fuel Shutoff Valve
Update Reason	Resistance values and instructions were added to the procedure.
Date	09-May-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-024 (/qs3/pubsys2/xml/en/procedures/100/100-001-024.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	Removed from outline.

Date	09-May-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-024 (/qs3/pubsys2/xml/en/procedures/41/41-001-024.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	Added to outline.
Date	24-Jul-2016
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-003 (/qs3/pubsys2/xml/en/procedures/41/41-006-003.html)
Procedure Title	Air in Fuel
Update Reason	Added new step in the Vent Step.
Date	29-Jul-2016
Section	Section 5 - Fuel System - Group 05
Procedure Number	41-005-043 (/qs3/pubsys2/xml/en/procedures/41/41-005-043.html)
Procedure Title	Fuel Shutoff Valve
Update Reason	Added the Generator Set applications to the procedure.
Date	28-Mar-2017
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-010-033-tr (/qs3/pubsys2/xml/en/procedures/41/41-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Radial Play measurement for Compressor wheel and Impeller has been replaced to remove incorrect diagnostic.

Date	28-Mar-2017
Section	Section 10 - Air Intake System - Group 10
Procedure Number	41-010-038 (/qs3/pubsys2/xml/en/procedures/41/41-010-038.html)
Procedure Title	Turbocharger Axial Clearance
Update Reason	Corrected Radial to Axial in table.
Date	02-June-2017
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-013 (/qs3/pubsys2/xml/en/procedures/41/41-006-013.html)
Procedure Title	Fuel Drain Lines
Update Reason	Update manual due to DCEC C series engines adding fuel pressure relief valve.
Date	02-June-2017
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	41-006-061 (/qs3/pubsys2/xml/en/procedures/41/41-006-061.html)
Procedure Title	Fuel Pressure Relief Valve
Update Reason	Update manual due to DCEC C series engines adding fuel pressure relief valve. Added this new procedure.
Date	02-Oct-2017
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-008 (/qs3/pubsys2/xml/en/procedures/41/41-001-008.html)
Procedure Title	Camshaft
Update Reason	Added Part Number 3934168 to Measure step.

Date	09-Oct-2017
Section	Section 14 - Engine Testing - Group 14
Procedure Number	100-014-010 (/qs3/pubsys2/xml/en/procedures/100/100-014-010.html)
Procedure Title	Crankcase Blowby, Measure
Update Reason	Added ISB6.7 CM2250 engine instructions for installing the blowby kit.
Date	03-Apr-2018
Section	Section 11 - Exhaust System - Group 11
Procedure Number	41-011-008 (/qs3/pubsys2/xml/en/procedures/41/41-011-008.html)
Procedure Title	Exhaust Manifold, Wet
Update Reason	Added to manual.
Date	27-Aug-2018
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-022-001_01 (/qs3/pubsys2/xml/en/procedures/41/41-022-001_01.html)
Procedure Title	Service Tools
Update Reason	Added new tools for removing and installing rear crankshaft seal.
Date	27-Aug-2018
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-024 (/qs3/pubsys2/xml/en/procedures/100/100-001-024.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	Replaced existing procedure with new procedure using new service tool kit.

Date	27-Aug-2018
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-104 (/qs3/pubsys2/xml/en/procedures/100/100-001-104.html)
Procedure Title	Crankshaft Seal Carrier, Rear
Update Reason	New procedure added to manual.
Date	15-Jan-2019
Section	Section 8 - Cooling System - Group 08
Procedure Number	100-008-018-tr (/qs3/pubsys2/xml/en/procedures/100/100-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	Updated the Coolant Replacer Method step.
Date	14-Feb-2019
Section	Section 1 - Cylinder Block
Procedure Number	41-001-028 (/qs3/pubsys2/xml/en/procedures/41/41-001-028.html)
Procedure Title	Cylinder Liner
Update Reason	Added direction to Procedure 001-026 for inspection, reuse, and repair guidelines.
Date	22-Mar-2019
Section	Section 1 - Cylinder Block
Procedure Number	100-001-058 (/qs3/pubsys2/xml/en/procedures/100/100-001-058.html)
Procedure Title	Cylinder Block Counterbore
Update Reason	Added to the outline.
Date	02-Mar-2020
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	41-007-003-tr (/qs3/pubsys2/xml/en/procedures/41/41-007-003-tr.html)
Procedure Title	Lubricating Oil Cooler
Update Reason	Consolidated torque values to reflect current practices.

Date	03-Mar-2020
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	41-001-051-tr (/qs3/pubsys2/xml/en/procedures/41/41-001-051-tr.html)
Procedure Title	Vibration Damper, Rubber
Update Reason	Rewrote the whole procedure to ensure the correct engine model and damper type was being shown.

Date	17-Sep-2020
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-058 (/qs3/pubsys2/xml/en/procedures/100/100-001-058.html)
Procedure Title	Cylinder Block Counterbore
Update Reason	Removed unnecessary items from Select Service Tools list and noted which Shims are available for C/L series engines to utilize. Added note that indicates different Cylinder Block Counterbore Cutting Kit exists for C and L series engines which is not compatible with X series engines.

Date	22-Jan-2021
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	100-001-058 (/qs3/pubsys2/xml/en/procedures/100/100-001-058.html)
Procedure Title	Cylinder Block Counterbore
Update Reason	Corrected shim thickness (in) specification listed for Part Number 3924449 to 0.0394.

Last Modified: 25-Jan-2021
