

Manual Change History (4021592) QSK19, QSK19 CM850 MCRS, and QSK19 CM2150 MCRS Service Manual

Date	Not Available
Section	front
Procedure Number	4021592-toc (/qs3/pubsys2/xml/en/manual/4021592/4021592-toc.html)
Procedure Title	Table of Contents
Update Reason	
Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-004 (/qs3/pubsys2/xml/en/procedures/99/99-204-004.html)
Procedure Title	Symbols
Update Reason	
Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-005 (/qs3/pubsys2/xml/en/procedures/99/99-204-005.html)
Procedure Title	Illustrations
Update Reason	
Date	03-Apr-2002
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-002 (/qs3/pubsys2/xml/en/procedures/99/99-t00-002.html)
Procedure Title	Troubleshooting Symptom Charts
Update Reason	

Date	01-Oct-2002
Section	Section 0 - Complete Engine - Group 00
Procedure Number	99-000-009 (/qs3/pubsys2/xml/en/procedures/99/99-000-009.html)
Procedure Title	Engine Steam Cleaning
Update Reason	
Date	29-Apr-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-055 (/qs3/pubsys2/xml/en/procedures/20/20-001-055.html)
Procedure Title	Gear Train Backlash, Front
Update Reason	
Date	29-Apr-2003
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-056 (/qs3/pubsys2/xml/en/procedures/20/20-001-056.html)
Procedure Title	Camshaft Thrust Bearing
Update Reason	
Date	29-Apr-2003
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-003 (/qs3/pubsys2/xml/en/procedures/20/20-006-003.html)
Procedure Title	Air in Fuel
Update Reason	
Date	29-Apr-2003
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-028 (/qs3/pubsys2/xml/en/procedures/20/20-007-028.html)
Procedure Title	Lubricating Oil Pressure Gauge
Update Reason	

Date	29-Apr-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-020 (/qs3/pubsys2/xml/en/procedures/20/20-008-020.html)
Procedure Title	Cooling System Diagnostics
Update Reason	
Date	29-Apr-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-038 (/qs3/pubsys2/xml/en/procedures/20/20-008-038.html)
Procedure Title	Fan Shroud Assembly
Update Reason	
Date	29-Apr-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-042 (/qs3/pubsys2/xml/en/procedures/20/20-008-042.html)
Procedure Title	Radiator
Update Reason	
Date	29-Apr-2003
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-047 (/qs3/pubsys2/xml/en/procedures/20/20-008-047.html)
Procedure Title	Radiator Pressure Cap
Update Reason	
Date	29-Apr-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-031 (/qs3/pubsys2/xml/en/procedures/20/20-010-031.html)
Procedure Title	Air Intake Restriction
Update Reason	

Date	29-Apr-2003
Section	Section 11 - Exhaust System - Group 11
Procedure Number	20-011-009 (/qs3/pubsys2/xml/en/procedures/20/20-011-009.html)
Procedure Title	Exhaust Restriction
Update Reason	
Date	29-Apr-2003
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-010 (/qs3/pubsys2/xml/en/procedures/20/20-012-010.html)
Procedure Title	Air Compressor Pin Bore Wear
Update Reason	
Date	29-Apr-2003
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-014-004-tr (/qs3/pubsys2/xml/en/procedures/20/20-014-004-tr.html)
Procedure Title	Engine Run-in (Without Dynamometer)
Update Reason	
Date	26-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	99-013-007 (/qs3/pubsys2/xml/en/procedures/99/99-013-007.html)
Procedure Title	Batteries
Update Reason	
Date	26-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	99-013-009 (/qs3/pubsys2/xml/en/procedures/99/99-013-009.html)
Procedure Title	Battery Cables and Connections
Update Reason	

Date	29-Jan-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	99-008-067 (/qs3/pubsys2/xml/en/procedures/99/99-008-067.html)
Procedure Title	Sea Water Strainer
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-010 (/qs3/pubsys2/xml/en/procedures/99/99-018-010.html)
Procedure Title	Fraction, Decimal, Millimeter Conversions
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-011 (/qs3/pubsys2/xml/en/procedures/99/99-018-011.html)
Procedure Title	Newton-Meter to Foot-Pound Conversions
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-012 (/qs3/pubsys2/xml/en/procedures/99/99-018-012.html)
Procedure Title	Pipe Plug Torque Values
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-013 (/qs3/pubsys2/xml/en/procedures/99/99-018-013.html)
Procedure Title	Tap-Drill Chart - U.S. Customary and Metric
Update Reason	

Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-014 (/qs3/pubsys2/xml/en/procedures/99/99-018-014.html)
Procedure Title	Weights and Measures - Conversion Factors
Update Reason	
Date	29-Mar-2004
Section	Section 14 - Engine Testing - Group 14
Procedure Number	00-014-012 (/qs3/pubsys2/xml/en/procedures/00/00-014-012.html)
Procedure Title	Engine Compression
Update Reason	
Date	02-Apr-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-003 (/qs3/pubsys2/xml/en/procedures/20/20-007-003.html)
Procedure Title	Lubricating Oil Cooler
Update Reason	
Date	02-Apr-2004
Section	Section 11 - Exhaust System - Group 11
Procedure Number	20-011-015-tr (/qs3/pubsys2/xml/en/procedures/20/20-011-015-tr.html)
Procedure Title	Exhaust manifold Heat Shield
Update Reason	
Date	05-May-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-058 (/qs3/pubsys2/xml/en/procedures/20/20-001-058.html)
Procedure Title	Cylinder Block Counterbore
Update Reason	

Date	05-May-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-066 (/qs3/pubsys2/xml/en/procedures/20/20-001-066.html)
Procedure Title	Gear Cover Accessory Drive Bushing
Update Reason	
Date	05-May-2004
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-008 (/qs3/pubsys2/xml/en/procedures/20/20-003-008.html)
Procedure Title	Rocker Lever
Update Reason	
Date	06-May-2004
Section	Section F - Familiarization
Procedure Number	20-011-999-tr (/qs3/pubsys2/xml/en/procedures/20/20-011-999-tr.html)
Procedure Title	Exhaust System - Overview
Update Reason	
Date	11-May-2004
Section	Section F - Familiarization
Procedure Number	20-012-999 (/qs3/pubsys2/xml/en/procedures/20/20-012-999.html)
Procedure Title	Compressed Air System - Overview
Update Reason	
Date	11-May-2004
Section	Section F - Familiarization
Procedure Number	20-013-999 (/qs3/pubsys2/xml/en/procedures/20/20-013-999.html)
Procedure Title	Electrical Equipment - Overview
Update Reason	

Date	11-May-2004
Section	Section F - Familiarization
Procedure Number	20-016-999 (/qs3/pubsys2/xml/en/procedures/20/20-016-999.html)
Procedure Title	Mounting Adaptations - Overview
Update Reason	
Date	11-May-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-061-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-061-shopds.html)
Procedure Title	Oil Transfer Connection
Update Reason	
Date	11-May-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-011-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-011-shopds.html)
Procedure Title	Lubricating Oil Dipstick Tube
Update Reason	
Date	11-May-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-011-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-011-shopas.html)
Procedure Title	Lubricating Oil Dipstick Tube
Update Reason	
Date	11-May-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-061-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-061-shopas.html)
Procedure Title	Oil Transfer Connection
Update Reason	

Date	11-May-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-011-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-011-tr.html)
Procedure Title	Lubricating Oil Dipstick Tube
Update Reason	
Date	11-May-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-061-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-061-tr.html)
Procedure Title	Oil Transfer Connection
Update Reason	
Date	24-May-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-008-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-008-shopds.html)
Procedure Title	Camshaft
Update Reason	
Date	24-May-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-011-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-011-shopds.html)
Procedure Title	Camshaft Cover Plate
Update Reason	
Date	24-May-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-008-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-008-shopas.html)
Procedure Title	Camshaft
Update Reason	

Date	24-May-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-011-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-011-shopas.html)
Procedure Title	Camshaft Cover Plate
Update Reason	
Date	24-May-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-008-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-008-tr.html)
Procedure Title	Camshaft
Update Reason	
Date	24-May-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-011-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-011-tr.html)
Procedure Title	Camshaft Cover Plate
Update Reason	
Date	27-May-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-013-001-shopds (/qs3/pubsys2/xml/en/procedures/20/20-013-001-shopds.html)
Procedure Title	Alternator
Update Reason	
Date	27-May-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-019-072-shopds (/qs3/pubsys2/xml/en/procedures/20/20-019-072-shopds.html)
Procedure Title	OEM Interface Harness
Update Reason	

Date	27-May-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-019-031-shopds (/qs3/pubsys2/xml/en/procedures/20/20-019-031-shopds.html)
Procedure Title	Electronic Control Module (ECM)
Update Reason	
Date	27-May-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-019-042-shopds (/qs3/pubsys2/xml/en/procedures/20/20-019-042-shopds.html)
Procedure Title	Engine Speed Sensor
Update Reason	
Date	27-May-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-019-066-shopds (/qs3/pubsys2/xml/en/procedures/20/20-019-066-shopds.html)
Procedure Title	Lubricating Oil Pressure Sensor
Update Reason	
Date	27-May-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-019-066-shopas (/qs3/pubsys2/xml/en/procedures/20/20-019-066-shopas.html)
Procedure Title	Lubricating Oil Pressure Sensor
Update Reason	
Date	27-May-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-013-001-shopas (/qs3/pubsys2/xml/en/procedures/20/20-013-001-shopas.html)
Procedure Title	Alternator
Update Reason	

Date	27-May-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-019-031-shopas (/qs3/pubsys2/xml/en/procedures/20/20-019-031-shopas.html)
Procedure Title	Electronic Control Module (ECM)
Update Reason	
Date	27-May-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-019-042-shopas (/qs3/pubsys2/xml/en/procedures/20/20-019-042-shopas.html)
Procedure Title	Engine Speed Sensor
Update Reason	
Date	27-May-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-019-072-shopas (/qs3/pubsys2/xml/en/procedures/20/20-019-072-shopas.html)
Procedure Title	OEM Interface Harness
Update Reason	
Date	27-May-2004
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-013-001-tr.html)
Procedure Title	Alternator
Update Reason	
Date	02-Jun-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-003-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-003-shopds.html)
Procedure Title	Accessory Drive Seal
Update Reason	

Date	02-Jun-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-052-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-052-shopds.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	
Date	02-Jun-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-003-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-003-shopas.html)
Procedure Title	Accessory Drive Seal
Update Reason	
Date	02-Jun-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-052-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-052-shopas.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	
Date	02-Jun-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-003-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-003-tr.html)
Procedure Title	Accessory Drive Seal
Update Reason	
Date	02-Jun-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-052-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-052-tr.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	

Date	17-Jun-2004
Section	Section F - Familiarization
Procedure Number	20-002-999 (/qs3/pubsys2/xml/en/procedures/20/20-002-999.html)
Procedure Title	Cylinder Head - Overview
Update Reason	
Date	28-Jun-2004
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-003 (/qs3/pubsys2/xml/en/procedures/20/20-013-003.html)
Procedure Title	Alternator Bracket
Update Reason	
Date	28-Jun-2004
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-022 (/qs3/pubsys2/xml/en/procedures/20/20-013-022.html)
Procedure Title	Alternator Adjusting Link
Update Reason	
Date	28-Jun-2004
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-014-008 (/qs3/pubsys2/xml/en/procedures/20/20-014-008.html)
Procedure Title	Engine Testing (In Chassis)
Update Reason	
Date	28-Jun-2004
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	20-016-008-tr (/qs3/pubsys2/xml/en/procedures/20/20-016-008-tr.html)
Procedure Title	Flywheel Ring Gear
Update Reason	

Date	02-Jul-2004
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	20-004-002 (/qs3/pubsys2/xml/en/procedures/20/20-004-002.html)
Procedure Title	Cam Follower Cover
Update Reason	
Date	02-Jul-2004
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-031 (/qs3/pubsys2/xml/en/procedures/20/20-009-031.html)
Procedure Title	Water Pump Drive Gear and Shaft
Update Reason	
Date	14-Jul-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-010-023-shopds (/qs3/pubsys2/xml/en/procedures/20/20-010-023-shopds.html)
Procedure Title	Air Intake Manifold
Update Reason	
Date	14-Jul-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-010-023-shopas (/qs3/pubsys2/xml/en/procedures/20/20-010-023-shopas.html)
Procedure Title	Air Intake Manifold
Update Reason	
Date	14-Jul-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-023-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-023-tr.html)
Procedure Title	Air Intake Manifold
Update Reason	

Date	17-Sep-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-019-043-shopds (/qs3/pubsys2/xml/en/procedures/20/20-019-043-shopds.html)
Procedure Title	Engine Wiring Harness
Update Reason	
Date	17-Sep-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-019-043-shopas (/qs3/pubsys2/xml/en/procedures/20/20-019-043-shopas.html)
Procedure Title	Engine Wiring Harness
Update Reason	
Date	24-Sep-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-040-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-040-shopds.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	
Date	24-Sep-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-040-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-040-shopas.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	
Date	24-Sep-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-039-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-039-tr.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	

Date	24-Sep-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-040-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-040-tr.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	
Date	29-Nov-2004
Section	Section F - Familiarization
Procedure Number	20-009-999-tr (/qs3/pubsys2/xml/en/procedures/20/20-009-999-tr.html)
Procedure Title	Drive Units - Overview
Update Reason	
Date	07-Dec-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-012-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-012-tr.html)
Procedure Title	Camshaft Gear (Camshaft Installed)
Update Reason	
Date	07-Dec-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-064-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-064-tr.html)
Procedure Title	Cylinder Liner Protrusion
Update Reason	
Date	07-Dec-2004
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-069-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-069-tr.html)
Procedure Title	Crankshaft Tone Wheel
Update Reason	

Date	07-Dec-2004
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	20-002-021 (/qs3/pubsys2/xml/en/procedures/20/20-002-021.html)
Procedure Title	Cylinder Head Gasket
Update Reason	
Date	07-Dec-2004
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-017 (/qs3/pubsys2/xml/en/procedures/20/20-012-017.html)
Procedure Title	Air Governor (Air Compressor Will Not Pump)
Update Reason	
Date	09-Dec-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-027 (/qs3/pubsys2/xml/en/procedures/20/20-010-027.html)
Procedure Title	Charge Air Cooler
Update Reason	
Date	13-Dec-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-019 (/qs3/pubsys2/xml/en/procedures/20/20-008-019.html)
Procedure Title	Cooling System - Air or Combustion Gas Test
Update Reason	
Date	13-Dec-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-022 (/qs3/pubsys2/xml/en/procedures/20/20-008-022.html)
Procedure Title	Cooling System Service Requirements
Update Reason	

Date	13-Dec-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-045 (/qs3/pubsys2/xml/en/procedures/20/20-008-045.html)
Procedure Title	Radiator Hoses
Update Reason	
Date	13-Dec-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-060 (/qs3/pubsys2/xml/en/procedures/20/20-008-060.html)
Procedure Title	Supplemental Coolant Additive (SCA)
Update Reason	
Date	13-Dec-2004
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-003-tr (/qs3/pubsys2/xml/en/procedures/20/20-012-003-tr.html)
Procedure Title	Air Compressor Carbon Buildup
Update Reason	
Date	13-Dec-2004
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-014-001 (/qs3/pubsys2/xml/en/procedures/20/20-014-001.html)
Procedure Title	Dynamometer Worksheet
Update Reason	
Date	20-Dec-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-008-029-shopds (/qs3/pubsys2/xml/en/procedures/20/20-008-029-shopds.html)
Procedure Title	Fan Drive Idler Arm Assembly
Update Reason	

Date	20-Dec-2004
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-012-014-shopds (/qs3/pubsys2/xml/en/procedures/20/20-012-014-shopds.html)
Procedure Title	Air Compressor
Update Reason	
Date	20-Dec-2004
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-012-014-shopas (/qs3/pubsys2/xml/en/procedures/20/20-012-014-shopas.html)
Procedure Title	Air Compressor
Update Reason	
Date	20-Dec-2004
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-029-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-029-tr.html)
Procedure Title	Fan Drive Idler Arm Assembly
Update Reason	
Date	20-Dec-2004
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-041-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-041-tr.html)
Procedure Title	Turbocharger Coolant Hoses
Update Reason	
Date	20-Dec-2004
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-014-tr (/qs3/pubsys2/xml/en/procedures/20/20-012-014-tr.html)
Procedure Title	Air Compressor
Update Reason	

Date	20-Dec-2004
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-014-002-tr (/qs3/pubsys2/xml/en/procedures/20/20-014-002-tr.html)
Procedure Title	Engine Testing (Chassis Dynamometer)
Update Reason	
Date	27-Apr-2005
Section	Section F - Familiarization
Procedure Number	20-200-006 (/qs3/pubsys2/xml/en/procedures/20/20-200-006.html)
Procedure Title	Flow Diagram, Compressed Air System
Update Reason	
Date	14-Oct-2005
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-010-076-shopds (/qs3/pubsys2/xml/en/procedures/20/20-010-076-shopds.html)
Procedure Title	Turbocharger Heat Shield
Update Reason	
Date	14-Oct-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-010-076-shopas (/qs3/pubsys2/xml/en/procedures/20/20-010-076-shopas.html)
Procedure Title	Turbocharger Heat Shield
Update Reason	
Date	14-Oct-2005
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-076-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-076-tr.html)
Procedure Title	Turbocharger Heat Shield
Update Reason	

Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t004-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t004-tr.html)
Procedure Title	Air Compressor Air Pressure Rises Slowly
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t006-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t006-tr.html)
Procedure Title	Air Compressor Noise is Excessive
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t007-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t007-tr.html)
Procedure Title	Air Compressor Pumping Excess Lubricating Oil into the Air System
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t008-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t008-tr.html)
Procedure Title	Air Compressor Will Not Maintain Adequate Air Pressure (Not Pumping Continuously)
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t009-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t009-tr.html)
Procedure Title	Air Compressor Will Not Pump Air
Update Reason	

Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t010-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t010-tr.html)
Procedure Title	Air Compressor Will Not Stop Pumping
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t013-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t013-tr.html)
Procedure Title	Alternator Not Charging or Insufficient Charging
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t014-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t014-tr.html)
Procedure Title	Alternator Overcharging
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t020-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t020-tr.html)
Procedure Title	Coolant Loss - External
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t022-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t022-tr.html)
Procedure Title	Coolant Temperature Above Normal - Gradual Overheat
Update Reason	

Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t023-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t023-tr.html)
Procedure Title	Coolant Temperature is Above Normal - Sudden Overheat
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t024-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t024-tr.html)
Procedure Title	Coolant Temperature is Below Normal
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t026-156-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t026-156-tr.html)
Procedure Title	Coolant Temperature Above Normal - Sea Water Cooling
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t047-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t047-tr.html)
Procedure Title	Engine Noise Excessive
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t048-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t048-tr.html)
Procedure Title	Engine Noise Excessive - Combustion Knocks
Update Reason	

Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t049-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t049-tr.html)
Procedure Title	Engine Noise Excessive - Connecting Rod
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t050-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t050-tr.html)
Procedure Title	Engine Noise Excessive - Main Bearing
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t051-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t051-tr.html)
Procedure Title	Engine Noise Excessive - Piston
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t052-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t052-tr.html)
Procedure Title	Engine Noise Excessive - Turbocharger
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t077-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t077-tr.html)
Procedure Title	Engine Will Not Crank or Cranks Slowly (Air Starter)
Update Reason	

Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t078-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t078-tr.html)
Procedure Title	Engine Will Not Crank or Cranks Slowly (Electric Starter)
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t081-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t081-tr.html)
Procedure Title	Engine Will Not Shut Off
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t083-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t083-tr.html)
Procedure Title	Fault Code Warning Lamps Stay On (No Apparent Reason)
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t084-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t084-tr.html)
Procedure Title	Fault Code Warning Lamps Do Not Illuminate
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t087-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t087-tr.html)
Procedure Title	Fuel Consumption Excessive
Update Reason	

Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t091-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t091-tr.html)
Procedure Title	Fuel in Coolant
Update Reason	
Date	03-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t092-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t092-tr.html)
Procedure Title	Fuel in the Lubricating Oil
Update Reason	
Date	05-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t096-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t096-tr.html)
Procedure Title	Intake Manifold Air Temperature Above Specification
Update Reason	
Date	05-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t099-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t099-tr.html)
Procedure Title	Low Idle Adjust Switch Does Not Work
Update Reason	
Date	05-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t104-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t104-tr.html)
Procedure Title	Lubricating Oil Pressure High
Update Reason	

Date	05-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t105-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t105-tr.html)
Procedure Title	Lubricating Oil Pressure Low
Update Reason	
Date	05-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t106-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t106-tr.html)
Procedure Title	Lubricating Oil Sludge in the Crankcase Excessive
Update Reason	
Date	05-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t107-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t107-tr.html)
Procedure Title	Lubricating Oil Temperature Above Specification
Update Reason	
Date	05-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t108-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t108-tr.html)
Procedure Title	Lubricating or Transmission Oil in the Coolant
Update Reason	
Date	05-May-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t122-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t122-tr.html)
Procedure Title	Turbocharger Leaks Engine Oil or Fuel
Update Reason	

Date	05-May-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-026-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-026-tr.html)
Procedure Title	Cylinder Block
Update Reason	
Date	15-May-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-066 (/qs3/pubsys2/xml/en/procedures/20/20-007-066.html)
Procedure Title	Eliminator Filter Centrifuge
Update Reason	
Date	18-May-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-013-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-013-shopas.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	
Date	22-May-2006
Section	front
Procedure Number	shop-frwd (/qs3/pubsys2/xml/en/manual/preface/shop-frwd.html)
Procedure Title	Forward
Update Reason	
Date	24-May-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-013-005-shopds (/qs3/pubsys2/xml/en/procedures/20/20-013-005-shopds.html)
Procedure Title	Drive Belt, Alternator
Update Reason	

Date	24-May-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-013-005-shopas (/qs3/pubsys2/xml/en/procedures/20/20-013-005-shopas.html)
Procedure Title	Drive Belt, Alternator
Update Reason	
Date	24-May-2006
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-005-tr (/qs3/pubsys2/xml/en/procedures/20/20-013-005-tr.html)
Procedure Title	Drive Belt, Alternator
Update Reason	
Date	15-Jun-2006
Section	Section F - Familiarization
Procedure Number	20-200-002 (/qs3/pubsys2/xml/en/procedures/20/20-200-002.html)
Procedure Title	Flow Diagram, Lubricating Oil System
Update Reason	
Date	26-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-023-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-023-shopds.html)
Procedure Title	Crankcase Seal, Front
Update Reason	
Date	26-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-031-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-031-shopds.html)
Procedure Title	Gear Cover, Front
Update Reason	

Date	26-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-036-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-036-shopds.html)
Procedure Title	Idler Gear, Camshaft
Update Reason	
Date	26-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-029-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-029-shopds.html)
Procedure Title	Gear Cover Spacer Plate
Update Reason	
Date	26-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-029-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-029-shopas.html)
Procedure Title	Gear Cover Spacer Plate
Update Reason	
Date	26-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-036-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-036-shopas.html)
Procedure Title	Idle Gear, Camshaft
Update Reason	
Date	26-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-031-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-031-shopas.html)
Procedure Title	Gear Cover, Front
Update Reason	

Date	26-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-023-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-023-shopas.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	
Date	26-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-018-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-018-tr.html)
Procedure Title	Crankshaft Gear, Front (Crankshaft Installed)
Update Reason	
Date	26-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-022-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-022-tr.html)
Procedure Title	Crankshaft Pulley
Update Reason	
Date	26-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-023-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-023-tr.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	
Date	26-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-027 (/qs3/pubsys2/xml/en/procedures/20/20-001-027.html)
Procedure Title	Cylinder Block and Liner Seats
Update Reason	

Date	26-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-029-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-029-tr.html)
Procedure Title	Gear Cover, Spacer Plate
Update Reason	
Date	26-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-031-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-031-tr.html)
Procedure Title	Gear Cover, Front
Update Reason	
Date	26-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-036-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-036-tr.html)
Procedure Title	Idler Gear, Camshaft
Update Reason	
Date	27-Jun-2006
Section	Section L - Service Literature
Procedure Number	99-205-002 (/qs3/pubsys2/xml/en/procedures/99/99-205-002.html)
Procedure Title	Service Literature Ordering Location
Update Reason	
Date	28-Jun-2006
Section	Section F - Familiarization
Procedure Number	20-003-999 (/qs3/pubsys2/xml/en/procedures/20/20-003-999.html)
Procedure Title	Rocker Levers - Overview
Update Reason	

Date	28-Jun-2006
Section	Section F - Familiarization
Procedure Number	20-004-999 (/qs3/pubsys2/xml/en/procedures/20/20-004-999.html)
Procedure Title	Cam Followers/Tappets - Overview
Update Reason	
Date	28-Jun-2006
Section	Section F - Familiarization
Procedure Number	20-010-999-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-999-tr.html)
Procedure Title	Air Intake System - Overview
Update Reason	
Date	28-Jun-2006
Section	Section F - Familiarization
Procedure Number	20-200-004 (/qs3/pubsys2/xml/en/procedures/20/20-200-004.html)
Procedure Title	Flow Diagram, Air Intake System
Update Reason	
Date	28-Jun-2006
Section	Section F - Familiarization
Procedure Number	20-014-999 (/qs3/pubsys2/xml/en/procedures/20/20-014-999.html)
Procedure Title	Engine Testing - Overview
Update Reason	
Date	28-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-013-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-013-tr.html)
Procedure Title	Camshaft Gear (Camshaft Removed)
Update Reason	

Date	30-Jun-2006
Section	Section F - Familiarization
Procedure Number	20-005-999-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-999-tr.html)
Procedure Title	Fuel System - Overview
Update Reason	
Date	30-Jun-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t089-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t089-tr.html)
Procedure Title	Fuel Temperature Above Normal Operating Range
Update Reason	
Date	30-Jun-2006
Section	Section 0 - Complete Engine - Group 00
Procedure Number	20-022-001_00 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_00.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2006
Section	Section 0 - Complete Engine - Group 00
Procedure Number	20-000-002 (/qs3/pubsys2/xml/en/procedures/20/20-000-002.html)
Procedure Title	Engine Installation
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-022-001_00 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_00.html)
Procedure Title	Service Tools
Update Reason	

Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-008-006-shopds (/qs3/pubsys2/xml/en/procedures/20/20-008-006-shopds.html)
Procedure Title	Coolant Filter
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-008-062-shopds (/qs3/pubsys2/xml/en/procedures/20/20-008-062-shopds.html)
Procedure Title	Water Pump
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-025-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-025-shopds.html)
Procedure Title	Lubricating Oil Pan
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-013-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-013-shopds.html)
Procedure Title	Lubricating Oil Filter
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-008-036-shopds (/qs3/pubsys2/xml/en/procedures/20/20-008-036-shopds.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	

Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-045-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-045-shopds.html)
Procedure Title	Lubricating Oil Cooler Cover
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-046-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-046-shopds.html)
Procedure Title	Lubricating Oil Cooler Housing
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-007-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-007-shopds.html)
Procedure Title	Lubricating Oil Cooler Element
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-013-020-shopds (/qs3/pubsys2/xml/en/procedures/20/20-013-020-shopds.html)
Procedure Title	Starting Motor
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-015-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-015-shopds.html)
Procedure Title	Lubricating Oil Filter Head
Update Reason	

Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-009-010-shopds (/qs3/pubsys2/xml/en/procedures/20/20-009-010-shopds.html)
Procedure Title	Alternator Drive Pulley
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-001-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-001-shopds.html)
Procedure Title	Alternator Drive Seal
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-009-029-shopds (/qs3/pubsys2/xml/en/procedures/20/20-009-029-shopds.html)
Procedure Title	Water Pump Drive
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-008-015-shopds (/qs3/pubsys2/xml/en/procedures/20/20-008-015-shopds.html)
Procedure Title	Coolant Thermostat Housing Support
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-046-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-046-shopds.html)
Procedure Title	Piston Cooling Nozzle
Update Reason	

Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-016-002-shopds (/qs3/pubsys2/xml/en/procedures/20/20-016-002-shopds.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-016-005-shopds (/qs3/pubsys2/xml/en/procedures/20/20-016-005-shopds.html)
Procedure Title	Flywheel
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-026-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-026-shopds.html)
Procedure Title	Lubricating Oil Pan Adapter Cover Plate
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-016-006-shopds (/qs3/pubsys2/xml/en/procedures/20/20-016-006-shopds.html)
Procedure Title	Flywheel Housing
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-009-024-shopds (/qs3/pubsys2/xml/en/procedures/20/20-009-024-shopds.html)
Procedure Title	Rear Gear Drive (Upper Assembly)
Update Reason	

Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-009-023-shopds (/qs3/pubsys2/xml/en/procedures/20/20-009-023-shopds.html)
Procedure Title	Rear Gear Drive (Lower Assembly)
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-006-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-006-shopds.html)
Procedure Title	Bearings, Main
Update Reason	
Date	30-Jun-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-007-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-007-shopds.html)
Procedure Title	Bearings, Thrust
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-022-001_00 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_00.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-007-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-007-shopas.html)
Procedure Title	Bearings, Thrust
Update Reason	

Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-006-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-006-shopas.html)
Procedure Title	Bearings, Main
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-009-023-shopas (/qs3/pubsys2/xml/en/procedures/20/20-009-023-shopas.html)
Procedure Title	Rear Gear Drive (Lower Assembly)
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-009-024-shopas (/qs3/pubsys2/xml/en/procedures/20/20-009-024-shopas.html)
Procedure Title	Rear Gear Drive (Upper Assembly)
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-016-006-shopas (/qs3/pubsys2/xml/en/procedures/20/20-016-006-shopas.html)
Procedure Title	Flywheel Housing
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-016-005-shopas (/qs3/pubsys2/xml/en/procedures/20/20-016-005-shopas.html)
Procedure Title	Flywheel
Update Reason	

Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-026-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-026-shopas.html)
Procedure Title	Lubricating Oil Pan Adapter Cover Plate
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-016-002-shopas (/qs3/pubsys2/xml/en/procedures/20/20-016-002-shopas.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-025-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-025-shopas.html)
Procedure Title	Lubricating Oil Pan
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-009-029-shopas (/qs3/pubsys2/xml/en/procedures/20/20-009-029-shopas.html)
Procedure Title	Water Pump Drive
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-001-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-001-shopas.html)
Procedure Title	Alternator Drive Seal
Update Reason	

Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-009-010-shopas (/qs3/pubsys2/xml/en/procedures/20/20-009-010-shopas.html)
Procedure Title	Alternator Drive Pulley
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-046-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-046-shopas.html)
Procedure Title	Piston Cooling Nozzle
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-008-015-shopas (/qs3/pubsys2/xml/en/procedures/20/20-008-015-shopas.html)
Procedure Title	Coolant Thermostat Housing Support
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-015-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-015-shopas.html)
Procedure Title	Lubricating Oil Filter Head
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-007-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-007-shopas.html)
Procedure Title	Lubricating Oil Cooler Element
Update Reason	

Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-046-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-046-shopas.html)
Procedure Title	Lubricating Oil Cooler Housing
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-045-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-045-shopas.html)
Procedure Title	Lubricating Oil Cooler Cover
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-008-036-shopas (/qs3/pubsys2/xml/en/procedures/20/20-008-036-shopas.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-008-062-shopas (/qs3/pubsys2/xml/en/procedures/20/20-008-062-shopas.html)
Procedure Title	Water Pump
Update Reason	
Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-008-006-shopas (/qs3/pubsys2/xml/en/procedures/20/20-008-006-shopas.html)
Procedure Title	Coolant Filter
Update Reason	

Date	30-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-013-020-shopas (/qs3/pubsys2/xml/en/procedures/20/20-013-020-shopas.html)
Procedure Title	Starting Motor
Update Reason	
Date	30-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-001-tr.html)
Procedure Title	Alternator Drive Seal
Update Reason	
Date	30-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-006-tr.html)
Procedure Title	Bearings, Main
Update Reason	
Date	30-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-007-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-007-tr.html)
Procedure Title	Bearings, Thrust
Update Reason	
Date	30-Jun-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-046-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-046-tr.html)
Procedure Title	Piston Cooling Nozzle
Update Reason	

Date	30-Jun-2006
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-022-001_03 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_03.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2006
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-010 (/qs3/pubsys2/xml/en/procedures/20/20-003-010.html)
Procedure Title	Rocker Lever Bushings
Update Reason	
Date	30-Jun-2006
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-022-001_05 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_05.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-022-001_07 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_07.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-007-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-007-tr.html)
Procedure Title	Lubricating Oil Cooler Element
Update Reason	

Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-009 (/qs3/pubsys2/xml/en/procedures/20/20-007-009.html)
Procedure Title	Lubricating Oil Dipstick
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-013-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-013-tr.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-015-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-015-tr.html)
Procedure Title	Lubricating Oil Filter Head
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-018 (/qs3/pubsys2/xml/en/procedures/20/20-007-018.html)
Procedure Title	Lubricating Oil Filter Head Adapter
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-024 (/qs3/pubsys2/xml/en/procedures/20/20-007-024.html)
Procedure Title	Lubricating Oil Leaks
Update Reason	

Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-025-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-025-tr.html)
Procedure Title	Lubricating Oil Pan
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-026-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-026-tr.html)
Procedure Title	Lubricating Oil Pan Adapter Cover Plate
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-029 (/qs3/pubsys2/xml/en/procedures/20/20-007-029.html)
Procedure Title	Lubricating Oil Pressure Regulator (Main Rifle)
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-035-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-035-tr.html)
Procedure Title	Lubricating Oil Suction Tube (Block-Mounted)
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-038 (/qs3/pubsys2/xml/en/procedures/20/20-007-038.html)
Procedure Title	Lubricating Oil Temperature Gauge
Update Reason	

Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-045-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-045-tr.html)
Procedure Title	Lubricating Oil Cooler Cover
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-046-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-046-tr.html)
Procedure Title	Lubricating Oil Cooler Housing
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-050 (/qs3/pubsys2/xml/en/procedures/20/20-007-050.html)
Procedure Title	Cylinder Smokes (Blue Smoke)
Update Reason	
Date	30-Jun-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-060 (/qs3/pubsys2/xml/en/procedures/20/20-007-060.html)
Procedure Title	Oil Scavenge Pump
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-022-001_08 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_08.html)
Procedure Title	Service Tools
Update Reason	

Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-004 (/qs3/pubsys2/xml/en/procedures/20/20-008-004.html)
Procedure Title	Coolant Temperature Gauge
Update Reason	

Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-006-tr.html)
Procedure Title	Coolant Filter
Update Reason	

Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-008 (/qs3/pubsys2/xml/en/procedures/20/20-008-008.html)
Procedure Title	Coolant Filter Head (Remote Mounted)
Update Reason	

Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-013-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-013-tr.html)
Procedure Title	Coolant Thermostat
Update Reason	

Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-015-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-015-tr.html)
Procedure Title	Coolant Thermostat Housing Support
Update Reason	

Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-016-tr.html)
Procedure Title	Coolant Thermostat Seal
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-017 (/qs3/pubsys2/xml/en/procedures/20/20-008-017.html)
Procedure Title	Coolant Vent Lines
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-036-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-036-tr.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-040 (/qs3/pubsys2/xml/en/procedures/20/20-008-040.html)
Procedure Title	Fan, Cooling
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-041 (/qs3/pubsys2/xml/en/procedures/20/20-008-041.html)
Procedure Title	Marine Gear Oil Cooler
Update Reason	

Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-051 (/qs3/pubsys2/xml/en/procedures/20/20-008-051.html)
Procedure Title	Radiator Top Tank
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-053 (/qs3/pubsys2/xml/en/procedures/20/20-008-053.html)
Procedure Title	Heat Exchanger
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-059 (/qs3/pubsys2/xml/en/procedures/20/20-008-059.html)
Procedure Title	Zinc Anode
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-062-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-065-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-065-tr.html)
Procedure Title	Torque Converter Cooler
Update Reason	

Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-071 (/qs3/pubsys2/xml/en/procedures/20/20-008-071.html)
Procedure Title	Water Pump Bearings
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-103 (/qs3/pubsys2/xml/en/procedures/20/20-008-103.html)
Procedure Title	Sea Water System Diagnostics
Update Reason	
Date	30-Jun-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-104 (/qs3/pubsys2/xml/en/procedures/20/20-008-104.html)
Procedure Title	Sea Water Hoses
Update Reason	
Date	30-Jun-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-022-001_09 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_09.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-005 (/qs3/pubsys2/xml/en/procedures/20/20-009-005.html)
Procedure Title	Accessory Drive Pulley Wear Sleeve
Update Reason	

Date	30-Jun-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-010-tr (/qs3/pubsys2/xml/en/procedures/20/20-009-010-tr.html)
Procedure Title	Alternator Drive Pulley
Update Reason	

Date	30-Jun-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-011 (/qs3/pubsys2/xml/en/procedures/20/20-009-011.html)
Procedure Title	Fuel Pump Drive
Update Reason	

Date	30-Jun-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-023-tr (/qs3/pubsys2/xml/en/procedures/20/20-009-023-tr.html)
Procedure Title	Rear Gear Drive (Lower Assembly)
Update Reason	

Date	30-Jun-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-024-tr (/qs3/pubsys2/xml/en/procedures/20/20-009-024-tr.html)
Procedure Title	Rear Gear Drive (Upper Assembly)
Update Reason	

Date	30-Jun-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-029-tr (/qs3/pubsys2/xml/en/procedures/20/20-009-029-tr.html)
Procedure Title	Water Pump Drive
Update Reason	

Date	30-Jun-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-030 (/qs3/pubsys2/xml/en/procedures/20/20-009-030.html)
Procedure Title	Water Pump Drive Bushing
Update Reason	
Date	30-Jun-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-036 (/qs3/pubsys2/xml/en/procedures/20/20-009-036.html)
Procedure Title	Outer Hydraulic Pump Support Drive
Update Reason	
Date	30-Jun-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-037 (/qs3/pubsys2/xml/en/procedures/20/20-009-037.html)
Procedure Title	Hydraulic Pump Support Bushing
Update Reason	
Date	30-Jun-2006
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-022-001_10 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_10.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2006
Section	Section 11 - Exhaust System - Group 11
Procedure Number	20-022-001_11 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_11.html)
Procedure Title	Service Tools
Update Reason	

Date	30-Jun-2006
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-022-001_12 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_12.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2006
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-018 (/qs3/pubsys2/xml/en/procedures/20/20-012-018.html)
Procedure Title	Air Governor (Air Compressor Pumps Continuously)
Update Reason	
Date	30-Jun-2006
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-019 (/qs3/pubsys2/xml/en/procedures/20/20-012-019.html)
Procedure Title	Air Leaks, Compressed Air System
Update Reason	
Date	30-Jun-2006
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-020 (/qs3/pubsys2/xml/en/procedures/20/20-012-020.html)
Procedure Title	Air Compressor (Oil Carryover)
Update Reason	

Date	30-Jun-2006
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-103 (/qs3/pubsys2/xml/en/procedures/20/20-012-103.html)
Procedure Title	Air Compressor Cylinder Head (Holset® SS and E-Type Models)
Update Reason	

Date	30-Jun-2006
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-106 (/qs3/pubsys2/xml/en/procedures/20/20-012-106.html)
Procedure Title	Air Compressor Cylinder Head (Holset® ST Models)
Update Reason	

Date	30-Jun-2006
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-022-001_13 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_13.html)
Procedure Title	Service Tools
Update Reason	

Date	30-Jun-2006
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-006 (/qs3/pubsys2/xml/en/procedures/20/20-013-006.html)
Procedure Title	Alternator Pulley
Update Reason	

Date	30-Jun-2006
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-017 (/qs3/pubsys2/xml/en/procedures/20/20-013-017.html)
Procedure Title	Starter Magnetic Switch
Update Reason	
Date	30-Jun-2006
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-018 (/qs3/pubsys2/xml/en/procedures/20/20-013-018.html)
Procedure Title	Starter Switch
Update Reason	
Date	30-Jun-2006
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-019 (/qs3/pubsys2/xml/en/procedures/20/20-013-019.html)
Procedure Title	Starter Solenoid
Update Reason	
Date	30-Jun-2006
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-020-tr (/qs3/pubsys2/xml/en/procedures/20/20-013-020-tr.html)
Procedure Title	Starting Motor
Update Reason	
Date	30-Jun-2006
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-022-001_14 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_14.html)
Procedure Title	Service Tools
Update Reason	

Date	30-Jun-2006
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-014-003 (/qs3/pubsys2/xml/en/procedures/20/20-014-003.html)
Procedure Title	Engine Run-in (Chassis Dynamometer)
Update Reason	
Date	30-Jun-2006
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-014-006 (/qs3/pubsys2/xml/en/procedures/20/20-014-006.html)
Procedure Title	Engine Run-in (Engine Dynamometer)
Update Reason	
Date	30-Jun-2006
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	20-022-001_16 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_16.html)
Procedure Title	Service Tools
Update Reason	
Date	30-Jun-2006
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	20-016-002-tr (/qs3/pubsys2/xml/en/procedures/20/20-016-002-tr.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	
Date	30-Jun-2006
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	20-016-005-tr (/qs3/pubsys2/xml/en/procedures/20/20-016-005-tr.html)
Procedure Title	Flywheel
Update Reason	

Date	30-Jun-2006
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	20-016-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-016-006-tr.html)
Procedure Title	Flywheel Housing
Update Reason	
Date	30-Jun-2006
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	20-016-011 (/qs3/pubsys2/xml/en/procedures/20/20-016-011.html)
Procedure Title	Rock Shields
Update Reason	
Date	05-Jul-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-010-002-shopds (/qs3/pubsys2/xml/en/procedures/20/20-010-002-shopds.html)
Procedure Title	Aftercooler Assembly
Update Reason	
Date	05-Jul-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-004-014-shopds (/qs3/pubsys2/xml/en/procedures/20/20-004-014-shopds.html)
Procedure Title	Push Rods or Tubes
Update Reason	
Date	05-Jul-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-003-013-shopds (/qs3/pubsys2/xml/en/procedures/20/20-003-013-shopds.html)
Procedure Title	Rocker Lever Housing
Update Reason	

Date	05-Jul-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-003-013-shopas (/qs3/pubsys2/xml/en/procedures/20/20-003-013-shopas.html)
Procedure Title	Rocker Lever Housing
Update Reason	
Date	05-Jul-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-004-014-shopas (/qs3/pubsys2/xml/en/procedures/20/20-004-014-shopas.html)
Procedure Title	Push Rods or Tubes
Update Reason	
Date	05-Jul-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-010-002-shopas (/qs3/pubsys2/xml/en/procedures/20/20-010-002-shopas.html)
Procedure Title	Aftercooler Assembly
Update Reason	
Date	05-Jul-2006
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-013-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-013-tr.html)
Procedure Title	Rocker Lever Housing
Update Reason	
Date	05-Jul-2006
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	20-004-014-tr (/qs3/pubsys2/xml/en/procedures/20/20-004-014-tr.html)
Procedure Title	Push Rods or Tubes
Update Reason	

Date	05-Jul-2006
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-010 (/qs3/pubsys2/xml/en/procedures/20/20-005-010.html)
Procedure Title	Fuel Consumption
Update Reason	
Date	05-Jul-2006
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-025 (/qs3/pubsys2/xml/en/procedures/20/20-005-025.html)
Procedure Title	Fuel Pump Gear Pump
Update Reason	
Date	05-Jul-2006
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-031 (/qs3/pubsys2/xml/en/procedures/20/20-005-031.html)
Procedure Title	Fuel Pump Pulsation Damper
Update Reason	
Date	05-Jul-2006
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-043-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-043-tr.html)
Procedure Title	Fuel Shutoff Valve
Update Reason	
Date	05-Jul-2006
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-002-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-002-tr.html)
Procedure Title	Aftercooler Assembly
Update Reason	

Date	05-Jul-2006
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-008 (/qs3/pubsys2/xml/en/procedures/20/20-010-008.html)
Procedure Title	Aftercooler Element
Update Reason	
Date	05-Jul-2006
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-019-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-019-tr.html)
Procedure Title	Air Crossover
Update Reason	
Date	05-Jul-2006
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-049 (/qs3/pubsys2/xml/en/procedures/20/20-010-049.html)
Procedure Title	Turbocharger Turbine Seal Leaks
Update Reason	
Date	10-Jul-2006
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-014-005 (/qs3/pubsys2/xml/en/procedures/20/20-014-005.html)
Procedure Title	Engine Testing (Engine Dynamometer)
Update Reason	
Date	14-Jul-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-006-022-shopds (/qs3/pubsys2/xml/en/procedures/20/20-006-022-shopds.html)
Procedure Title	Fuel Manifold (Supply)
Update Reason	

Date	14-Jul-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-006-049-shopds (/qs3/pubsys2/xml/en/procedures/20/20-006-049-shopds.html)
Procedure Title	Fuel Control Valve Body Assembly
Update Reason	
Date	14-Jul-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-006-025-shopas (/qs3/pubsys2/xml/en/procedures/20/20-006-025-shopas.html)
Procedure Title	Static Injection Timing
Update Reason	
Date	14-Jul-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-006-022-shopas (/qs3/pubsys2/xml/en/procedures/20/20-006-022-shopas.html)
Procedure Title	Fuel Manifold (Supply)
Update Reason	
Date	14-Jul-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-006-049-shopas (/qs3/pubsys2/xml/en/procedures/20/20-006-049-shopas.html)
Procedure Title	Fuel Control Valve Body Assembly
Update Reason	
Date	14-Jul-2006
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	20-002-001 (/qs3/pubsys2/xml/en/procedures/20/20-002-001.html)
Procedure Title	Crosshead
Update Reason	

Date	14-Jul-2006
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	20-002-022 (/qs3/pubsys2/xml/en/procedures/20/20-002-022.html)
Procedure Title	Injector Protrusion
Update Reason	
Date	14-Jul-2006
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-006-tr.html)
Procedure Title	ECM Cooling Plate, Fuel Cooled
Update Reason	
Date	14-Jul-2006
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-012 (/qs3/pubsys2/xml/en/procedures/20/20-006-012.html)
Procedure Title	Fuel Drain Line Restriction
Update Reason	
Date	14-Jul-2006
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-022-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-022-tr.html)
Procedure Title	Fuel Manifold (Supply)
Update Reason	
Date	14-Jul-2006
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-025-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-025-tr.html)
Procedure Title	Static Injection Timing
Update Reason	

Date	14-Jul-2006
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-049-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-049-tr.html)
Procedure Title	Fuel Control Valve Body Assembly
Update Reason	
Date	19-Jul-2006
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-006-tr.html)
Procedure Title	Aftercooler Coolant Tube
Update Reason	
Date	19-Jul-2006
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-104 (/qs3/pubsys2/xml/en/procedures/20/20-012-104.html)
Procedure Title	Air Compressor Cylinder Head (Holset® QE Models)
Update Reason	
Date	21-Jul-2006
Section	Section 11 - Exhaust System - Group 11
Procedure Number	20-011-001 (/qs3/pubsys2/xml/en/procedures/20/20-011-001.html)
Procedure Title	Exhaust Connection Pipe
Update Reason	
Date	03-Aug-2006
Section	Section F - Familiarization
Procedure Number	20-001-999 (/qs3/pubsys2/xml/en/procedures/20/20-001-999.html)
Procedure Title	Cylinder Block - Overview
Update Reason	

Date	03-Aug-2006
Section	Section F - Familiarization
Procedure Number	20-007-999-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-999-tr.html)
Procedure Title	Lubricating Oil System - Overview
Update Reason	

Date	03-Aug-2006
Section	Section 0 - Complete Engine - Group 00
Procedure Number	20-000-001 (/qs3/pubsys2/xml/en/procedures/20/20-000-001.html)
Procedure Title	Engine Removal
Update Reason	

Date	03-Aug-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-008-052-shopds (/qs3/pubsys2/xml/en/procedures/20/20-008-052-shopds.html)
Procedure Title	Expansion Tank
Update Reason	

Date	03-Aug-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-008-057-shopds (/qs3/pubsys2/xml/en/procedures/20/20-008-057-shopds.html)
Procedure Title	Sea Water Pump
Update Reason	

Date	03-Aug-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-008-057-shopas (/qs3/pubsys2/xml/en/procedures/20/20-008-057-shopas.html)
Procedure Title	Sea Water Pump
Update Reason	

Date	03-Aug-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-008-052-shopas (/qs3/pubsys2/xml/en/procedures/20/20-008-052-shopas.html)
Procedure Title	Expansion Tank
Update Reason	
Date	03-Aug-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-052-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-052-tr.html)
Procedure Title	Expansion Tank
Update Reason	
Date	03-Aug-2006
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-057-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-057-tr.html)
Procedure Title	Sea Water Pump
Update Reason	
Date	03-Aug-2006
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-004 (/qs3/pubsys2/xml/en/procedures/20/20-009-004.html)
Procedure Title	Accessory Drive Pulley
Update Reason	
Date	15-Sep-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-004-001-shopds (/qs3/pubsys2/xml/en/procedures/20/20-004-001-shopds.html)
Procedure Title	Cam Follower Assembly
Update Reason	

Date	15-Sep-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-004-001-shopas (/qs3/pubsys2/xml/en/procedures/20/20-004-001-shopas.html)
Procedure Title	Cam Follower Assembly
Update Reason	
Date	15-Sep-2006
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	20-004-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-004-001-tr.html)
Procedure Title	Cam Follower Assembly
Update Reason	
Date	24-Oct-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-027-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-027-shopds.html)
Procedure Title	Lubricating Oil Pan Adapter
Update Reason	
Date	24-Oct-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-027-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-027-shopas.html)
Procedure Title	Lubricating Oil Pan Adapter
Update Reason	
Date	24-Oct-2006
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-027-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-027-tr.html)
Procedure Title	Lubricating Oil Pan Adapter
Update Reason	

Date	14-Nov-2006
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-024-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-024-shopds.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	
Date	14-Nov-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-024-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-024-shopas.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	
Date	14-Nov-2006
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-024-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-024-tr.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	
Date	14-Nov-2006
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-061 (/qs3/pubsys2/xml/en/procedures/20/20-006-061.html)
Procedure Title	Fuel Pressure Relief Valve
Update Reason	
Date	15-Nov-2006
Section	Section V - Specifications
Procedure Number	20-018-024 (/qs3/pubsys2/xml/en/procedures/20/20-018-024.html)
Procedure Title	Cummins/Fleetguard™ Filter Specifications
Update Reason	

Date	21-Nov-2006
Section	Section F - Familiarization
Procedure Number	20-006-999 (/qs3/pubsys2/xml/en/procedures/20/20-006-999.html)
Procedure Title	Injectors and Fuel Lines - Overview
Update Reason	
Date	26-Jan-2007
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-003-011-shopds (/qs3/pubsys2/xml/en/procedures/20/20-003-011-shopds.html)
Procedure Title	Rocker Lever Cover
Update Reason	
Date	26-Jan-2007
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-003-011-shopas (/qs3/pubsys2/xml/en/procedures/20/20-003-011-shopas.html)
Procedure Title	Rocker Lever Cover
Update Reason	
Date	26-Jan-2007
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-011-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-011-tr.html)
Procedure Title	Rocker Lever Cover
Update Reason	
Date	31-Jan-2007
Section	Section V - Specifications
Procedure Number	20-018-016 (/qs3/pubsys2/xml/en/procedures/20/20-018-016.html)
Procedure Title	Fuel System
Update Reason	

Date	31-Jan-2007
Section	Section V - Specifications
Procedure Number	20-018-018 (/qs3/pubsys2/xml/en/procedures/20/20-018-018.html)
Procedure Title	Cooling System
Update Reason	

Date	31-Jan-2007
Section	Section V - Specifications
Procedure Number	20-018-019 (/qs3/pubsys2/xml/en/procedures/20/20-018-019.html)
Procedure Title	Air Intake System
Update Reason	

Date	31-Jan-2007
Section	Section V - Specifications
Procedure Number	20-018-020 (/qs3/pubsys2/xml/en/procedures/20/20-018-020.html)
Procedure Title	Exhaust System
Update Reason	

Date	31-Jan-2007
Section	Section V - Specifications
Procedure Number	20-018-021 (/qs3/pubsys2/xml/en/procedures/20/20-018-021.html)
Procedure Title	Electrical System
Update Reason	

Date	31-Jan-2007
Section	Section V - Specifications
Procedure Number	20-018-022 (/qs3/pubsys2/xml/en/procedures/20/20-018-022.html)
Procedure Title	Compressed Air System
Update Reason	

Date	31-Jan-2007
Section	back
Procedure Number	4021592-backcover (/qs3/pubsys2/xml/en/manual/4021592/4021592-backcover.html)
Procedure Title	Backcover
Update Reason	
Date	19-Feb-2007
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-044 (/qs3/pubsys2/xml/en/procedures/20/20-007-044.html)
Procedure Title	Lubricating Oil Contamination
Update Reason	
Date	20-Feb-2007
Section	Section E - Engine Identification
Procedure Number	20-100-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-100-001-tr.html)
Procedure Title	Engine Identification
Update Reason	
Date	20-Feb-2007
Section	Section L - Service Literature
Procedure Number	20-205-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-205-001-tr.html)
Procedure Title	Additional Service Literature
Update Reason	
Date	20-Feb-2007
Section	Section V - Specifications
Procedure Number	20-018-015 (/qs3/pubsys2/xml/en/procedures/20/20-018-015.html)
Procedure Title	General Engine
Update Reason	

Date	02-Mar-2007
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-006-024-shopds (/qs3/pubsys2/xml/en/procedures/20/20-006-024-shopds.html)
Procedure Title	Fuel Supply Lines
Update Reason	
Date	02-Mar-2007
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-006-024-shopas (/qs3/pubsys2/xml/en/procedures/20/20-006-024-shopas.html)
Procedure Title	Fuel Supply Lines
Update Reason	
Date	02-Mar-2007
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-013-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-013-tr.html)
Procedure Title	Fuel Drain Lines
Update Reason	
Date	02-Mar-2007
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-024-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-024-tr.html)
Procedure Title	Fuel Supply Lines
Update Reason	
Date	08-May-2007
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-017-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-017-tr.html)
Procedure Title	Fuel Filter Head
Update Reason	

Date	05-Jun-2007
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-020-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-020-tr.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	
Date	28-Jun-2007
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-018-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	
Date	23-Jul-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	20-t00-004 (/qs3/pubsys2/xml/en/procedures/20/20-t00-004.html)
Procedure Title	Troubleshooting Overview
Update Reason	
Date	24-Jul-2007
Section	Section i - Introduction
Procedure Number	99-204-008 (/qs3/pubsys2/xml/en/procedures/99/99-204-008.html)
Procedure Title	General Cleaning Instructions
Update Reason	
Date	25-Jul-2007
Section	Section AS - Engine Assembly - Group 00
Procedure Number	28-008-029-shopas (/qs3/pubsys2/xml/en/procedures/28/28-008-029-shopas.html)
Procedure Title	Fan Drive Idler Arm Assembly
Update Reason	

Date	27-Jul-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t021-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t021-tr.html)
Procedure Title	Coolant Loss - Internal
Update Reason	
Date	22-Aug-2007
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	20-022-001_02 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_02.html)
Procedure Title	Service Tools
Update Reason	
Date	14-Sep-2007
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-003-006-shopas (/qs3/pubsys2/xml/en/procedures/20/20-003-006-shopas.html)
Procedure Title	Overhead Set
Update Reason	
Date	14-Sep-2007
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-006-tr.html)
Procedure Title	Overhead Set (OBC)
Update Reason	
Date	01-Nov-2007
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-022-001_06 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_06.html)
Procedure Title	Service Tools
Update Reason	

Date	05-Dec-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t027-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t027-tr.html)
Procedure Title	Crankcase Gases (Blowby) Excessive
Update Reason	
Date	07-Dec-2007
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	00-ttecm (/qs3/pubsys2/xml/en/procedures/00/00-ttecm.html)
Procedure Title	No Communication Troubleshooting Tree
Update Reason	
Date	25-Mar-2008
Section	Section F - Familiarization
Procedure Number	20-200-003-tr (/qs3/pubsys2/xml/en/procedures/20/20-200-003-tr.html)
Procedure Title	Flow Diagram, Cooling System
Update Reason	
Date	28-Apr-2008
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-001-tr.html)
Procedure Title	Crankcase Breather (External)
Update Reason	
Date	30-May-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	99-019-071 (/qs3/pubsys2/xml/en/procedures/99/99-019-071.html)
Procedure Title	OEM Wiring Harness
Update Reason	

Date	30-May-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	99-019-071 (/qs3/pubsys2/xml/en/procedures/99/99-019-071.html)
Procedure Title	OEM Wiring Harness
Update Reason	
Date	12-Jun-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-007-031-shopds (/qs3/pubsys2/xml/en/procedures/20/20-007-031-shopds.html)
Procedure Title	Lubricating Oil Pump
Update Reason	
Date	12-Jun-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-007-031-shopas (/qs3/pubsys2/xml/en/procedures/20/20-007-031-shopas.html)
Procedure Title	Lubricating Oil Pump
Update Reason	
Date	12-Jun-2008
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-031-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-031-tr.html)
Procedure Title	Lubricating Oil Pump
Update Reason	
Date	11-Jul-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-028-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-028-shopds.html)
Procedure Title	Cylinder Liner
Update Reason	

Date	11-Jul-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-028-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-028-shopas.html)
Procedure Title	Cylinder Liner
Update Reason	

Date	11-Jul-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-022-001_01 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_01.html)
Procedure Title	Service Tools
Update Reason	

Date	11-Jul-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-028-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	

Date	11-Aug-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-011-007-shopds (/qs3/pubsys2/xml/en/procedures/20/20-011-007-shopds.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	

Date	11-Aug-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-011-007-shopas (/qs3/pubsys2/xml/en/procedures/20/20-011-007-shopas.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	

Date	11-Aug-2008
Section	Section 11 - Exhaust System - Group 11
Procedure Number	20-011-007-tr (/qs3/pubsys2/xml/en/procedures/20/20-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	
Date	18-Aug-2008
Section	Section V - Specifications
Procedure Number	20-018-017 (/qs3/pubsys2/xml/en/procedures/20/20-018-017.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	14-Oct-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-043 (/qs3/pubsys2/xml/en/procedures/20/20-001-043.html)
Procedure Title	Piston
Update Reason	
Date	27-Oct-2008
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-073 (/qs3/pubsys2/xml/en/procedures/20/20-006-073.html)
Procedure Title	Delta Pressure Indicator
Update Reason	
Date	13-Nov-2008
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	00-016-010 (/qs3/pubsys2/xml/en/procedures/00/00-016-010.html)
Procedure Title	Engine Mounts
Update Reason	

Date	17-Nov-2008
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-010-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-010-tr.html)
Procedure Title	Camshaft Bushings
Update Reason	
Date	18-Nov-2008
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-016 (/qs3/pubsys2/xml/en/procedures/20/20-009-016.html)
Procedure Title	Hydraulic Pump Drive
Update Reason	
Date	17-Dec-2008
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-003-009-shopds (/qs3/pubsys2/xml/en/procedures/20/20-003-009-shopds.html)
Procedure Title	Rocker Lever Assembly
Update Reason	
Date	17-Dec-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-003-009-shopas (/qs3/pubsys2/xml/en/procedures/20/20-003-009-shopas.html)
Procedure Title	Rocker Lever Assembly
Update Reason	
Date	17-Dec-2008
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-009-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-009-tr.html)
Procedure Title	Rocker Lever Assembly
Update Reason	

Date	20-Jan-2009
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	13-t02-1001 (/qs3/pubsys2/xml/en/procedures/13/13-t02-1001.html)
Procedure Title	Engine Performance Troubleshooting Tree
Update Reason	
Date	30-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-014-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-014-tr.html)
Procedure Title	Connecting Rod
Update Reason	
Date	04-Feb-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-054-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-054-shopds.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	
Date	04-Feb-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-054-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-054-shopas.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	
Date	04-Feb-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-054-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	

Date	16-Feb-2009
Section	Section E - Engine Identification
Procedure Number	20-100-002-tr (/qs3/pubsys2/xml/en/procedures/20/20-100-002-tr.html)
Procedure Title	Engine Diagrams
Update Reason	
Date	16-Feb-2009
Section	Section F - Familiarization
Procedure Number	20-200-005-tr (/qs3/pubsys2/xml/en/procedures/20/20-200-005-tr.html)
Procedure Title	Flow Diagram, Exhaust System
Update Reason	
Date	19-Mar-2009
Section	Section F - Familiarization
Procedure Number	20-000-999 (/qs3/pubsys2/xml/en/procedures/20/20-000-999.html)
Procedure Title	Complete Engine - Overview
Update Reason	
Date	19-Mar-2009
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-045 (/qs3/pubsys2/xml/en/procedures/20/20-005-045.html)
Procedure Title	Fuel Lift Pump
Update Reason	
Date	19-Mar-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-030-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-030-tr.html)
Procedure Title	Fan Drive Idler Pulley Assembly
Update Reason	

Date	19-Mar-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-045 (/qs3/pubsys2/xml/en/procedures/20/20-010-045.html)
Procedure Title	Turbocharger Oil Drain Line
Update Reason	
Date	19-Mar-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-046 (/qs3/pubsys2/xml/en/procedures/20/20-010-046.html)
Procedure Title	Turbocharger Oil Supply Line
Update Reason	
Date	19-Mar-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-129 (/qs3/pubsys2/xml/en/procedures/20/20-010-129.html)
Procedure Title	Aftercooler Heat Shield
Update Reason	
Date	19-Mar-2009
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-013 (/qs3/pubsys2/xml/en/procedures/20/20-012-013.html)
Procedure Title	Air Compressor Unloader and Valve Assembly
Update Reason	
Date	19-Mar-2009
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	20-016-004 (/qs3/pubsys2/xml/en/procedures/20/20-016-004.html)
Procedure Title	Flexplate
Update Reason	

Date	26-Mar-2009
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	105-t02-1005a (/qs3/pubsys2/xml/en/procedures/105/105-t02-1005a.html)
Procedure Title	Vibration Excessive
Update Reason	
Date	07-Apr-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-008-002-shopds (/qs3/pubsys2/xml/en/procedures/20/20-008-002-shopds.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	
Date	07-Apr-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-008-002-shopas (/qs3/pubsys2/xml/en/procedures/20/20-008-002-shopas.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	
Date	07-Apr-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-002-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-002-tr.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	
Date	08-Apr-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-006-011-shopds (/qs3/pubsys2/xml/en/procedures/20/20-006-011-shopds.html)
Procedure Title	Fuel Filter, Remote Mounted
Update Reason	

Date	08-Apr-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-006-011-shopas (/qs3/pubsys2/xml/en/procedures/20/20-006-011-shopas.html)
Procedure Title	Fuel Filter, Remote Mounted
Update Reason	
Date	08-Apr-2009
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-011-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-011-tr.html)
Procedure Title	Fuel Filter, Remote Mounted
Update Reason	
Date	08-Apr-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-037 (/qs3/pubsys2/xml/en/procedures/20/20-007-037.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	15-Apr-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-010-037-shopds (/qs3/pubsys2/xml/en/procedures/20/20-010-037-shopds.html)
Procedure Title	Turbocharger, Water Cooled
Update Reason	
Date	15-Apr-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-010-037-shopas (/qs3/pubsys2/xml/en/procedures/20/20-010-037-shopas.html)
Procedure Title	Turbocharger, Water Cooled
Update Reason	

Date	15-Apr-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-037-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-037-tr.html)
Procedure Title	Turbocharger, Water Cooled
Update Reason	
Date	20-May-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-067-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-067-tr.html)
Procedure Title	Eliminator Filter
Update Reason	
Date	22-May-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-024-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-024-tr.html)
Procedure Title	Air Leaks, Air Intake and Exhaust Systems
Update Reason	
Date	25-Jun-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-001-tr (/qs3/pubsys2/xml/en/procedures/99/99-t00-001-tr.html)
Procedure Title	Troubleshooting Procedures and Techniques
Update Reason	
Date	01-Jul-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-057-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-057-tr.html)
Procedure Title	Intake Manifold Pressure
Update Reason	

Date	03-Jul-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-048-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-048-tr.html)
Procedure Title	Turbocharger Support Bracket
Update Reason	
Date	13-Jul-2009
Section	Section F - Familiarization
Procedure Number	20-200-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-200-001-tr.html)
Procedure Title	Flow Diagram, Fuel System
Update Reason	
Date	22-Jul-2009
Section	Section L - Service Literature
Procedure Number	99-205-004 (/qs3/pubsys2/xml/en/procedures/99/99-205-004.html)
Procedure Title	Cummins Customized Parts Catalog
Update Reason	
Date	27-Jul-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-010-033-shopds (/qs3/pubsys2/xml/en/procedures/20/20-010-033-shopds.html)
Procedure Title	Turbocharger
Update Reason	
Date	27-Jul-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-010-033-shopas (/qs3/pubsys2/xml/en/procedures/20/20-010-033-shopas.html)
Procedure Title	Turbocharger
Update Reason	

Date	27-Jul-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-033-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	
Date	07-Aug-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-001 (/qs3/pubsys2/xml/en/procedures/20/20-008-001.html)
Procedure Title	Belt Guard
Update Reason	
Date	10-Sep-2009
Section	Section i - Introduction
Procedure Number	99-204-002-shopds (/qs3/pubsys2/xml/en/procedures/99/99-204-002-shopds.html)
Procedure Title	About the Manual
Update Reason	
Date	10-Sep-2009
Section	Section i - Introduction
Procedure Number	99-204-003-shopds (/qs3/pubsys2/xml/en/procedures/99/99-204-003-shopds.html)
Procedure Title	How to Use the Manual
Update Reason	
Date	24-Sep-2009
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-011-008-shopds (/qs3/pubsys2/xml/en/procedures/20/20-011-008-shopds.html)
Procedure Title	Exhaust Manifold, Wet
Update Reason	

Date	24-Sep-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-011-008-shopas (/qs3/pubsys2/xml/en/procedures/20/20-011-008-shopas.html)
Procedure Title	Exhaust Manifold, Wet
Update Reason	
Date	24-Sep-2009
Section	Section 11 - Exhaust System - Group 11
Procedure Number	20-011-008-tr (/qs3/pubsys2/xml/en/procedures/20/20-011-008-tr.html)
Procedure Title	Exhaust Manifold, Wet
Update Reason	
Date	08-Oct-2009
Section	Section i - Introduction
Procedure Number	99-204-007-tr (/qs3/pubsys2/xml/en/procedures/99/99-204-007-tr.html)
Procedure Title	General Repair Instructions
Update Reason	
Date	20-Oct-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-017 (/qs3/pubsys2/xml/en/procedures/20/20-007-017.html)
Procedure Title	Lubricating Oil Filter Head (Remote Moutned)
Update Reason	
Date	21-Jan-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-001-016-shopds (/qs3/pubsys2/xml/en/procedures/20/20-001-016-shopds.html)
Procedure Title	Crankshaft
Update Reason	

Date	21-Jan-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-001-016-shopas (/qs3/pubsys2/xml/en/procedures/20/20-001-016-shopas.html)
Procedure Title	Crankshaft
Update Reason	
Date	25-Jan-2010
Section	Section i - Introduction
Procedure Number	99-204-006-tr (/qs3/pubsys2/xml/en/procedures/99/99-204-006-tr.html)
Procedure Title	General Safety Instructions
Update Reason	
Date	25-Jan-2010
Section	Section V - Specifications
Procedure Number	99-018-005 (/qs3/pubsys2/xml/en/procedures/99/99-018-005.html)
Procedure Title	Drive Belt Tension
Update Reason	
Date	25-Jan-2010
Section	Section V - Specifications
Procedure Number	99-018-009 (/qs3/pubsys2/xml/en/procedures/99/99-018-009.html)
Procedure Title	Capscrew Markings and Torque Values
Update Reason	
Date	05-Feb-2010
Section	front
Procedure Number	4021592-titlepage (/qs3/pubsys2/xml/en/manual/4021592/4021592-titlepage.html)
Procedure Title	Titlepage
Update Reason	

Date	11-Feb-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-002-004-shopds (/qs3/pubsys2/xml/en/procedures/20/20-002-004-shopds.html)
Procedure Title	Cylinder Head
Update Reason	
Date	11-Feb-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-002-004-shopas (/qs3/pubsys2/xml/en/procedures/20/20-002-004-shopas.html)
Procedure Title	Cylinder Head
Update Reason	
Date	11-Feb-2010
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	20-002-004-tr (/qs3/pubsys2/xml/en/procedures/20/20-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	
Date	18-Feb-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-009-001-shopds (/qs3/pubsys2/xml/en/procedures/20/20-009-001-shopds.html)
Procedure Title	Accessory Drive
Update Reason	
Date	18-Feb-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-009-001-shopas (/qs3/pubsys2/xml/en/procedures/20/20-009-001-shopas.html)
Procedure Title	Accessory Drive
Update Reason	

Date	01-Mar-2010
Section	Section F - Familiarization
Procedure Number	20-008-999-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-999-tr.html)
Procedure Title	Cooling System - Overview
Update Reason	
Date	01-Mar-2010
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t102-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t102-tr.html)
Procedure Title	Lubricating Oil Consumption Excessive
Update Reason	
Date	24-Mar-2010
Section	Section i - Introduction
Procedure Number	99-204-009 (/qs3/pubsys2/xml/en/procedures/99/99-204-009.html)
Procedure Title	Acronyms and Abbreviations
Update Reason	
Date	14-Apr-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-005-016-shopds (/qs3/pubsys2/xml/en/procedures/20/20-005-016-shopds.html)
Procedure Title	Fuel Pump
Update Reason	
Date	14-Apr-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-005-016-shopas (/qs3/pubsys2/xml/en/procedures/20/20-005-016-shopas.html)
Procedure Title	Fuel Pump
Update Reason	

Date	14-Apr-2010
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	
Date	05-May-2010
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-051-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	
Date	11-May-2010
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-009-001-tr.html)
Procedure Title	Accessory Drive
Update Reason	
Date	17-May-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-047 (/qs3/pubsys2/xml/en/procedures/20/20-001-047.html)
Procedure Title	Piston Rings
Update Reason	
Date	19-May-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	

Date	27-May-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-006-026-shopds (/qs3/pubsys2/xml/en/procedures/20/20-006-026-shopds.html)
Procedure Title	Injector
Update Reason	

Date	27-May-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-006-026-shopas (/qs3/pubsys2/xml/en/procedures/20/20-006-026-shopas.html)
Procedure Title	Injector
Update Reason	

Date	27-May-2010
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-026-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-026-tr.html)
Procedure Title	Injector
Update Reason	

Date	23-Jun-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	20-006-015-shopds (/qs3/pubsys2/xml/en/procedures/20/20-006-015-shopds.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	

Date	23-Jun-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-006-015-shopas (/qs3/pubsys2/xml/en/procedures/20/20-006-015-shopas.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	

Date	23-Jun-2010
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-005 (/qs3/pubsys2/xml/en/procedures/20/20-001-005.html)
Procedure Title	Bearings, Connecting Rod
Update Reason	
Date	23-Jun-2010
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-015-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-015-tr.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	
Date	17-Sep-2010
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-062-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Update to the Clean and Inspect for Reuse/Install Sections for Rail/Industrial Applications.
Date	23-Jun-2010
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-026-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-026-tr.html)
Procedure Title	Injector
Update Reason	Updated Initial Check section with new service tool.

Date	11-Feb-2010
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	20-002-004-tr (/qs3/pubsys2/xml/en/procedures/20/20-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Updated procedure with revised Vacuum Test section.
Date	11-Nov-2010
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-014-tr (/qs3/pubsys2/xml/en/procedures/20/20-012-014-tr.html)
Procedure Title	Air Compressor
Update Reason	Updated procedure to include new mounting baracket.
Date	23-Jun-2010
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-022-001_06 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_06.html)
Procedure Title	Service Tools
Update Reason	Updated service tools with injector tester.
Date	29-Apr-2003
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-033-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Updated Initial Check and Measure sections with HX83 specifications.

Date	19-Nov-2010
Section	Section 01- Cylinder Block - Group 01
Procedure Number	20-001-024-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-024-tr.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	Added service tool part number and updated wear sleeve instructions in the Remove section.
Date	06-Jan-2011
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-026-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-026-tr.html)
Procedure Title	Injector
Update Reason	Added High-Pressure Injector Return Flow Test and High-Pressure Injector Return Flow Isolation Test Steps.
Date	06-Jan-2011
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-061 (/qs3/pubsys2/xml/en/procedures/20/20-006-061.html)
Procedure Title	Fuel Pressure Relief Valve
Update Reason	Added Fuel Pressure Relief Valve Return Flow Test Step.
Date	07-Jan-2011
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-005-tr (/qs3/pubsys2/xml/en/procedures/20/20-013-005-tr.html)
Procedure Title	Drive Belt, Alternator
Update Reason	Added information for captive fasteners on belt guard.

Date	07-Jan-2011
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-001 (/qs3/pubsys2/xml/en/procedures/20/20-008-001.html)
Procedure Title	Belt Guard
Update Reason	Added information for captive fasteners on belt guard.
Date	10-Mar-2011
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-022-001_06 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_06.html)
Procedure Title	Service Tools
Update Reason	Added fuel system leak test service tool kit to procedure.
Date	25-Mar-2011
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-003 (/qs3/pubsys2/xml/en/procedures/20/20-006-003.html)
Procedure Title	Air in Fuel
Update Reason	Updated procedure with electronically actuated injector.
Date	04-May-2011
Section	Section AS - Engine Assembly - Group 00
Procedure Number	20-003-011-shopas (/qs3/pubsys2/xml/en/procedures/20/20-003-011-shopas.html)
Procedure Title	Rocker Lever Cover
Update Reason	Add dust seal installation to rocker lever top cover.

Date	04-May-2011
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-011-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-011-tr.html)
Procedure Title	Rocker Lever Cover
Update Reason	Add dust seal installation to rocker lever top cover.

Date	01-Jun-2011
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Adde General Information Section.

Date	02-Jun-2011
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	13-t02-1001 (/qs3/pubsys2/xml/en/procedures/13/13-t02-1001.html)
Procedure Title	Engine Performance Troubleshooting Tree
Update Reason	Multiple step updates.

Date	06-Jun-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-026-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-026-tr.html)
Procedure Title	Cylinder Block
Update Reason	Added cylinder block height and main bearing bore alignment to procedure and specifications.

Date	11-Jul-2011
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-041-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-041-tr.html)
Procedure Title	Turbocharger Coolant Hoses
Update Reason	Added checks for fretting on lines and new male union for the oil supply line.
Date	11-Jul-2011
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-046 (/qs3/pubsys2/xml/en/procedures/20/20-010-046.html)
Procedure Title	Turbocharger Oil Supply Line
Update Reason	Added checks for fretting on lines and new male union for the oil supply line.
Date	14-Sep-2011
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-009-001-tr.html)
Procedure Title	Accessory Drive
Update Reason	Updated to reflect mechanically actuated injectors only.
Date	14-Sep-2011
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-011 (/qs3/pubsys2/xml/en/procedures/20/20-009-011.html)
Procedure Title	Fuel Pump Drive
Update Reason	Updated to reflect electronically actuated injectors only.

Date	22-sep-2011
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-001-tr.html)
Procedure Title	Crankcase Breather (External)
Update Reason	Remove step: After removing the breather cover from the underside of the rocker lever cover by removing the three spring nuts. Discard the spring nuts.
Date	28-Sep-2011
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-087-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-087-tr.html)
Procedure Title	Cooling Fan Belt Tensioner
Update Reason	Added procedure to outline and manual.
Date	25-Oct-2011
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Update procedure links in the Clean and Inspect for Reuse section.
Date	25-Oct-2011
Section	Section TS - Troubleshooting Symptoms
Procedure Number	4021592-t108-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t108-tr.html)
Procedure Title	Lubricating or Transmission Oil in the Coolant
Update Reason	Revised turbocharger bearing housing is cracked or porous step.

Date	14-Nov-2011
Section	Section 5 - Fuel System - Group 5
Procedure Number	20-005-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Revised fuel rail pressure sensor torque value and added note.
Date	05-Dec-2011
Section	Section 08 - Cooling System
Procedure Number	20-008-062-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	Assemble Step, revised text to install the oil seal with the stepped lip facing down towards the impeller.
Date	19-Dec-2011
Section	Section 3 - Rocker Levers
Procedure Number	20-003-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-006-tr.html)
Procedure Title	Overhead Set (OBC)
Update Reason	Added: Use service tool Part Number 3163171 (intake) or Part Number 3163172 (exhaust).
Date	20-Dec-2011
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	20-002-004-tr (/qs3/pubsys2/xml/en/procedures/20/20-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Updated procedure with revised valve guide height in Assembly Step - Mechanically Actuated Injectors.

Date	20-Dec-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-027 (/qs3/pubsys2/xml/en/procedures/20/20-001-027.html)
Procedure Title	Cylinder Block and Liner Seats
Update Reason	Edited to include information concerning oversize block bores.
Date	20-Dec-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-028-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Edited to include information concerning oversize cylinder liners.
Date	10-Jan-2012
Section	Section F - Familiarization
Procedure Number	20-200-002 (/qs3/pubsys2/xml/en/procedures/20/20-200-002.html)
Procedure Title	Flow Diagram, Lubricating Oil System
Update Reason	Updated procedure to include a flow diagram for the pre-lube pump.
Date	18-Jan-2012
Section	Section 5 - Fuel System
Procedure Number	20-005-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Assemble Step, removed stepblock concerning install fuel pump support bracket and attaching the fuel pump support bracket.

Date	01-Feb-2012
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-006-tr.html)
Procedure Title	Overhead Set (OBD)
Update Reason	Increased overhead set torque values for valves and injector.
Date	26-Apr-2012
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	20-002-004-tr (/qs3/pubsys2/xml/en/procedures/20/20-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Added valve designation in the Grind Step and drop gauge testing and repair of valve guide in Assembly Step.
Date	30-Apr-2012
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Added information to General Information section about relieving rail pressure before removing parts from the fuel pump.
Date	30-May-2012
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-075-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-075-tr.html)
Procedure Title	Fuel Filter (Stage 1)
Update Reason	Updated graphics to show components more accurately.

Date	30-May-2012
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-076-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-076-tr.html)
Procedure Title	Fuel Filter (Stage 2)
Update Reason	Updated graphics to show components more accurately.

Date	27-Jun-2012
Section	Section 6 - Injectors and Fuel Lines
Procedure Number	20-006-025-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-025-tr.html)
Procedure Title	Static Injection Timing
Update Reason	Changed Control Part List (CPL) Manual, Bulletin to 4021328, added refer to Procedure 99-850-013.

Date	27-Jun-2012
Section	Section 1 - Cylinder Block
Procedure Number	20-001-054-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Replaced piston ring compressor tool, Part Number 3375342 with 4918898.

Date	27-Jun-2012
Section	Section 1 - Cylinder Block
Procedure Number	20-022_001_ (/qs3/pubsys2/xml/en/procedures/20/20-022_001_.html)
Procedure Title	Service Tools
Update Reason	Replaced piston ring compressor tool, Part Number 3375342 with 4918898.

Date	25-Jun-2012
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-028-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Updated the Remove step to add instruction that liner seals must be discarded if removed from the liner.
Date	20-Aug-2012
Section	Section TS - Troubleshooting System
Procedure Number	4021592-t102-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t102-tr.html)
Procedure Title	Lubricating Oil Consumption Excessive
Update Reason	Changed first step to include inspection of OEM components for external oil leaks.
Date	23-Oct-2012
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	123-t02-1001 (/qs3/pubsys2/xml/en/procedures/123/123-t02-1001.html)
Procedure Title	Engine Performance Troubleshooting Tree - CM2150 Electronic Control System
Update Reason	Added this procedure to the manual.
Date	24-Oct-2012
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-011-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-011-tr.html)
Procedure Title	Rocker Lever Cover
Update Reason	In the electronically actuated injector section, a statement is added to discard the o-ring after removing it from the rocker lever cover plate.

Date	27-Nov-2012
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-061 (/qs3/pubsys2/xml/en/procedures/20/20-006-061.html)
Procedure Title	Fuel Pressure Relief Valve
Update Reason	Revised the Fuel Pressure Relief Valve Return Flow Test step.
Date	06-Jan-2013
Section	Section 6 - Injectors - Group 06
Procedure Number	20-022-001_06 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_06.html)
Procedure Title	Fuel System Tester
Update Reason	Added Service Tool Part Number 4918612.
Date	22-Jan-2013
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-027-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-027-tr.html)
Procedure Title	Lubricating Oil Pan Adapter
Update Reason	Added steps to the Installation section and defined Preferred Method and Optional Method of installation.
Date	05-Apr-2013
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-006 (/qs3/pubsys2/xml/en/procedures/20/20-010-006.html)
Procedure Title	Aftercooler Coolant Tube
Update Reason	Revised Install and Remove Steps for the coolant inlet transfer connection.

Date	19-Apr-2013
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-020-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-020-tr.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	Revised the Fuel Inlet Restriction to included maximum OEM restriction at Stage 1 inlet.
Date	22-Apr-2013
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Added Flush section to procedure.
Date	28-June-2013
Section	Section 3 - Rocker Levers
Procedure Number	20-003-013-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-013-tr.html)
Procedure Title	Rocker Lever Housing
Update Reason	Install Step: Added statement, checking for capscrews for damage. Change capscrew torque to 122 N.m [90 ft-lb].
Date	06-Aug-2013
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-020-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-020-tr.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	Revised the Maximum Fuel Inlet Restriction values for Stage 1 and Stage 2 filters.

Date	06-Aug-2013
Section	Section V - Maintenance Guidelines
Procedure Number	20-018-024 (/qs3/pubsys2/xml/en/procedures/20/20-018-024.html)
Procedure Title	Cummins®/Fleetguard® Filter Specifications
Update Reason	Updated filter specifications and part numbers.

Date	13-Aug-2013
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-075-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-075-tr.html)
Procedure Title	Fuel Filter (Stage 1)
Update Reason	Added information and illustration for FH239 fuel filter.

Date	26-Aug-2013
Section	Section 14 - Engine Testing - Group 14
Procedure Number	00-014-012 (/qs3/pubsys2/xml/en/procedures/00/00-014-012.html)
Procedure Title	Engine Compression
Update Reason	Updated Preparatory Step and Finishing Step procedure links.

Date	28-Aug-2013
Section	Section V - Maintenance Guidelines
Procedure Number	20-018-016 (/qs3/pubsys2/xml/en/procedures/20/20-018-016.html)
Procedure Title	Fuel System
Update Reason	Updated fuel inlet maximum restriction.

Date	05-Nov-2013
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	102-016-008 (/qs3/pubsys2/xml/en/procedures/102/102-016-008.html)
Procedure Title	Flywheel Ring Gear
Update Reason	Updated procedure for improved clarity and safety.
Date	08-Jan-2014
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-020-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-020-tr.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	Correction to the Initial Check section.
Date	14-Jan-2014
Section	Section TS - Troubleshooting System
Procedure Number	4021592-t102-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t102-tr.html)
Procedure Title	Lubricating Oil Consumption Excessive
Update Reason	Added step three to TS tree. Verifying original equipment manufacturer (OEM) lubricating oil system components.
Date	31-Jan-2014
Section	Section E - Engine and System Identification
Procedure Number	20-100-002-tr (/qs3/pubsys2/xml/en/procedures/20/20-100-002-tr.html)
Procedure Title	Engine Diagrams
Update Reason	Corrected errors under "Left View".

Date	11-Feb-2013
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-015-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-015-tr.html)
Procedure Title	Coolant Thermostat Housing Support
Update Reason	Added information about spacers used with cast iron gear cover.
Date	04-Mar-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-069-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-069-tr.html)
Procedure Title	Crankshaft Tone Wheel
Update Reason	Added inspection and install steps.
Date	28-Apr-2014
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	20-002-022 (/qs3/pubsys2/xml/en/procedures/20/20-002-022.html)
Procedure Title	Injector Protrusion
Update Reason	Revised sections in the Injector Protrusion procedure.
Date	29-Apr-2014
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-026-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-026-tr.html)
Procedure Title	Injector
Update Reason	Revision of Inspect for Reuse section, and install section with requirements to replace the injector sealing ring (mechanically actuated injector only) if removed.

Date	20-Aug-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-054-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Added bolt stretch measurements for reuse.
Date	03-Sep-2014
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-011-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-011-tr.html)
Procedure Title	Rocker Lever Cover
Update Reason	Added instructions to pry evenly on the rocker lever cover.
Date	08-Oct-2014
Section	Section TS - Troubleshooting Symptoms - Group t00
Procedure Number	4021592-t107-tr (/qs3/pubsys2/xml/en/manual/4021592/4021592-t107-tr.html)
Procedure Title	Lubricating Oil Temperature Above Specification
Update Reason	Updated TS tree with correct wording for field service on lubricating oil above or below specification.
Date	16-Oct-2014
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-029 (/qs3/pubsys2/xml/en/procedures/20/20-007-029.html)
Procedure Title	Lubricating Oil Pressure Regulator (Main Rifle)
Update Reason	Updated service tool number from Part Number 3375055 to Part Number 5299024.

Date	20-Oct-2014
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-022-001_07 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_07.html)
Procedure Title	Service Tools
Update Reason	Updated service tool number from Part Number 3375055 to Part Number 5299024.
Date	04-Dec-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-026 (/qs3/pubsys2/xml/en/procedures/20/20-001-026.html)
Procedure Title	Cylinder Block
Update Reason	Updated the Inspect for Reuse step to add specifications for the main bearing bore inside diameter measurement.
Date	07-Jan-2015
Section	Section V - Maintenance Specifications
Procedure Number	20-018-024 (/qs3/pubsys2/xml/en/procedures/20/20-018-024.html)
Procedure Title	Cummins/Fleetguard®/Nelson Filter Specifications
Update Reason	A new Sea Pro filter part number is added to the Cummins®/Fleetguard® Filter Specifications procedure.
Date	27-Feb-2015
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-029-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-029-tr.html)
Procedure Title	Gear Cover Spacer Plate
Update Reason	Added note in the Install step for the use of a steel core gasket.

Date	07-Apr-2015
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-018-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	Added directions to allow the coolant to cool before draining.

Date	03-Aug-2015
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-027-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-027-tr.html)
Procedure Title	Lubricating Oil Pan Adapter
Update Reason	Added direction on the proper instalation of the RTV sealant and torque sequence.

Date	13-Aug-2015
Section	Section 1 - Cylinder Block
Procedure Number	20-001-028-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Updated to new geometry for standard cylinder liner sizes.

Date	20-Aug-2015
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-009-001-tr.html)
Procedure Title	Accessory Drive
Update Reason	Corrected inconsistencies in verbiage used and torque specifications.

Date	20-Aug-2015
Section	Section 11 - Exhaust System - Group 11
Procedure Number	20-011-007-tr (/qs3/pubsys2/xml/en/procedures/20/20-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	Added Cautions and notes for exhaust lock plate tabs.
Date	24-Aug-2015
Section	Section 6 - Injectors and Fuel Lines
Procedure Number	20-006-026-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-026-tr.html)
Procedure Title	Injector
Update Reason	Revised the color of the o-ring in the Install step.
Date	24-Aug-2015
Section	Section 0 - Complete Engine - Group 00
Procedure Number	99-000-005-tr (/qs3/pubsys2/xml/en/procedures/99/99-000-005-tr.html)
Procedure Title	Engine Steam Cleaning
Update Reason	Added to outline.
Date	25-Aug-2015
Section	Section 10 - Air Intake System
Procedure Number	20-010-033-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Revised mechanically and electronically acutated injectors engines, turbocharger capscrew torque.

Date	27-Oct-2015
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-014-008 (/qs3/pubsys2/xml/en/procedures/20/20-014-008.html)
Procedure Title	Engine Testing (In Chassis)
Update Reason	Procedure has been commonized for all high horsepower engine families.

Date	12-Jan-2016
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-010 (/qs3/pubsys2/xml/en/procedures/20/20-003-010.html)
Procedure Title	Rocker Lever Bushings
Update Reason	Updated the art and instructions as to the orientation of the lever assembly bushing installation.

Date	13-Jan-2016
Section	Section L - Service Literature
Procedure Number	20-205-001-tr (/qs3/pubsys2/xml/en/procedures/20/20-205-001-tr.html)
Procedure Title	Additional Service Literature
Update Reason	Procedure was updated to add CM2150 publications to this listing, remove any duplicates & obsolescences, and correct other errors.

Date	13-Jan-2016
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-045 (/qs3/pubsys2/xml/en/procedures/20/20-005-045.html)
Procedure Title	Fuel Lift Pump
Update Reason	The procedure was updated to include a new on-engine mounted fuel lift pump.

Date	30-May-2016
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-075-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-075-tr.html)
Procedure Title	Fuel Filter (Stage 1)
Update Reason	The procedure was updated to include instructions on the new FH240 Series Sea Pro® units.

Date	22-Jan-2016
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-051-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	Updated pressure relief warning in Leak Test section for C3 fuel systems.

Date	15-Sep-2015
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-008-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-008-tr.html)
Procedure Title	Camshaft
Update Reason	Updated Remove and Install steps to accommodate new service tool part number for MCRS engines.

Date	07-Jun-2016
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-007-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-007-tr.html)
Procedure Title	Lubricating Oil Cooler Element
Update Reason	Changes have been made to the cleaning recommendations for oil cooler elements.

Date	11-Aug-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-054-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Removed rod bolt stretch tool instructions as this tool does not apply to this engine.

Date	08-Sep-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-036-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-036-tr.html)
Procedure Title	Idler Gear, Camshaft
Update Reason	Updates to include the specifications of the outer diameter of the Idler Gear Camshaft.

Date	08-Sep-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-039-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-039-tr.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	Updates to include the specifications of the outer diameter of the Idler Gear Shaft Hydraulic pump.

Date	08-Sep-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-040-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-040-tr.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	Updates to include the specifications of the outer diameter of the Idler Gear Shaft Water pump.

Date	26-Sep-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-028-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Updated specifications for liner flange diameters for electronically actuated injectors.
Date	27-Oct-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-006-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Updated main bearing thickness specifications.
Date	05-Dec-2016
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	00-ttecm (/qs3/pubsys2/xml/en/procedures/00/00-ttecm.html)
Procedure Title	ECM - No Communication Troubleshooting Tree
Update Reason	Modified Steps 2, 6, 9 and 11 and added information for new INLINE™ 7 data link.
Date	24-Mar-2017
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-002-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-002-tr.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	Updated to include an inspect and re-use guideline for the drive belt tensioner.

Date	06-Mar-2017
Section	Section F - Familiarization - Group 209
Procedure Number	20-009-999 (/qs3/pubsys2/xml/en/procedures/20/20-009-999.html)
Procedure Title	Drive Units - Overview
Update Reason	Updated capscrew on fuel pump coupling oil drilling.

Date	24-May-2017
Section	Section 1 - Cylinder Block
Procedure Number	20-001-031-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-031-tr.html)
Procedure Title	Gear Cover, Front
Update Reason	Added Grade 5 and Grade 8 Capscrew torque.

Date	28-Aug-2017
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-012 (/qs3/pubsys2/xml/en/procedures/20/20-006-012.html)
Procedure Title	Fuel Drain Line Restriction
Update Reason	Included the information for the Fuel Drain Line Restriction for the electronically actuated injectors.

Date	21-Sep-2017
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-017 (/qs3/pubsys2/xml/en/procedures/20/20-007-017.html)
Procedure Title	Lubricating Oil Filter Head (Remote Mounted)
Update Reason	Updated the Install Step for new gasket.

Date	27-Oct-2017
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	Revised Clean & Inspect step, changed "gear pumps" to "pump gears".

Date	10-Nov-2017
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-006-tr.html)
Procedure Title	Overhead Set (OBC)
Update Reason	Updated instructions to include MCRS adjustment screw information and torque values.

Date	09-Mar-2018
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-043 (/qs3/pubsys2/xml/en/procedures/20/20-001-043.html)
Procedure Title	Piston
Update Reason	Added the General Information Step and removed note from Preparatory Step.

Date	14-Mar-2018
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-037-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-037-tr.html)
Procedure Title	Turbocharger, Water-Cooled
Update Reason	Added 'Remove' and 'Install' steps.

Date	18-May-2018
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-026-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-026-tr.html)
Procedure Title	Injector
Update Reason	Updated procedure to replace the current graphic for the injector return flow test with the correct graphic.
Date	22-Jun-2018
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	20-013-005-tr (/qs3/pubsys2/xml/en/procedures/20/20-013-005-tr.html)
Procedure Title	Charging System Alternator Drive Belt
Update Reason	Revised belt tension measurements.
Date	19-Jul-2018
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-050 (/qs3/pubsys2/xml/en/procedures/20/20-007-050.html)
Procedure Title	Cylinder Smokes (Blue Smoke)
Update Reason	Added direction for the manifold to cool before removing.
Date	20-Jul-2018
Section	Section 9 - Drive Units - Group 09
Procedure Number	20-009-031 (/qs3/pubsys2/xml/en/procedures/20/20-009-031.html)
Procedure Title	Crankcase Breather Adapter
Update Reason	Revised to include measurements of the gear's inner and shaft outer diameter.

Date	03-Oct-2018
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	20-022-001_16 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_16.html)
Procedure Title	Service Tools
Update Reason	Revised information for the Engine Lifting Hooks.

Date	17-Oct-2018
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-039-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-039-tr.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	Updated hydraulic pump plug bolt size.

Date	13-Nov-2018
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-025-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-025-tr.html)
Procedure Title	Static Injection Timing
Update Reason	Procedure updated to include worksheets A, B, and C to calculate the offset camshaft key.

Date	14-Nov-2018
Section	Section 1 - Cylinder Block
Procedure Number	20-001-039-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-039-tr.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	Added: Measure the hydraulic pump idler block bore diameter table.

Date	14-Nov-2018
Section	Section 1 - Cylinder Block
Procedure Number	20-001-040-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-040-tr.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	Added: Measure the hydraulic pump idler block bore diameter table.
Date	16-Nov-2018
Section	Section 1 - Cylinder Block
Procedure Number	20-001-036-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-036-tr.html)
Procedure Title	Idler Gear, Camshaft
Update Reason	Added: Measure the water pump idler block bore diameter table.
Date	21-Nov-2018
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-050 (/qs3/pubsys2/xml/en/procedures/20/20-007-050.html)
Procedure Title	Cylinder Smokes (Blue Smoke)
Update Reason	Procedure was updated to make it clear not to run the engine with the exhaust manual OFF.
Date	07-Dec-2018
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	123-t02-1001 (/qs3/pubsys2/xml/en/procedures/123/123-t02-1001.html)
Procedure Title	Engine Performance Troubleshooting Tree - CM2150 Electronic Control System
Update Reason	Removed 'Check fuel filter head check ball for proper operation' step.

Date	18-Jan-2019
Section	Section V - Specifications
Procedure Number	20-018-017 (/qs3/pubsys2/xml/en/procedures/20/20-018-017.html)
Procedure Title	Lubricating Oil System
Update Reason	Added specifications for Centrifuge Filter.
Date	23-Apr-2018
Section	Section 7 - Lubricating Oil System
Procedure Number	20-007-067-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-067-tr.html)
Procedure Title	Eliminator™ Filter
Update Reason	Updated to replace eliminator motor instead of repair.
Date	16-Apr-2019
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-039-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-039-tr.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	Removed the word "Bushing" from the "Idler Gear Bushing Inside Diameter" table in the Clean and Inspect for Reuse step.
Date	16-Apr-2019
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-040-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-040-tr.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	Removed the word "Bushing" from the "Idler Gear Bushing Inside Diameter" table in the Clean and Inspect for Reuse step.

Date	17-Apr-2019
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-036-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-036-tr.html)
Procedure Title	Idler Gear, Camshaft
Update Reason	Removed the word "Bushing" from the "Idler Gear Bushing Inside Diameter" table in the Clean and Inspect for Reuse step.

Date	22-Apr-2019
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-047 (/qs3/pubsys2/xml/en/procedures/20/20-001-047.html)
Procedure Title	Piston Rings
Update Reason	Updated Piston Ring Gap specifications.

Date	09-Jul-2019
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-052-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-052-tr.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	Revised graphic in Wobble Check step.

Date	03-Feb-2020
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-022-001_14 (/qs3/pubsys2/xml/en/procedures/20/20-022-001_14.html)
Procedure Title	Service Tools
Update Reason	Added cylinder diagnostic tool to Service Tools table.

Date	06-Feb-2020
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-029-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-029-tr.html)
Procedure Title	Gear Cover Spacer Plate
Update Reason	Added Loctite™ 577 Part Number 4919202 to Service Tools list. Added note to use Loctite™ 577 in the Install step of the procedure.
Date	20-Mar-2020
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Corrected listed specifications for the Rod Bearing Journal Outside Diameter, Main Bearing Journal Outside Diameter, and Thrust Distance.
Date	25-Mar-2020
Section	Section 14 - Engine Testing - Group 14
Procedure Number	00-014-012 (/qs3/pubsys2/xml/en/procedures/00/00-014-012.html)
Procedure Title	Engine Compression
Update Reason	Added additional information throughout procedure.
Date	25-Mar-2020
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	20-012-020 (/qs3/pubsys2/xml/en/procedures/20/20-012-020.html)
Procedure Title	Air Compressor (Oil Carryover)
Update Reason	Reconfigured procedure to commonize it.

Date	14-Jul-2020
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-014-002-tr (/qs3/pubsys2/xml/en/procedures/20/20-014-002-tr.html)
Procedure Title	Engine Testing (Chassis Dynamometer)
Update Reason	Added tri-axles and drive axles only.
Date	09-Sep-2020
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-051-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	Added note to complete a fuel system flush if the fuel line on the fuel pump has been removed into the Finishing Steps of the procedure.
Date	19-Jan-2021
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-056 (/qs3/pubsys2/xml/en/procedures/20/20-001-056.html)
Procedure Title	Camshaft Thrust Bearing
Update Reason	Corrected the listed minimum specification for the thrust bearing thickness.
Date	19-Jan-2021
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-067-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-067-tr.html)
Procedure Title	Eliminator™ Filter
Update Reason	Added steps to Disassemble, Clean and Inspect for Reuse, and Assemble sections of the procedure.

Date	25-Jan-2021
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-027-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-027-tr.html)
Procedure Title	Lubricating Oil Pan Adapter
Update Reason	Updated to remove reference to procedures for coolant filter head bracket, crankcase breather, fuel filter head bracket, and oil scavenge return hose procedures as these do not apply to K114 engines.
Date	10-Jun-2021
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-033-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Added instruction to inspect the charge-air cooler for debris in Preparatory Steps. Added instruction to clean debris from the charge-air cooler in Finishing Steps.
Date	29-Jun-2021
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-056 (/qs3/pubsys2/xml/en/procedures/20/20-001-056.html)
Procedure Title	Camshaft Thrust Bearing
Update Reason	Added Select Service Tools list to procedure, corrected misspelling.
Date	09-Jul-2021
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-031-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-031-tr.html)
Procedure Title	Lubricating Oil Pump
Update Reason	Corrected minimum and maximum specifications for the Spring Force.

Date	11-Aug-2021
Section	Section V - Specifications
Procedure Number	20-018-024-tr (/qs3/pubsys2/xml/en/procedures/20/20-018-024-tr.html)
Procedure Title	Filter Specifications
Update Reason	Added Part Number 4328043, option FS53014 to Filters for Engines with Electronic Fuel Injectors table.

Date	23-Feb-2022
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-039-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-039-tr.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	Corrected length listed for capscrew in Clean and Inspect for Reuse step.

Date	10-Aug-2022
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-009-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-009-tr.html)
Procedure Title	Rocker Lever Assembly
Update Reason	Updated torque for rocker lever shaft A.

Date	10-Aug-2022
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-021 (/qs3/pubsys2/xml/en/procedures/20/20-006-021.html)
Procedure Title	Fuel Manifold (Drain)
Update Reason	Added to manual on 8/10/2022.

Date	22-Aug-2022
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-043-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-043-tr.html)
Procedure Title	Fuel Shutoff Valve
Update Reason	Added Voltage Check step to procedure.
Date	28-Oct-2022
Section	Section 10 - Air Intake System - Group 10
Procedure Number	20-010-033-tr (/qs3/pubsys2/xml/en/procedures/20/20-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Added HE800 to specifcation tables for Compressor Inlet Axial and Compressor Impeller Radial Endplay.
Date	01-Nov-2022
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-051-tr (/qs3/pubsys2/xml/en/procedures/20/20-006-051-tr.html)
Procedure Title	Injector Supply Lines (High Pressure)
Update Reason	Revised the procedure to add a check for a blockage in the outer wall of the dual wall high pressure fuel lines.
Date	02-Jan-2023
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	20-006-003 (/qs3/pubsys2/xml/en/procedures/20/20-006-003.html)
Procedure Title	Air in Fuel
Update Reason	Deleted and added text to revise actions to take if an air leak is found.

Date	03-Jan-2023
Section	Section V - Specifications
Procedure Number	20-018-017 (/qs3/pubsys2/xml/en/procedures/20/20-018-017.html)
Procedure Title	Lubricating Oil System
Update Reason	Changed oil specification chart to reflect proper values.

Date	27-Jan-2023
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-043 (/qs3/pubsys2/xml/en/procedures/20/20-001-043.html)
Procedure Title	Piston
Update Reason	Corrected table of piston skirt diameter specifications. Deleted references to gallery cooled and crown cooled.

Date	16-Aug-2023
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-027-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-027-tr.html)
Procedure Title	Lubricating Oil Pan Adapter
Update Reason	Changed specification from ft-lb to in-lb.

Date	05-Jan-2026
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-047 (/qs3/pubsys2/xml/en/procedures/20/20-001-047.html)
Procedure Title	Piston Rings
Update Reason	Corrected top piston ring gap specifications for mm and in for the mechanically actuated injector.

Date	15-Jan-2026
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	20-016-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-016-006-tr.html)
Procedure Title	Flywheel Housing
Update Reason	Corrected column width for table to display correctly in procedure.
Date	03-Feb-2026
Section	Section 8 - Cooling System - Group 08
Procedure Number	20-008-036-tr (/qs3/pubsys2/xml/en/procedures/20/20-008-036-tr.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	Corrected column width for table to display correctly in procedure.
Date	13-Feb-2026
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	20-016-006-tr (/qs3/pubsys2/xml/en/procedures/20/20-016-006-tr.html)
Procedure Title	Flywheel Housing
Update Reason	Corrected column width for table to display correctly in procedure.
Date	13-Feb-2026
Section	Section 14 - Engine Testing - Group 14
Procedure Number	20-014-004 (/qs3/pubsys2/xml/en/procedures/20/20-014-004.html)
Procedure Title	Engine Run-in (Without Dynamometer)
Update Reason	Corrected column width for table to display correctly in procedure.

Date	13-Feb-2026
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	20-007-031-tr (/qs3/pubsys2/xml/en/procedures/20/20-007-031-tr.html)
Procedure Title	Lubricating Oil Pump
Update Reason	Corrected column width for table to display correctly in procedure.

Date	13-Feb-2026
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-045 (/qs3/pubsys2/xml/en/procedures/20/20-005-045.html)
Procedure Title	Fuel Lift Pump
Update Reason	Corrected column width for table to display correctly in procedure.

Date	13-Feb-2026
Section	Section 5 - Fuel System - Group 05
Procedure Number	20-005-043-tr (/qs3/pubsys2/xml/en/procedures/20/20-005-043-tr.html)
Procedure Title	Fuel Shutoff Valve
Update Reason	Corrected column width for table to display correctly in procedure.

Date	13-Feb-2026
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-008 (/qs3/pubsys2/xml/en/procedures/20/20-003-008.html)
Procedure Title	Rocker Lever
Update Reason	Corrected column width for table to display correctly in procedure.

Date	13-Feb-2026
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-036-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-036-tr.html)
Procedure Title	Idler Gear, Camshaft
Update Reason	Corrected column width for table to display correctly in procedure.

Date	13-Feb-2026
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-027 (/qs3/pubsys2/xml/en/procedures/20/20-001-027.html)
Procedure Title	Cylinder Block and Liner Seats
Update Reason	Corrected column width for table to display correctly in procedure.

Date	13-Feb-2026
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	20-001-016-tr (/qs3/pubsys2/xml/en/procedures/20/20-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	Corrected column width for table to display correctly in procedure.

Date	18-Feb-2026
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-008 (/qs3/pubsys2/xml/en/procedures/20/20-003-008.html)
Procedure Title	Rocker Lever
Update Reason	Corrected column width for table to display correctly in procedure.

Date	20-Feb-2026
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	20-003-009-tr (/qs3/pubsys2/xml/en/procedures/20/20-003-009-tr.html)
Procedure Title	Rocker Lever Assembly
Update Reason	Corrected column width for table to display correctly in procedure.

Last Modified: 11-Mar-2026
