



Technical Service Bulletin

Technical Service Bulletin: tsb100258

Released Date: 05-Mar-2004

Rear Seal Service Kits, for Rear Engine Power Take-off (REPTO)

Rear Seal Service Kits, for Rear Engine Power Take-off (REPTO)

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces a change in the part number for the rear engine power take-off (REPTO) rear seal service kit.

The rear engine seal service kit for rear engine power take-off (REPTO) applications with wet clutch, Part Number 3800969 has **not** changed.

Description	New Part Number	Old Part Number
Rear Seal Kit, for rear engine power take-off (Dry Clutch)	4089544	3800968

Note : This a product improvement **not** subject to campaign.

Last Modified: 05-Mar-2004