



Technical Service Bulletin

Technical Service Bulletin: tsb100431	Released Date: 27-Feb-2007
New MidRange Machined-from-Solid Turbocharger Compressor Wheel	

New MidRange Machined-from-Solid Turbocharger Compressor Wheel

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin is superseded by 07T10-9 (T2675); please replace this topic with 07T10-9 (T2675).

Last Modified: 27-Feb-2007
