



Technical Service Bulletin

Technical Service Bulletin: tsb100785

Released Date: 15-Jan-2009

New Rear Crankshaft Seal and Seal Kit

New Rear Crankshaft Seal and Seal Kit

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces a change to the rear crankshaft seal used on B, C, and L engines. Rear crankshaft seal, Part Number 3970548, will be replaced by rear crankshaft seal, Part Number 3933262.

The rear crankshaft seal, Part Number 3933262, has a lip profile that is more robust against static and dynamic leaks, and will improve rear crankshaft seal reliability and durability. See Table 1 for new and old rear crankshaft seal and crankshaft seal kit part numbers.

Engine serial number (ESN) first for Rocky Mount Engine Plant is: 46961419.

Table 1: New and Old Rear Crankshaft Seal

New Part Number	Description	Old Part Number	Part Disposition
3933262	Rear Crankshaft Seal	3970548	Use to Depletion
3934486	Rear Crankshaft Seal Kit	4089342	Use to Depletion

Last Modified: 15-Jan-2009