



Technical Service Bulletin

Technical Service Bulletin: tsb100838

Released Date: 09-Jul-2009

New MidRange Machined-from-Solid Turbocharger Compressor Wheel

New MidRange Machined-from-Solid Turbocharger Compressor Wheel

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Note : This Technical Service Bulletin supersedes 07T10-9A (T2675). Please replace 07T10-9A (T2675) with this topic.

This Technical Service Bulletin has been modified to include one additional turbocharger kit for 6C Mechanical engines that has been released to improve low cycle fatigue issues.

The kit that has been added is Part Number 4955254.

This Technical Service Bulletin announces a new machined-from-solid turbocharger compressor wheel for certain MidRange engine and application combinations. The new turbocharger compressor wheel improves low cycle fatigue mode issues.

The previous compressor wheel is a cast design with the outer blade contour machined to achieve the desired profile. The sides of the cast wheel blades are in the "as cast" condition.

The new compressor wheel is a machined-from-solid design which is created by machining the wheel from a solid billet of aluminum. All surfaces of the machined-from-solid wheel are machined.

This product improvement is **not** covered by warranty.

Only certain high-duty cycle applications are eligible to receive machined-from-solid turbocharger compressor wheels.

Only certain high-duty cycle applications are subject to a Temporary Repair Practice (TRP). In most instances, cast compressor wheels have **not** been obsoleted and superseded.

Consult QuickServe™ Online to determine if a given engine and application combination is eligible to receive this product improvement.

The compatibility chart below shows the machined-from-solid turbocharger compressor wheels that can potentially be used with the CPLs listed.

Engine	CPL	Cast Compress or Wheels	MFS Compress or Wheels	MFS Service Kit	MFS ReCon®	Direct Super session?
ISB 225	2685	3538868	4036133	4089633	N/A	No
ISB 240	2684	3538873	4036142	4089634	N/A	No
ISB 260	2682, 2683	3538876	4037253	4089753	N/A	No
6C Mech	1566, 1918, 2103, 2106	3532222	4039184	4090038	3802613R X	No
6C Mech	1566, 1918, 2103, 2107, 2108	3533005	4039186	4090039	3802614R X	No
6C Mech	1949, 2034, 2108, 2150	3536329	4039188	4090040	3802739R X	No
6C Mech	1949, 2034, 2108, 2150	3536333	4039190	4090041	3802769R X	No
6C Mech	7696	3599592	4036122	4955254	N/A	No
ISC	2236, 2237	3594995	4037973	4025037	N/A	Yes
ISC	2236, 2237	3594997	4036949	4089716	4089716N X	Yes
ISC	2236, 2237	3594998	4037975	4025040	N/A	Yes
QSC	8153	3596418	4040245	4090010	N/A	No
QSC	8152	3591020	4040244	4090009	N/A	No
ISL	2692, 8042, 8473	3595808	4038046	4025305	N/A	Yes
ISL	8042, 8473	3595810	4038047	4025306	N/A	Yes
ISL	2692, 8042, 8473	3595813	4038050	4025307	N/A	Yes
ISL	2692, 8042, 8473	3596384	4038044	4025308	N/A	Yes
6C Mech	2194	3536056	4042044	4955206	N/A	Yes
6C Mech	2193	3533000	4042042	4955207	N/A	Yes
6C Mech	2368	3536404	4042040	4955208	N/A	Yes
ISCe	8056	3596147	4046191	4955603	N/A	Yes
ISCe	8056	3596146	4046192	4955604	N/A	Yes
ISCe	8056	3595821	4046193	4955605	N/A	Yes
ISBe	2925	3599975	4044154	4955451	N/A	No

Engine	CPL	Cast Compress or Wheels	MFS Compress or Wheels	MFS Service Kit	MFS ReCon®	Direct Super session?
ISBe	2925	3596647	4044050	4955452	N/A	No
ISBe	2925	4035327	4043270	4955477	N/A	No
QSC Tier 3	8578	3596418	4047592	4955793	N/A	No

Last Modified: 09-Jul-2009
