



Technical Service Bulletin

Technical Service Bulletin: tsb101163	Released Date: 31-May-2002
Revision of Lubricating Oil Procedure	

Revision of Lubricating Oil Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic revises the fill section of the Lubricating Oil and Filters Procedure, 007-002.
--

Last Modified: 31-May-2002
