



Technical Service Bulletin

Technical Service Bulletin: tsb101344

Released Date: 17-Nov-2003

Revision to Procedure 022-001, Service Tools (Injectors and Fuel Lines)

Revision to Procedure 022-001, Service Tools (Injectors and Fuel Lines)

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 022-001 (/qs3/pubsys2/xml/en/procedures/41/41-022-001.html), Service Tools (Injectors and Fuel Lines).

Related Procedures

41-022-001_06
(/qs3/pubsys2/xml/en/procedures/41/41-022-001_06.html)

Service Tools
(/qs3/pubsys2/xml/en/procedures/41/41-022-001_06.html)

Last Modified: 17-Nov-2003