



Technical Service Bulletin

Technical Service Bulletin: tsb101350

Released Date: 29-Jan-2004

New and Revised Procedures for Engine Cooling System

New and Revised Procedures for Engine Cooling System

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces and revises Procedures, Coolant Thermostat 008-013, Cooling System 008-018, Radiator Hoses 008-045, Sea Water Pump 008-057, Sea Water Strainer 008-067, Sea Water System Diagnostic, 008-103, and Sea Water Hoses 008-104.

Related Procedures

41-008-013-tr (/qs3/pubsys2/xml/en/procedures/41/41-008-013-tr.html)	Coolant Thermostat (/qs3/pubsys2/xml/en/procedures/41/41-008-013-tr.html)
41-008-018-tr (/qs3/pubsys2/xml/en/procedures/41/41-008-018-tr.html)	Cooling System (/qs3/pubsys2/xml/en/procedures/41/41-008-018-tr.html)
41-008-057 (/qs3/pubsys2/xml/en/procedures/41/41-008-057.html)	Sea Water Pump (/qs3/pubsys2/xml/en/procedures/41/41-008-057.html)
41-008-103 (/qs3/pubsys2/xml/en/procedures/41/41-008-103.html)	Sea Water System Diagnostics (/qs3/pubsys2/xml/en/procedures/41/41-008-103.html)
99-008-045-tr (/qs3/pubsys2/xml/en/procedures/99/99-008-045-tr.html)	Radiator Hoses (/qs3/pubsys2/xml/en/procedures/99/99-008-045-tr.html)

99-008-067 (/qs3/pubsys2/xml/en/procedures/99/99-008-067.html)	Sea Water Strainer (/qs3/pubsys2/xml/en/procedures/99/99-008-067.html)
99-008-104 (/qs3/pubsys2/xml/en/procedures/99/99-008-104.html)	Sea Water Hoses (/qs3/pubsys2/xml/en/procedures/99/99-008-104.html)

Last Modified: 29-Jan-2004
