



# Technical Service Bulletin

---

|                                        |                            |
|----------------------------------------|----------------------------|
| Technical Service Bulletin: tsb101439  | Released Date: 24-May-2004 |
| Turbocharger Leak Troubleshooting Tree |                            |

## Turbocharger Leak Troubleshooting Tree

### Warranty Statement

---

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

---

The purpose of this Service/Parts Topic is to update Troubleshooting Tree T122 with improved troubleshooting logic.

Turbocharger Leaks Engine Oil or Fuel

---

Last Modified: 24-May-2004

---