



Technical Service Bulletin

Technical Service Bulletin: tsb101602

Released Date: 07-Feb-2005

Oil Cooler Specification Change

Oil Cooler Specification Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-003 Oil Cooler Cover. Torque information describing the installation of the 8 mm dimpled oil cooler cover is included.

Note : This is a product improvement and not subject to campaign.

Related Procedures

100-007-003
(/qs3/pubsys2/xml/en/procedures/100/100-007-003.html)

Lubricating Oil Cooler
(/qs3/pubsys2/xml/en/procedures/100/100-007-003.html)

Last Modified: 07-Feb-2005